

County Surveyor's Record, Douglas County, Oregon

Government Corners Renewed

T 22 S R 8 W WM

WEST COAST PRINTING & BINDING CO., PORTLAND 13735

Ben B. Irving, Co. Surveyor
Milo Godfrey, Witness
March 1945

CHAINS

C.S. 17/39 A 10-72

Meander Corner on the left bank of the Umpqua River between Secs. 22 & 23, T 22 S, R 8 W, WM. This corner is also the Witness corner to the section corner 14-15-22-23 which is in the Umpqua River.

A 42" Oak was found which fit the location for the original bearing tree. This tree carried scars which corresponded with those which are normally where witness blazes have grown over. These were cut out but the tree was hollow and the interior was so badly rotted that positive identification was impossible.

A careful check of distances and bearings was made from this tree and from the NW corner of DLC No. 42 and as both gave nearly identical locations for the Meander Corner it was concluded that the location was correct.

A 1 1/2" x 42" pipe was set for the corner from which a white oak 42" in diam. bears S 18° 10' E 103.2 ft. blazed and scribed MC-WC S 23 CS BT. and a black oak 48" in diam. bears S 65° 40' W 166.6 ft. blazed and scribed MC-WC S 22 CS BT. - New Gov't. Brass CAP AT CORNER - BT's (by Irving) O.K. SEPT. 1964 - C.S. 52/44

43

Floyd J. Cole
Deputy
April 16, 1913.

C.S. Vol 12, Page 185

1/4 Corner between secs 12 & 13.

Found both trees, one dead, marks visible. Set sandstone 8" x 10" x 14" from which

A Maple tree 12" in dia. bears S. 72° E., 63.1 feet.

An Oak 28" in dia. bears N. 40° 35' E., 273.2 feet dist.

44

Southeast corner of the William Hathaway D. L. C. No. 44.

We find 9 inch x 14 inch x 18 inch stone and both BTs as scribed in 1913 which check for bearing and distance. The N.E. BT we cut out and scribing visible-tree alive. The S. W. BT center rotted and all scribing gone.

Set an iron pipe with brass cap at side of stone and blaze and scribe:

16 inch W. O., S. 45° E., 28.0 feet mkd. S. E. DLC 44 CS BT.

14 inch R. Fir, N. 57 1/2° E., 69.7 feet mkd. S. E. DLC 44 CS BT.

Rev. #12

RE-RENEWED, SEE CORNER NO. #170

45

Interior "L" corner of William Hathaway D. L. C. No. 44.

Location of corner established by proportional measurement. No evidence of "L" corners found - The call for creek checks.

Set an iron pipe with brass cap at corner point mkd. Co. Surveyors Office, 1955, Int L, CL 44 T22S R8W.

Blazed and scribed:

16 inch R. Fir, N. 38° E., 13.0 feet mkd. Cl. 44 T 22 R 8 CS BT.

14 inch R. Fir, N. 25° W., 11.0 feet mkd. Cl. 44 T 22 R 8 CS BT.

Note: This corner falls at East edge of old Co. road at bottom of cut bank

Exterior "L" corner of William Hathaway D. L. C. No. 44.

Corner located by proportional method. No evidence of "L" corners found - the call for creek checks.

Set an iron pipe with brass cap at corner mkd. Co. Su. Off., 1955, Ext L Cl 44 T22S R8W.

Blazed and scribed:

10 inch R. Fir, N. 9° W., 4.6 feet mkd. Cl. Ext L Cl 44 CS BT.

8 inch R. Fir, S. 88 1/2° E., 47.9 feet mkd. Cl Ext. L Cl 44 CS BT.

S 88 1/2° E Per Research done 5/10/95 DCSO SC

CORNER FOUND IN GOOD CONDITN - SEPT. 44 L.P.

47

James W. Byren, Deputy County Surveyor
February, 1955.
C. S. File No. 46/125.

Southwest corner of the William Hathaway D. L. C. No. 44. (Witness)

Found a 4 feet fir snag, bark scribed C 44 on NE face. I use this tree for orig. corner. I also find 30 inch Fir stump which bears S. 88° W., 9.2 feet bark scribed 4 at top of cut.

Set an iron pipe with brass cap 3 feet east of center of 4 feet snag, mkd. W. C. 3 feet West to S. W. corner D.L.C. 44 T 22 S, R8W, County Surveyors Office, 1955.

Blazed and scribed:

14 inch R. Fir, N. 28° W., 27.0 feet mkd. W. C. SW Cl 44 T22S R8W.

8 inch R. Fir, S. 44 1/2° W., 14.2 feet mkd. W. C. SW Cl 44 CS BT.

48

RE-RENEWED, SEE CORNER NO. 81