

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

Exp. ok 8/1
H. Wilcox Mills-60

Section Corner to Sections 7 & 18, T22-8W. & Secs. 12 & 13, T22-9W. 97
Found - Brass Cap set in 1931 in good condition.
33" Maple N.12°E. 38.9 ft., good axe scars visible.
30" Fir S.85°W. 35.0 ft., scars plainly visible, Tree partially dead.
30" Maple N.40°W. 48.2 ft. Tree in poor condition, but no other
trees available to Northwest.
Southeast Tree is gone, no trace found.
New BT's: 14" D.Fir S.45°E. 102.7 ft. Mkd: T22S R8W S18 CS BT.
15" D.Fir S.64°W. 55.5 ft. Mkd: T22S R9W S13 CS BT.

Sept. 11, 1963

South $\frac{1}{4}$ Corner to Sec. 31, T21-8W. 98
(on N. Line Sec. 6, T22-8W)
Found - Brass Cap set by Cadastral Survey of 1945. - *SEE GOV'T. NOTES*
Stump of 38" Fir N.30°E. 149.8 ft. *Vol. 33, Pg. 13731*
34" Fir N.77 $\frac{1}{2}$ °E. 25.1 ft., no scribing visible, old face badly
burned. - Blaze & Rescribe, " $\frac{1}{4}$ S31 CS BT".
60" Fir N.72°W. 134.0 ft., recently blazed & scribed " $\frac{1}{4}$ S31 BT".

Wit. Corner to $\frac{1}{4}$ Corner for Section 6 only. 99
(on S. Line T21S R8W)
Found - Brass Cap set in 1945.
Both BT's. mkd. in 1945, uprooted stump only. Both show good scars.
 $\frac{1}{4}$ Corner, W. Fir Tree, uprooted and down.
New BT's: 9" W. Fir S.25 $\frac{1}{2}$ °W. 36.0 ft. Mkd: W C $\frac{1}{4}$ S 6 CS BT.
7" W. Fir S.18°W. 43.2 ft. Mkd: W C $\frac{1}{4}$ S 6 CS BT.

Closing Corner to Sections 2 and 1. 100
(on S. Line Sec. 35, T21S R8W)
Found - Brass Cap set in 1952.
All BT's. called for in govt. notes, 1952, found, but all are
uprooted & down. (fairly recent)
New BT's: 11" D.Fir S.83°W. 63.7 ft. Mkd: T22S R8W CC S2 CS BT.
22" Madrone N.36°W. 94.0 ft. Mkd: CC S1 S2 CS BT.
No trees available in Section 1.
Note - Bottom of blaze on Madrone 4 ft. above ground.

North $\frac{1}{4}$ Corner Section 1, only. 101
(on S. Line Section 36, T. 21S, R8W)
Found - Brass Cap set in 1952.
42" D.Fir S.26 $\frac{1}{2}$ °E. 36.3 ft., very plain axe blaze visible.
55" Fir S.49 $\frac{1}{2}$ °W. 37.0 ft. is uprooted and down.
New BT: 38" D.Fir N.52°E. 22.5 ft., Mkd: " $\frac{1}{4}$ S 1 CS BT.
No other tree available south of line.

South $\frac{1}{4}$ Corner Section 36 only, T21S R8W. 102
(on N. Line Sec. 1, T22S R8W)
Found - Brass Cap set in 1952.
Sawed Stump of 52" Fir N. 7° E. 30.4 ft., shows good scar.
Burned Shell of 70" Fir N.40°E. 16.5 ft. No marks remain.
No trace of 7" Hemlock mkd. in 1952.
New BT: 9" Maple N.37°E. 78.2 ft. Mkd: " $\frac{1}{4}$ S36 CS BT".
No other trees available.

Section Corner to Sections 34 & 35, T21S R8W. 103
(on N. Line Sec.2, T22S R8W)
Found - Brass Cap set in 1952, under uprooted 36" Fir.
7" Hemlock, now 10", N.78 $\frac{1}{2}$ °W. 23.1 ft. Tree alive & in good condition.
55" Fir N.30°E. 29.7 ft. is now a stump, sawed off 2 ft. above ground.
47" Fir N.35 $\frac{1}{2}$ °E. 60.7 ft. is now a shattered snag.
New BT: 10" Hemlock N.7 $\frac{1}{2}$ °W. 68.0 ft. Mkd: "T21S R8W S34 CS BT".
No trees available in Section 35.

Milo E. Godfrey, Deputy County Surveyor

Mike Stone

September, 1963

C. S. File No. 52/14