

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

108

TOWNSHIP CORNER -

T21S  
R9W 

S 36	S 31
S 1	S 6

 R8W  
T22S

Found - Brass Cap set by Cadastral Survey of 1945, bulldozed out & buried in ground, lying across corner position.

38" Fir Stump N.12 $\frac{1}{2}$ °W. 12.5 ft.

48" Fir Stump S.18 $\frac{1}{2}$ °W. 163.0 ft., axe marks in bark "S1 BT".

Burned remnants of big Fir Stump S.21 $\frac{1}{2}$ °E. 18.5 ft.

38" Fir Stump N.36°E. 107.6 ft.

36" Fir Stump N.37°E. 34.3 ft.

No scribe marks found - No trace of other old BT's.

Reset Gov't. Brass Cap in proper position.

Rescribe - 38" Fir Stump N.12 $\frac{1}{2}$ °W. 12.5 ft., "T21S R9W S36". (broke scribe)

No live trees available.

Sept. 25, 1963

Meander Corner Right Bank Sec. 18, T22-8W. & Sec. 13, T22-9W.

Found - Alder, 18" diam., mkd. in 1931 for Wit. Cor. to M. C.,

shows good scars.

27" White Oak S.40°W. 45.5 ft., cut open & found good scribe mks. "T".

No trace of N. E. Tree.

Set - At true proportionate point for meander corner, according to 1931 survey, 17.8 ft. North of Witness Corner:

Brass Cap Mkd: County Surveyor's Office, 1963

T 22S R 9 W. M.C. R9W S13/S18 R8W

New BT's: 12" Alder S.23°E. 14.4 ft. Mkd: M. C. S18 CS BT.

16" White Oak S.37°W. 35.5 ft. Mkd: M.C. S13 CS BT.

Angle at S.W. Corner of concrete block wall bears N.13°W. 150.5 ft.,

Wall along ledge of yard around house.

Oct. 3, 1963

Closing Corner to Sections 4 and 3, T23-8W.

(South Line T22S R8W)

Found - Old Fir Stump S.52 $\frac{1}{2}$ °E. 179.5 ft., cut open & found it had been opened many years ago & grown over axe notch at bottom of badly burned old face. No scribing found.

Stump Hole with Fir Roots S.31°W. 91.1 ft.

Note - These 2 BT's. were same trees used as BT's. for standard corner, Secs. 3 & 4, which was 60 lks. East of this corner.

This location is 10 ft. longer than record distance from C. C.

Secs. 33 & 34, T22S R8W, as set by Cadastral Survey of 1963.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963

T23S R8S CC S 4/S 3

New BT's: 31" Bl. Oak S.84°E. 137.5 ft. Mkd: T23S R8W CC S3 CS BT.

17" W.Oak N.13°W. 23.8 ft. Mkd: T23S R8W CC S3 S4 CS BT.

No tree near in Section 4.

Corner lies 5 ft. South of E. and W. Fence Line.

Brass Cap at C. C. Sections 33 and 34 bears N.87°W. 221.7 feet.

MARCH, 1967 - FOUND BRASS CAP O.K. V.R.T.

Oct. 2, 1963

N.W. Cor. D.L.C. 44 Common Corner With N.E. Cor. D.L.C. #45.

Found - 2 Bearing Trees per Cole's Renewal, See Ren. No. 11.

Set - Lot Marker from the above Bearing Trees.

(Angle Iron & Brass Cap)

August 1955

Interior "L" Corner D. L. C. No. 42.

Found -  $\frac{1}{2}$ " Iron Pipe set by Irving in 1945 (See Ren. #41)

Fir Stump N.86°W. 21.0 ft., scribing visible, "SW Int. DLC 42".

32" D.Fir N.54°W. (not N.59°W.) 76.5 ft., very plain axe scars visible, tree in good condition.

New BT: 21" D.Fir N.5 $\frac{1}{2}$ °E. 76.8 ft. Mkd: "Int. L DLC 42 CS BT.

FD OK PER DOLAW  
M 109 - 6 SEPT 1989

Milo E. Godfrey, Deputy County Surveyor  
Wm. Stoffel and Mike Stone  
September 1963 - October 1963  
C. S. File No. 52/14.

Wilford N. Haines  
C.S. 42/30  
Map File  
M 10 - 69

Milo E. Godfrey and Crew  
Sept. 10, 1964  
C. S. File No. 52/14

RENEWED CORNER NO. #148

110

111

117

112