

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Godfrey & Crew
Sept. 1964
C.S. File 52/14

Mike E. Godfrey, Deputy Co. Surv.
Wm. Steffel & Mike Stone
October 1964
C. S. File No. 52/14

Vernon "Ray"
Tracy
& Crew
C. S. File
No. 52/14

Vernon B. Tracy & Crew
C. S. File No. 52/14

$\frac{1}{4}$ Corner Sections 21 and 28.

Found - Old White Oak Stump S.65°W. 134.6 ft., no marks on stump at present time, but tree was cut by Mr. Riley several years ago & scribing was found at that time.
See affidavit of Mr. Riley on back of this sheet.

No trace of N.W. tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R8W $\frac{1}{4}$ S21
Office, 1964 S28

New BT's: 30" W.Oak S.57°W. 126.5 ft. Mkd: $\frac{1}{4}$ S28 CS BT.

23" W.Oak S.16°E. 123.5 ft. Mkd: $\frac{1}{4}$ S28 CS BT.

No trees suitable near in Section 21.

118

N. E. Corner D.L.C. No. 42

N.W. Corner D.L.C. No. 41.

Found - Tie Rod set by Irving in 1945 with $\frac{1}{2}$ " pipe alongside. (Ren. #42)
Ash Tree N.23°W. 27.6 ft. S. E. face of tree entirely rotted away.

No trace found of N. E. Tree.

Set - Brass Cap alongside Tie Rod & Mkd: T22S R8W
County Surveyor's Off. 1964

N. E.	N. W.
DLC	DLC
42	41

New BT's: 7" Ash S.18°W. 36.0 ft. Mkd: N. E. DLC 42 CS BT.

40" Dbl. Maple S.70°E. 23.7 ft. Mkd: NW. DLC 41 CS BT.

119

Mst. Southerly S.W. Corner D. L. C. No. 42.

Found - $\frac{1}{2}$ " Iron Pipe set by B.Irving, 1945, new $1\frac{1}{2}$ " galv. I.P. alongside.
(See Ren.#40)

Stump of 24" Fir N.10°W. 70.4 ft., scribing vis. "XT 42 BT".

Stump of 12" Fir N.82°W. (not N.62°W.) 24.3 ft., scribing visible.

New BT's: 10" D.Fir N.87°E. 12.4 ft. Mkd: SW DLC 42 CS BT.

5" D.Fir S.68°W. 30.9 ft. Mkd: SW DLC 42 CS BT.

120

Wit. Corner to $\frac{1}{4}$ Corner Sections 22 and 27.

Found - 1963 BLM Brass Cap, probably set from Orig. BT., down.

8" Maple N. 11 $\frac{1}{2}$ ° E. 22 lks. 14.5 ft. Mkd: " $\frac{1}{4}$ S22 BT".

12" Hemlock S. 26 $\frac{1}{2}$ ° W. 67 lks. 44.2 ft. Mkd: " $\frac{1}{4}$ S27 BT".

Move Brass Cap 100 ft. West & Reset & Add "W.C. 100 ft. E. to Cor."

on Brass Cap & Mkd. New BT's:

17" Hemlock N. 40° W. 29.5 ft. Mkd: "WC $\frac{1}{4}$ S22 CS BT."

17" Hemlock S. 65° W. 5.7 ft. Mkd: WC $\frac{1}{4}$ S27 CS BT.

Note - This corner lies approx. 70 ft. west of proposed new road.

Feb. 3, 1966

Sec. Cor. to Sections 32 & 33 only, T22-8W.

Found - 1962 G.L.O. Brass Cap at corner, properly marked.

25" Fir, now 6 ft. high stump, N. 5 $\frac{1}{2}$ ° E., 10.9 ft., scribe visible, on pitched blaze.

18" W. Fir, now 6 ft. high stump, N. 20 $\frac{1}{2}$ ° W. 48.2 ft., scribe visible on unhealed blaze.

New BT: 7" W. Fir N. 38° W. 121.5 ft. mkd. T22S R8W S32 CS BT.

No trees close to N. E.

Note - Corner lies in logged-off unit 50 ft. North of new access road.

Dec. 27, 1966

MICROFILM TO HERE - 10/67 -

123

Most Northerly NW. cor. DLC No. 53

Found - $1\frac{1}{2}$ " Iron pipe, 40" long, with steel fence post along side. (unrecorded)

Orig. 24" now 28" Oak S.58°E. 10.6 ft. now snag. We open & find scribe

Orig. 12" now 22" Oak N.8°E. 33.7 ft., dying. No scar visible.

WE DO NOT SET BRASS CAP

New BT's-10" Douglas Fir S.41°W. 12.6 ft. mkd. NNW DLC 53 CS BT.

14" Douglas Fir S.9°E. 9.5 ft. mkd. NNW DLC 53 CS BT.

Note - This cor. lies 35 ft. N. of ridge top course NE-SW.

Jan 28, 1970