

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 8 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

124

Northwest Corner D. L. C. No. 47.

Found - 9", now 11" W. Fir, S. 77 1/2° E. 48.8 ft., shows good scar.
45", now 45" Forked D. Fir, S. 75° W. 11.9 ft., shows good scar.
30", now 35" D. Fir, N. 40° W. 9.9 ft., shows scar.

Fd. Iron Pipe set by Frear, lying on surface of ground. ^{REN. 1963}
By using metal location finder found 1963 Cadastral Brass Cap ^{#174}

T 22 S R 8 W
S 9 / S 47

This cap buried under 10" of soil, apparently disturbed by errant
cat skinner during logging operation.

Reset Brass Cap at proper location with Iron Pipe alongside.

This corner lies on top of ridge, running S.E. about 150.0 ft.
north of log landing.

12/28/70

John M. Powell & Crew
12/28/70 C.S. 52/14

MARCH 71

Southeast Corner D.L.C. No. 54.

125

Found - 35" W. Oak, N. 63° W., 5.3 ft., scribe visible T28S R8W
C54 BT.

6" Fir, now dead, N. 15° E., 23.8 ft., shows scar.

Also Fd. 1964 B.L.M. Brass Cap, properly marked.

New BT: 14" D. Fir, N. 9° W., 76.0 ft., scribed S.E. DLC 54 CS BT.

Note - This corner lies 5.0 ft. north of fence. Fence runs E. & W.

1/13/72

FND OK 9/92 R. DELAN M115-68

Southwest Corner D.L.C. No. 55

126

Found - 18" Oak, now stump, N. 1/4° W., 493.7 ft. Scribe found "BT".
No trace of SW BT.

Set - 2" x 30" I. pipe at corner.

New BT's - 9" W. Oak, N. 31 1/2° E., 23.6 ft., scribed SW DLC 55 CS BT.

13" D. Fir, N. 72° E., 13.0 ft., scribed SW DLC 55 CS BT.

Note - Fence corner running N & E, N. 33° E., 6.4 ft.

Old corner fence post lies in bottom of ravine where cor. is.

Mr. Garrison confirms that it was old cor. post and that our

2" iron pipe is where cor. should be.

I do not set brass cap because cor. falls in ravine full of
water. No water in summer. Maybe brass can be set at that time.

1/12/72

John M. Powell & Crew
1/13/72 C.S.
File 52/14

JAN 1973

S. W. Corner of D. L. C. No. 54.

127

Found - Both 1964 Cadastral BT's. alive and in good condition,
Fir healed, Cedar has scribe visible on partially healed
blaze.

1964 Cadastral Brass Cap was found in creek bottom.

Reset at the corner point & also Reset Steel Fence Post alongside.

Note - This corner lies on East bank of small creek, course North,
and in very dense underbrush.

7/12/73

Vernon "Ray"
Tracy & J.H.
C. S. File
No. 56/34

1/4 Corner to Sections 21 and 28.

128

Found - 30" W. Oak S. 57° W. 126.5 ft., shows good scar.

23" W. Oak S. 16° E. 123.5 ft., shows good scar.

C.S. Brass Cap, 1964, Bent over by Cat. See Ren. #118.

Reset - Brass Cap and remarked so Sec. 21 is to the North
& Sec. 28 to the South.

9/14/73

Powell, John
Earle, Pete
C.S.
56/38

1/4 Corner for Secs. 9 and 10.

129

No trace of original.

Set - 5/8" Steel Rod.

New BT - 40" Maple N. 53° W., 24.6 ft. scribed.

Fd 4/89
D. BAKER
M101-55

Wilford Haines
for George Vant-
zet.

9/23/74
M 54 - 32

Sept. 23, 1974