

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

134

Section Corner to Sections 33 and ~~35~~³⁴ only T21-8
(on ~~4~~ Line of Sec. 3, T22S R8W)
Found: Remains of one BT marked in 1945; A fragmented, rotten hemlock stump bearing N.46°45'W., 57.4 ft., with scribing "W S33 BT" visible. ^(BLM RESURVEY)
The brass cap set in 1945, and all other corner accessories have been destroyed.
Due to extremely steep slopes, shallow soil and loose rock, it is impractical to set any type of permanent monument. We do however place a steel fencepost at the corner point.
We mark the following new BT's.
An 8" Red Alder bears N.55°W., 34.7 ft. scribed "T21S R8W S33 CS BT" on a double blaze.
A 7" D. Fir bears N 51°E., 23.6 Ft., scribed "T21S R8W S34 CS BT" on double blaze. Compass Declination: 20° East

Gary L Langlitz
Clell E Goodwin
M. Lenora Ladig
A. Vic Cangie
C.S. 57/34
8/7/75

135

Center 1/4 Corner Sec. 25
Found-US BLM 1964 brass cap properly marked. Iron fence post along side.
BT's - A fir snag 35" dia. bears N 19°E., 23.1 ft. has good blaze, tagged.
A Hemlock snag 37 (rec. 36) inches dia. bears S 78 1/2°W., 10.6 ft. scribed scribed "C 1/4 S 25" tagged
Renewal-A hemlock, 10" Dia bears N 8°W., 90.9 ft. Scribed, "C 1/4 S 25 CS BT" Tag.
A Maple 20" dia. bears N 67 1/2°E., 55.1 ft. Scribed "C 1/4 S 25 CS BT" Tagged.
Bearing tree is A double tree, one base. Measurement and bearing are taken to center of base, dia. is on larger (scribed) trunk. 11/18/75

L. E. Monrean
P. L. E.
K. C.
11/18/75
CS 57/39

136

Witness Corner to Meander Corner, Sections 5 and 4.
Found - A 12" now 20" Fir, bears N.20 1/4°E., 142.6 ft. Tree has double blaze I open lower blaze and find scribing "T".
A 22" Maple bears N.61 1/2°W., 153.0 ft. (1963 Resurvey rec. is 15" Oak N.62°W., 148 ft.) Tree has double blaze, lower blaze chopped out "BT" visible.
I find no trace of recorded objects at witness corner.
This corner lies directly over large culvert under Highway number 38.
Set - At witness corner to meander corner I place a 1" x 30" I.P. with brass cap attached stamped "Douglas County Surveyor" 1976
T 22 S R 8 W
W C
S 5 | S 4
M C
Brass cap is set 1" above ground.
Note: The southerly edge of State Highway No. 38 is 14.7 ft. from this corner. (Rec. 14.5 ft.) Set post and witness sign approx. 1 ft. North of cap.

Larry E. Monrean, Doug. Co. Surveyors
P. L. Earle
K. Cheney
Nov. 10, 1976
C.S. 59/26

11/10/76

137

Northwest Corner DLC #52
Found - 15" Oak, S85°E., 1295 lks. now stump.
36" Oak, N.87 1/2°E., 1291 lks. now 48" Oak
Set - 5/8" rebar
BT's- 12" Fir, N.35°W., 34.6 ft. scribed.
16" Fir, N.38°E., 41.0 ft.

Wilford N. Hain
For: Kenneth
Gossel
June 1977
M 66 - 15

138

Northeast Corner DLC #52
Found - 12" Oak, S.57°W., 275 lks. now stump
12" Oak, N.72 1/2°W., 330 lks. now 22" Oak down.
Found Good reverse scribe
Set - 5/8" Rebar
Note - Property corner set 18.7 ft. east of NE DLC corner. Set 5/8" rebar and scribed 12" Fir S.55°W., 20.7 ft.

139

Northwest corner for D.L.C. #50.
Found - A 22 cal. gun barrel, laying on it's side. Ren. #76
A 8" now 19" Ash bears N.34°E., 12.4 ft. with a healed upper blaze, lower blaze rotted out. (Ren. #25).
A 15" Myrtle bears S.6°E., 31.1 ft. with a well healed blaze. Ren. #76

R. B. Kimberling
F.C. Silagy
Doug. Co. Surveyors
Office
Jan. 16, 1978
C.S. 59/46