

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 8 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 97401

173

Daniel Baker
L.S. #1978
April, 1989
M 101 - 54

Northeast Exterior "L" Corner DLC #50
Found - Rotten 30" Fir stump S.2°E., 33.0 ft. (Reverse scribing on old burned face).
Set - 3/4" x 30" alum. rod and I.P. Co. Alum. Cap.
New BTs - 14" Fir, N.45°E., 6.6 ft. (scribed CL50BT)
13" Fir, S.26°E., 13.6 ft. (scribed CL50 BT)

4/89

174

Douglas County
Surveyors Office
Stephen Glause
T.R. Franssen
August 6, 1991
C.S. File 64/17

N.W. Corner for DLC #47
Found - A rusted & bent 22" long 1 1/2" O.D. I.P. found out of ground & out of position approx. S.33°W., 31 ft. dist. from cor. Location determined from found BTs. I.P. monument in Renewal 18 described as 1 1/2" x 24". See also Ren. No. 124
Found monument & missing monument probably disturbed by road work to nearby clear-cut.
Orig. Fir 30" dia. now a rotted 40" dia. 36" tall Fir stump with no scribing or face evident; bears S.07°E., 69.3 ft. (as per record)
Orig. Fir 9" now forked Fir 45" DBH with a fully healed blaze, bears S.75°W., 11.9 ft. (agrees with BLM and subsequent renewals - Orig. rec. S.60°W., 11.9 ft.)
Possible evidence of a 24" Fir later called a Fir 30" dia. in BLM resurvey, now a broken rotted 30" dia. 36" tall Fir stump with no blazes or scribing found, bears N.45°W., 9.9 ft. (BLM resurvey rec. N.40°W., 9.9 ft.) Ren. No. 18
A 9" Fir now a 36" dia. 12" tall Fir stump with the possible remains of a partial lower blaze bears S.77 1/2°E., 48.8 ft. as per record. 1963 BLM Resurvey.
Set - At location determined by intersecting distance measurements from found BTs as noted, a 2 3/8" dia. brass cap mkd. "Douglas County Surveyors Office T22S R8W on a 1 1/2" O.D. 31" long

S9
1963

Iron pipe is firmly set protruding approx. 6" above the ground. The found 1 1/2" I.P. is set on the south edge of the B.C. monument and protrudes 4" above ground.
New BTs - A 4" DBH D. Fir scribed "X BT" on a double blaze, bears N.80°E., 28.1 ft. distant.
A 5" DBH D. Fir scribed "T22S R8W C 47 CS BT" on a double blaze bears S.34°W., 53.2 ft. distant.
Approx. 320 ft. southerly along spur road from BLM Rd#22-8-9.1. At edge of older reprod. unit on wide bench & near edge of recent clearcut unit.

8/6/91
175

Douglas County
Surveyors Office
Randall Smith
Stephen Flaue
Feb. 12, 1992
C.S. File 64/23

Section Corner for 35 and 36 only (South)
Found - 3 1/2" dia. 1964 BLM brass cap on an Iron pipe flush with ground 19" now 37" dia. W.Oak with a fully healed single blaze, bears N.17 1/2°E., 58.7 ft. (agrees w/rec.) 1964 BLM
15" now a cluster of W.Oaks, brg. distance and fully healed single blaze is on 17" East trunk, East trunk's root crown bears N.64 1/2°W., 70.6 ft. (agrees/rec) 1964 BLM
New Accessories:
26" dia. W.Oak double blazed and scribed "T22S R8W S36 CS BT" bears N.27°E., 106.4 ft.
5/8" Iron rod with plastic cap 5" below ground bears East 211.2 f (T23S R8W NW Cor. S.1) (Ren. No. 127 in T.23-8)
2/12/92

Douglas County
Surveyors Office
Randall Smith
Stephen Flaue
Feb. 12, 1992
C.S. File 64/23

Section Corner for Secs. 1 and 2 only of T.23-8
Found - 5/8" Iron rod with yellow plastic cap, 5" below ground. Ren. No. 152 176
24" now 25" dia. W.Oak with a fully healed double blaze bears S.25°W., 58.4 ft. (agrees w/rec.) Ren. No. 152
32" now 34" W.Oak with a fully healed double blaze bears S.62°E., 165.2 ft. (agrees w/rec) Ren. No. 152
New Accessories:
20" W.Oak double blazed and scribed "T23S R8W S1 CS BT" bears S.20 1/2°E., 150.1 ft.
3 1/2" dia. BLM brass cap/iron pipe flush with ground bears West 211.2 ft. (T22S R8W SE Cor S35, BLM 1964)
2/12/92