

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Renewed Corner R9W R8W  
S 36 / S 31 T22S  
S 6 T23S

Found - 1 1/2" Iron Pipe, galv., & wooden stake.  
54" Fir N.65°W. 77.9 ft., old uproot, dead, Good bark scribing.  
72" Fir N.70°E. 90.4 ft., old, dead, uproot, bark charred & covered with mud, no scribing found.

DID NOT SET BRASS CAP - Iron Pipe in good condition.  
New BT's: 9" D.Fir N.68°E. 45.8 ft. Mkd: T22S R8W S31 CS BT.  
20" D.Fir N.66°W. 25.0 ft. Mkd: T22S R9W S36 CS BT.  
D.Fir S.89°W. 30.4 ft. Mkd: T23S R8W S 6/CS BT.

Corner lies on steep N. E. slope.

Fd. OK. by: 25  
R. Luckman 1-13-83  
M 93-41

N. E. Corner Section 1, T23-9W. S 36

Found - 1 1/2" Galv. Iron Pipe at corner.  
Old, uprooted Fir, now 32", N.88°W. 19.1 ft., traces of old scribing visible on previously opened face. "S" only legible.  
Old, uprooted Fir, now 30", S.50°W. 15.8 ft., lying face down.  
40" Fir Stump N.20°E. 15.8 ft., bark flaking badly, no mks. vis.  
27" Hollow Chinq. snag S.70°E. 26.4 ft., both upper & lower blaze visible on bark, but entire center rotted away.

DID NOT SET BRASS CAP. - Corner lies on top of ridge.  
New BT's: 13" W.Fir S.44°E. 31.4 ft. Mkd: T22S R9W S36 CS BT.  
12" W.Fir S.49°W. 58.3 ft. Mkd: T23S R9W S1 CS BT.

S. W. Corner Sec. 36, T22 - 9 W., E. line Sec. 1, T23-9W.

Found - 40" Fir Stump, badly burned, N.40°W. 27.1 ft., found scribing, "S6 W" at bottom edge of upper face. BT. scar completely burned.  
Stump hole with Fir Roots S.30°E. 29.5 ft.  
No trace of Dogwood to N.E. Area has been logged & burned.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S S 1 | S 36 T22-9W  
Office, 1963 R 9W | S 6 T23-8W

Rescribe, 40" Fir Stump N.40°W. 27.1 ft. Mkd: T23S R9W S1 CS BT.  
New BT - 9" D.Fir S.70°E. 56.2 ft. Mkd: T23S R8W S6 CS BT.  
No other live trees near.

Corner lies on west slope approx. 300 ft. West of ridge top.

Section Corner to Secs. 13 & 24, T22-9W. and Secs. 18 & 19, T22-8W.

Found - ~~Bot~~ Brass Cap set in 1931.  
10" Hemlock, now 20", N.76°W. 22.4 ft., shows good scar. Didn't open.  
Shattered Cedar Snag N.51 1/2°E. 56.8 ft., fragmentary scribing visible on badly charred face, none legible.

No trace of either the S.E. or S.W. trees marked in 1931.  
New BT's: 26" Hemlock N.88°E. 32.6 ft. Mkd: T22S R8W S18 CS BT.  
9" Hemlock S.80°W. 33.6 ft. Mkd: T22S R9W S24 CS BT.  
18" Alder S.53°E. 6.0 ft. Mkd: T22S R8W S19 CS BT.

Note - Corner lies on very steep north slope, approximately 600 ft. West of Creek. (Gov't. notes, 1931, Call for Corner 3.54 chains West of Creek.)

Wft. Cor. Meander Corner S13/S18 (LEFT BANK)

Found - Brass Cap set in 1931, now buried 18" below surface of sand.  
Dead Alder Snag S.54°W. 50.2 ft. Did not look for scribing, snag badly rotted.  
Remains of rotted Alder Stump S.40°E. 48.2 ft. Too far gone to find markings.

Set - 2" Iron Pipe alongside Brass Cap - extends 16" above present level of sand.

New BT's: 16" Maple S.42°E. 48.2 ft. Mkd: "WC MC S18 CS BT.  
11" Maple S.63°E. 32.0 ft. Mkd: "WC MC S18 CS BT.  
No trees worth marking West of Line.

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy and Mike Stone  
March 1963  
C. S. File No. 52/14

25

26

27

28

29