

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

42

Section Corner(Wit.Corner) to Sections 23 - 24 - 25 - 26.
Found - Orig. 12", now 20" Fir, broken off & down, N.54°E. 44.2 ft.,
find scribe on log & stump.
No trace other Orig. BT's., corner would fall in Lutsinger Ck.Rd.
Set - 5/8" Iron Rod 2" below surface of road & go 25 ft. East and
Set Witness Corner: Brass Cap Mkd: County Surveyor's Office, 1967
Wit.Cor. S 23 | S 24 25 ft.
T22S R9W S 26 | S 25 W. to Cor.
New BT's: 4" Alder S.62°E. 8.3 ft. mkd. "W.C. S25 CS BT".
16" D.Fir N. 65° E. 41.7 ft. mkd. "WC T22S R9W S24 CS BT."
5" Alder N. 1° W. 7.0 ft. mkd. "WC S23 CS BT."
(1 in.) 8" Alder S.63°W. 54.7 ft. mkd. "W.C. T22S R9W S26 CS BT."
Note - Iron Pipe bears N.44°W. 14.1 ft. from Wit. Cor.

43

Sec.Cor. to Secs. 32 & 33, T22-9W. & Secs. 4 & 5, T23-9W.
Found - Orig. 40", now 36" Fir, burned stump, N.65°W. 9.2 ft., frag.
scribe marks on old axe blaze.
Orig. 36", now 26" Fir, burned stump, S.30°W. 49.5 ft.,
possible scribe on burned blaze.
No trace other Orig. BT's., this area apparently burned before
BT's: healed over.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967
R9W T 22S S 32 | S 33
T 23S S 5 | S 4
New BT's: 14" D.Fir N.53°W. 11.6 ft. mkd. T22S R9W S32 CS BT.
12" D.Fir N.16°E. 9.2 ft. mkd. T22S R9W S33 CS BT.
7" D.Fir S. 72° E. 6.0 ft. mkd. T23S R9W S 4 CS BT.
11" D.Fir S. 16° W. 13.9 ft. mkd. T23S R9W S 5 CS BT.
Note - This corner lies on westerly slope on spur ridge, course S.

44

Sec. Cor. to Secs. 34 & 35, T22-9W. & Sec. 3 & 2, T23-9W.
Found - 1 1/2" I.P. & Iron Cap at corner, unrecorded.
Orig. 60", now 66" Fir, alive, N.60°E. 46.9 ft., frag. bark scribe.
Orig. 30", now 32" Fir, decayed stump, S.50°W. 29.7 ft.(not 9.9 ft.),
no scribe.
Orig. 14", now 28" Fir Stump, S.20°E. 65.3 ft., opened & find "B".
No trace Orig. BT. to N. W.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967
T22S R9W S 34 | S 35
T23S S 3 | S 2
Deposit old corner pipe alongside.
New BT's: 7" D.Fir N. 49° E. 30.0 ft. mkd. T22S R9W S35 CS BT.
14" D.Fir N. 55° W. 50.1 ft. mkd. T22S R9W S34 CS BT.
15" Hemlock S. 79° W. 43.6 ft. mkd. T23S R9W S 3 CS BT.
17" D.Fir S. 40° E. 39.9 ft.mkd. T23S R9W S2 CS BT.
Note - This corner lies on N.W. slope of spur, sloping West.

45

Sec. Cor. to Secs. 33 & 34, T22-9W. & Secs. 4 & 3, T23-9W.
Found - Orig. 24", now 42" Fir, Alive, N.50°E. 23.8 ft.(slope), bark
scribing visible in poor condition. #88
Orig. 30", now 40" Fir, alive, S.30°W. 59.4 ft., bark scribing vis.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967
T22S R9W S 33 | S 34
T23S S 4 | S 3
New BT's: 12" Hemlock N. 2° W. 32.2 ft. mkd. T22S R9W S33 CS BT.
8" Maple N. 8° E. 18.5 ft. mkd. T22S R9W S34 CS BT.
8" Hemlock S. 16° W. 82.7 ft. mkd. T23S R9W S 4 CS BT.
8" Hemlock S. 28° E. 74.2 ft. mkd. T23S R9W S 3 CS BT.
Note - This corner lies on very steep, westerly slope approx. 175 ft.
west of ridge top.

46

1/4 Corner to Section 2 only, T23-9W.
Found - 1 1/2" Iron Pipe & brazed Iron Cap, unrecorded.
Orig. 16", now 38" Fir, alive, East 23.1 ft., shows scar, do not open.
Orig. 8", now 30" Fir, now down, West 34.3 ft., broken off stump
in place, scribed "1/4".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967
T22S R9W 1/4
T23S S 2
New BT's: 16" Maple. S. 89° W. 14.2 ft. mkd. 1/4" S 2 CS BT".
7" D.Fir S. 31° E. 18.4 ft. mkd. "1/4" S2 CS BT".
Deposit Iron Pipe alongside Brass Cap. - This corner lies on moderate
north slope of ridge.

Vernon "Ray" Tracy
Jack Heritage & V. Perron
December, 1967
C. S. File No. 54/60
F.D.B.C.
6/84 R. Howe
M 97-6