

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Deputy
& Crew
C.S. 52/86
Map File M 22 - 16

John M. Powell
W. Penley & J. Heritage
September, 1971
C.S. File 53/66

East $\frac{1}{4}$ Corner to Section 13, T22S.-R10W.
Found - Orig. 12", now 30" R.Fir, N.61°W. 18.5 ft., not 14.5 ft.
Shows good scar at base & old face above previously
opened & partly burned, no scribing found.

Sandstone at corner with chisled "S" on west face.
Set - Brass Cap alongside Corner Stone Mkd: County Surveyor's T22S
Office East $\frac{1}{4}$ S13 |
1961 R10W R9W

New BT's: Rescribed O.B.T.: 30" R.Fir N.61°W. 18.5 ft., $\frac{1}{4}$ S13 CS BT".
9" R.Fir bears N.29° E. 24.7 ft. scribed " S18 CS BT".

Sept.-Oct.1961

68

Section Corner to Section 31 and 32 T21-9

Found - 8" Fir, N.17 $\frac{1}{2}$ °E., 103.6 ft. This tree opened years ago & rotten.
30" Fir, S. 73°E., 128.7 ft. This tree destroyed in 1894.

I do not find NW BT.

Using these two trees, call on top of ridge of 42.9 ft. and coming 207.2 ft.
east from closing corner of $\frac{31}{615}$ I

Set: Brass Cap at sec. cor. mkd: County Surveyor's T 21 S R 9 W
Office S 31 | S 32
1971 S 5

New BT's: 22" D. Fir, N.83°E., 22.1 ft. Scribed T21S R9W S32 CS BT.
22" D. Fir, N.13°W., 24.7 ft. Scribed T21S R9W S31 CS BT.
10" D. Fir., S.21°E., 15.0 ft. Scribed S5 CS BT.

9/29/71

Closing Corner To Sections 6 and 5 T22-9

Found - Splintered Stump, N.17°W., 42.9ft. Scribed found "BT".
Possible BT, rotten and down, S.27 $\frac{1}{2}$ ° W., 59.4 ft.

I did not find SE BT.

Call on creek (draw) of 313.5 ft. from $\frac{31}{615}$ | $\frac{32}{615}$ or 106 ft. from $\frac{31}{615}$ hits good.

Set: Brass Cap at C.C. mkd: County Surveyor's T 21 S R 9 W
Office S 31 |
1971 S 6 | S 5
C.C.
T 22 S

New BT's: 18" D. Fir, S.61°W., 10.6 ft. Scribed T22S R9W S6 CC CS BT.
10" D. Fir, S.26°E., 17.6 ft. Scribed T22S R9W S5 CC CS BT.

9/29/71

Sec. Cor. to Sections 33 and 34, T21 - 9 W only. see C.S. 4/292 71

Found - 1" I. Pipe at Corner, unrecorded.

24" D.Fir, now 46" Stump, N.88°W. 38.9 ft., opened
for scribe "9W" & other marks.

24" D.Fir, now 40" Stump, S.76 1/2° W. 42.9 ft.,
shows axe work

No trace of S. E. Bearing Tree.

New BT's: 6" D.Fir N.53°W. 4.0 ft. scribed S33 CS BT.
6" Maple N.24°E. 12.9 ft. scribed S34 CS BT.
6" D.Fir S.80°E. 7.0 ft. scribed S 3 CS BT.

This corner lies about 80 ft. E. of skid road on ridge top.

10/5/71

Closing Corner for Sections 4 and 9 only. REN. #9 72

Found - 10" D.Fir, now 30 ft. Snag, S.82°W. 16.5 ft., scribe vis.
18" D.Fir, now 20 ft. Snag, S.52°E. 15.2 ft., shows scar.

Set - Brass Cap at C.C. Mkd: County Surveyor's T22S R9W
(Excav. for Brass Cap was Office S 4 |
made to Hard Sandstone) 1971 S 9 | C.C.

New BT's: 16" D.Fir S.56 1/2° E. 40.7 ft. scribed
"T22S R9W S9 CC CS BT".

6" D.Fir N.74°E. 12.6 ft. scribed "C S4 CS BT"

Note-This corner lies on steep, S.W. slope. Cap set shallow
in mound of stones about 2 ch. west of ridge top.

10/18/71