

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

83

SE corner for DLC #42 (Most easterly corner along north line DLC #43)
Set - I Set a 2 1/2" Brass cap marked: "T22S R9W W.M., S.E. Cor.
D.L.C. 42, 1977"

From which:

A 40" D. Fir stump, badly rotted orig. BT, with scribes T22S
R9W 42" visible, bears N.86°W., 693.0 ft.
Orig. Oak BT now missing.

New BT's-20" D. Fir, I scribed "T22S R9W Sec. DLC 42 BT" bears S.34°E
153.0 ft.

12" D. Fir, I scribed "T22S R9W Sec. DLC 42 BT" bears N.69 1/2°W
296.7 ft.

8/10/77

84

NE Corner for DLC #42.

Set - a 2 1/2" Brass cap marked "T22S R9W W.M., NEC DLC 42 1977"

From which:

54" D. Fir, orig. BT, with scribe "2" visible in opened face
bears S.20°E., 72.6 ft.

24" D. Fir, orig. BT with old burnt face, bears N.24°E., 16.5 ft.
(Rec. N.18°E.)

8" D. Fir, 1894 BT, now missing.

16" D. Fir, I Scribed "T22S R9W NEC DLC 42 BT" bears S.82°W.,
44.4 ft.

10/7/77

85

Meander Corner on North (right) bank of Umpqua River, common to Secs.
13, of T. 22-9, and 18, of T. 22-8.

Found - 1963 Douglas Co. Surveyor's B.C., buried 2-ft., Ren.# 34.
from which:

BT's - 18" rotten alder snag bears South, 17.8-ft.

12" rotten alder snag bears S.2-1/2°E., 14.4-ft., per Ren.#34.

24" oak, face evident, but rotted, bears S.31°W., 61.0-ft.
(Rec. S.37°W., 85.5-ft.)

BO - SW corner of concrete wall bears N13°W., 150.5-ft., Ren.#34.

Set - 7/8" x 48" galv. I.P., with plastic cap mkd. LS 1667, over
the B.C., from which:

New BT's- 8" alder bark scribed: T22S R8W MC BT bears N.79°E., 33.8-ft.

10" alder bark scribed: T22S R9W MC BT bears S.3°W., 15.6-ft.

5/8/82

86

SE Cor. DLC 44 & SW Cor. DLC 45, T.22S R.9W.

Set - 1-3/4" x 40" galv. I.P., 28" in grnd., with 2-1/2" B.C. mkd:

T22S R9W DLC 44, DLC 45 1982 LS 1667, from which:

52", three-stemmed cottonwood, scribed DLC BT bears
S.15-3/4°E., 4.0-ft.

22" oak, scribed SE, DLC 44, BT bears N.37-1/2°W., 31.3-ft.

14" oak scribed SW, DLC 45, BT bears N.69-3/4°E., 45.9-ft.

5/8/82

87

NE Cor. DLC 44 & NW Cor. DLC 45, T.22S R.9W.

Set - 1-3/4" x 24" galv. I.P., 12" in grnd. with a 2-1/2" B.C. mkd:

T22S R9W DLC 44 DLC 45 1982 LS 1667, from which:

10" oak scribed NW DLC 45 T22S R9W BT bears N.71-3/4°E., 105.4-ft.

12" D.Fir scbd. NW DLC 45 T22S R9W BT bears S.2-1/4°E., 316.5-ft.

5" D.Fir scbd. DLC BT bears N.15-1/2°W., 135.9-ft.

5/8/82

88

Section corner for Secs. 33 and 34; and Secs. 4 & 3 of T.23-9

Found - Iron fence post which had been placed, by me, along side corner
monument in 1980 and five BTs listed below. REN.# 45

Set - Drove Douglas County Surveyor's 30" x 1" galv. I.P. with 1967 brass
cap which had been removed by I.P. Co. cutting crew, alongside
the fence post from which:

34" D. fir stump, with IPCo tag, bears N.35°E., 23.5 ft.

6" burnt hemlock stob, with IPCo tag, bears S.29 1/2°E., 77.0 ft.

14" hemlock stump, with IPCo tag, bears S.14 1/4°W., 78.7 ft.

42" D fir stump, with IPCo tag, bears S.27°W., 57.3 ft.

15" hemlock stump, scribing visible, with IPCo tag, bears N.01°W.,
34.4 ft.

BTs in Sec. 3 and 4 treated with pentachlorophenol and covered with galv. metal.

8/82

Bruce Shaner
For: Reservation Ranch
Wm. Diekman; Mark Heimburger; Hank Cole
July, Aug. Oct.; 1977
C.S. 58/176

W. Carey Weatherly
For: W. Carey Weatherly
May 8, 1982
C.S. 58/247 (3pages)

W. Carey Weatherly
For: International
Paper Company
August 1982
C.S. 58/276