

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 10 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

36

Section Corner to Sections 5 and 4, T22-10W.

Found - 2" I.P., filled with concrete, and brass cap, broken off,
at corner point with 1919 BT's., as follows:

14", now 32" Fir, alive, S.75°E. 26.4 ft., shows good scar.

We do not open. Rescribe: "T22S R10W S 4 CS BT".

12", now 20" Alder, alive, S.31°W. 39.6 ft., shows scar.

We Rescribe: "T22S R10W S5 CS BT."

Set - Brass Cap at Cor.Mkd: County Surveyor's T21S
(Deposit old pipe & Office T22S S 5 | S 4 R10W
Brass Cap alongside)

Used Original BT's. to rescribe because new trees would be too far.

Note - This corner lies on steep N.W. slope 50' E. of small ravine,
course NE & approx. 200' W. of top of spur, sloping NE.

Dense salmonberry & vine maple brush.

37

Wit. Corner to Sections 32 and 33, T21-10W.

Found - 1965 C.S. Brass Cap & Stumps of BT's., See Ren. #28.

26" Fir Stump N.17°E. 6.8 ft., scribe visible on pitched blaze.

24" Fir Stump S.75°E. 15.4 ft., scribe visible on pitched blaze.

Set - 6 ft. Steel Fence Post alongside Brass Cap.

Note - No trees available for new BT's. Corner lies 35' south of
U.S.F.S. Rd. #2173 on top of cut bank in logged off area.

46

Section Corner to Sections 35 and 36, T21-10W.

Found - No trace of I.P. or Brass Cap set in 1919.

Orig. 14", now 26" Fir, turned out & slid downhill, N.39°E. 25.7 ft.

Orig. 60", now 65" Fir, 50 ft. high snag, N.53°W. 54.1 ft., open & fd. scribe.

Set - Brass Cap at Cor.Mkd: County Surveyor's T21S S 35 | S 36 R10W
(Set 6' Steel Fence Post) Office, 1968 T22S

New BT's: 14" Maple N.59°W. 47.3 ft. mkd. T21S R10W S35 CSBT.

16" D. Fir N.11°E. 57.2 ft. mkd. T21S R10W S36 CS BT.

38

Section Corner to Section 33 & 34, T21-10W.

Found - 1919 GLO Brass Cap, broken off with concrete-filled I.P., in place.

Orig. 22", now 38" Fir, alive, N.54½°E. 31.0 ft., shows good scar.

We do not open. Rescribed: "T21S R10W S34 CS BT".

Orig. 20", now 35" Fir, alive, N.83°W. 42.2 ft., shows good scar.

We do not open. Rescribed: "T21S R10W S33 CS BT".

Set - Brass Cap at Cor.Mkd: County Surveyor's T21S R10W S 33 | S 34
Office, 1968 T22S

We rescribed Orig. BT's. because nothing other than Alders close to North.
This corner lies on very steep S. slope approx. 175' W. of top of ridge.

39

North ¼ Corner to Section 2, T22-10W.

Found - 1919 GLO Brass Cap, broken off, concrete-filled pipe in place,
alongside corner tree, a badly decayed stump.

Orig. (1894) 40" Fir, now badly decayed snag, N.75°E. 15.2 ft., we open
and find "¼ S7" scribe.

(1919) 8", now 9" Fir, S. 5°E. 9.9 ft. (Rec. S.5W) now snag, we open
and find "¼ S7" scribe.

(1919) 16", now 22" Fir, alive, S.73°W. 7.9 ft., shows scar.

We Rescribe: "¼ S 2 CS BT".

Set - Brass Cap at Cor.Mkd: County Surveyor's T21S R10W ¼ S 2
Office, 1968 T22S

Set B.C. on north side of corner stump at place where bearings and
distances meet. Deposit corner material alongside Brass Cap.

New BT: 16" D. Fir S.22°E. 26.2 ft. mkd. ¼ S 2 CS BT.

Note - This corner lies on very steep S.E. slope approx. 75.0 ft.
west of ravine, course south.

40

Vernon "Ray" Tracy
Jack Heritage & V. Perron
May, 1968
C. S. File No. 54/1