

Douglas County Surveyor's Record of
Government Corners Renewed

T 22

T. S. R 10

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21991

102

Section Corner for 8 and 9 only.

(No original evidence found.)

Set - 2" x 30" alum. pipe with 3" alum. cap marked T22S R10 W S8|S9
S16 1989 LS 1342.

New BTs - I scribed a 10" D. fir N.14°E., 7.6 ft. scribed T22S R10W S9 BT.

I scribed a 21" D. fir N.59°W., 51.6 ft. scribed T22S R10 S8 BT.

Corner falls on north slope 790 ft. west of N/S ridge (Record 891).

103

South 1/4 Corner for Section 9 only.

Found - Original 36" (now 60" W.R. cedar N.87°E., 26.4 ft. (scar on
SW quadrant. No marks)

Original alder BT is missing

Set - 2" x 30" alum. pipe with 3" alum. cap marked T22S R10W S9
1989 LS 1342. ONLY

New BTs - A 40" D. fir N.60°W., 52.0 ft. scribed 1/4 S 9 BT.

Corner falls on North slope 117 ft. west of creek (record 82.5 ft.)

104

Closing Corner for Sections 15 and 16 only.

No evidence of original closing corner found.

Set - 2" x 30" alum. pipw with 3" alum. cap mkd. T22S R10W S9

1989 LS 1342.

S16| S15

New BTs - 33" cedar S.29°E., 31.8 ft. scribed T22S R10W S15 CC BT.

20" cedar S.44°W., 32.2 ft. scribed T22S R10W S16 CC BT.

Corner is on north slope 175 ft. west of a creek. (rec. 66 ft.)

105

West 1/4 Corner for Section 16

Found - Original position perpetuated by Oregon State Board of

Forestry. Ren. No. 64 1 1/2" iron pipe with 3" brass cap.

6" fir now 36" uprooted with visible "T" scribe N.29°E., 34.1 ft.

26" fir now 29" N.25°W., 18.5 ft. (Rec. face 17.6 ft.)

22" fir now 25" N.69 1/2°E., 15.3 ft. (Rec. face 14.3 ft.)

Both BTs with healed face.

New BT - A 12" maple S.25 1/2°W., 50.1 ft. scribed 1/4 S16 BT. A 1968 tag
reads N.28°W., 42 ft.

9/89

106

1/4 Corner for Sections 19 and 20

Found - Cross (X) at exacg corner point with 1/4 S on West side, this
point falling on a flat rock, 30ft x 40 ft. on North slope
(cross(X) and 1/4 S missing, sandstoen soft and badly decayed.
30 ft. x 40 ft. flat rock face in place)

4" chittem bears N.28°E., 125 lks.; now 12" badly decayed chittem
on ground with clump of live chittem surrounding stump hole.

8" fir bears S.80°W., 75 lks.; now 30" N.78°W., 49.2 ft. exposed
scribes 1/4. Evidence of bearing tree having moved approx.

3 ft. downhill on a steep rock face. I believe the original
bearing of S.80°W., should have been N.80°W.

Restored: Chiseled 1 ft. x 1 ft. cross (X) at corner point on 30 ft. x
40 ft. rock face, with 1/4 on West side

New BTs - 25" fir bears N.03°W., 15.6 ft. to an alum. nail in face,
scribed 1/4 S 19 BT.

26" fir bears N.75°E., 33.7 ft. to an alum. nail in face,
scribed 1/4 S 20 BT.

26" fir bears N.21°E., 34.0 ft. to an alum. nail in face,
scribed 1/4 S 20 BT.

34" fir bears N.04°W., 29.9 ft. to an alum. nail in face,
scribed 1/4 S 19 BT.

Set - 4" x 4" x 72" white painted cedar post N.02°E., 19.2 ft. from
corner point.

Magnetic variation 19 1/2° East.

4/25/90

Ronald Stuntzner
For: Siuslaw
National Forest
Sept. 1989
M 108 - 75

Oregon Dept
of Forestry
Lloyd D. Smith
Present and
Witnessed by
Tim Van Vleet
Eric Urstadt
April 25, 1990
C.S. 63/114