

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 12 W. R. W. W. M.

MOSE-CHAPMAN CO., EUGENE, ORE. 21881

44

Section Corner to Sections 5 - 6 - 7 - 8.
Found - Orig. 40", now 48" Spruce, S. 86° W. 35.0 ft., now badly
decayed stump. Open & find "S7 T22S R12W", scribe & reverse.
No trace other Original BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967

T 22 S	R 12 W
S 6	S 5
S 7	S 8

New BT's: 20" Spruce N. 46° E. 32.7 ft. mkd. T22S R12W S5 CS BT.
20" Spruce S. 82° E. 35.5 ft. mkd. T22S R12W S8 CS BT.
11" Spruce S. 40° W. 31.8 ft. mkd. T22S R12W S7 CS BT.
12" Alder N. 66° W. 28.7 ft. mkd. T22S R12W S6 CS BT.

Note - This corner lies in canyon bottom, course S. 25° E. on E. side
of ridge approx. 360 ft. from top.

Vernon "Ray" Tracy
Jack Heritage & E. West
June, 1967
C.S. File No. 54/46

45

1/4 Corner to Section 6 and 7.

Found - 2" I. Pipe & BT. as recorded in Ren. #1. (Set by Boyer, 1936)
40" Spruce Stump, badly decayed, S. 29° E. 9.2 ft. (face),
scribe marks visible.

New BT's: 6" Spruce S. 80° E. 11.0 ft. mkd. 1/4 S7 CS BT.
14" Alder N. 1° W. 12.3 ft. mkd. 1/4 S6 CS BT.
No trace of Boyer's S.W. BT.

Note - This corner lies 8.0 ft. W. 81° W. of old fence corner,
fences S. & E. and easterly slope ridge.

RENEWED CORNER NO. #167

James W. Byron, Co. Surv.
John M. Powell & J. Brady
August 24, 1967
C.S. File No. 54/46

46

Sec. Cor. to Secs. 33 & 34, T21-12W. & Sec. 3 & 4, T22-12W.

Found - No trace of Iron Pipe at Section Corner.

Orig. 24" Spruce, now 36" rotted Stump, S. 85° W. 11.9 ft.,
scribe visible "S4 22 R12W".

Orig. 20" Spruce, now 24" rotted Stump, N. 29° W. 34.3 ft.,
scribing found, "R12W T22".

No trace of N.E. or S.E. BT's.

Distances from Orig. BT's. taken from face.

Set - Brass Cap at Cor. Mkd: County Surveyors Office 1967

T 21 S	R 12 W
S 33	S 34
S 4	S 3

Note - (Brass Cap in 12"x24" Tile which is filled with concrete.)

New BT's: 38" Spruce N. 40° W. 83.6 ft. mkd. T21S R12W S33 CS BT.
38" Hemlock N. 73° E. 90.0 ft. mkd. T21S R12W S34 CS BT.
Power Pole, bearing object, S. 50° W. 110.7 ft. FP #AG04A-34.

Note - This corner lies in middle of draw running E. & W.
Also north of Forest Hills Road or 22nd., approx. 125.0 ft.

FD. OK 2/12/75 L.E.M. CO. SURV. OFF. C.S. 59/46

FD. OK
10/87
R. STUNTENER
M101-28

47

Meander Corner for Sections 6 and 7.

Found - 1 1/2" Iron Pipe for Meander Corner, See Ren. #2. (NOT A G10 M.C.)
(See C.S. 30/33 for 1 1/2" I.P. West of 1/4 Corner.) FLZ 2-28-90

Found 1 1/2" I.P. West of 1/4 Corner.

No other evidence found.

New BT: 30" Spruce N. 70° E. 15.5 ft. mkd. M. C. CS BT.

Note - This corner lies on very steep, south slope above Coast Guard Station.
Sept. 7, 1967

48

Sec. Cor. to Sections 7 & 18, T22-12W. & Secs. 12 & 13, T22-13W.

Found - R.P. Bolt set in solid rock 1' above shoulder grade on one side
of Oregon Coast Hwy. & R.P. RR Spke set in solid rock 2' above
shoulder grade on other side of Hwy.

Located metal object in highway with metal finder. Did not open.

(Ore. St. Hwy. set drill stem 18" long, 1" below surface of pavement)

Note - See Ore. St. Hwy. Map in file for sketch - Corner set in 1954.

8/13/73 - FOUND O.K. V.R.T. C.S. 56/35 - FD. OK 2/19/75 L.E.M. 59/46

49

Point on Range Line btwn. Rg's. 12 and 13.

Setting of point on range line from traverse line on S. edge of Co. Road.

Set - Brass Cap on Range Line Mkd: County Surveyors Office, 1967

T 22 S	R12W	S 12/	S 7	R12W
--------	------	-------	-----	------

New BT's: 7" Alder N. 68° W. 4.7 ft. mkd. T22S R13W S12 CS BT.
6" Alder N. 35° E. 9.0 ft. mkd. T22S R12W S7 CS BT.

Also find PK nail in rock point approx. 6.0 ft. high S. 77° E. 2.2 ft.
(See sketch in filed notes, C.S. File No. 54/54)

James W. Byron, Co. Surv.
John M. Powell, J. Brady &
D. West
August, 1967
C.S. 54/54 M 33 - 24