

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 12 R. W. W. M.

KOYE-CHAPMAN CO., EUGENE, ORE. 21881

ORE. ST. BD. OF FORESTRY - ARNOLD G. GIBSON
May 21, 1970 - C.S. File 55/154

Arnold G. Gibson, Ore. St. Bd. of Forestry
March 20, 1970
Map File M 33 - 79

65

$\frac{1}{4}$ Corner to Section 13 (E side), T22S, R12W, W.M. Douglas Co., Ore.
Orig.-Post (Missing, reported destroyed by Slang in 1910) from which a:
28" Fir bears N86° E 12 lks.; now 36" Wind fall, axe work visible.
24" Fir bears S 5° W 36 lks.; now missing.
35" Fir snag 75' tall bears S65 $\frac{1}{2}$ ° E 40.1 ft. to face; scribes $\frac{1}{4}$
visible in open face, no record of restoration.
Restoration by C.A. Sland, 1910.
Post missing from which a:
42" Fir bears S80° W 44lks.; now 44" stump in place, scribes $\frac{1}{4}$ visible.
36" Fir bears N49 $\frac{1}{2}$ ° W185 lks.; now 42", 56.1 Ft., X above grown over
face.
Restored
Set - 1 $\frac{1}{2}$ "x36" galv. I.P. with 3" bronze cap mkd. "Ore.St.Bd.For. $\frac{1}{4}$ S13 1970
RS359", 34" in ground, and from which a:
45" Fir (Slang's) bears N49 $\frac{1}{2}$ ° W55.7 ft. to face; scribed RS359.
37" Fir bears S49°W 85.5 ft. to face; scribed $\frac{1}{4}$ S13 BT.
Set - 4"x4"x72" white painted Cedar post 1.0 ft. NE of corner pipe. Ore.
St.For.Dept. metal location poster on 45" Fir BT N49 $\frac{1}{2}$ ° W 55.7 ft.
Dated May 21, 1970.

5/18/70

66

$\frac{1}{4}$ Corner common to Sections 24 and 25, T22S, R12W, W.M., Doug.Co., Ore.
Orig.-Hemlock post (missing) from which a:
40" Fir bears N88 3/4° E 65 lks.; now 75" stump, scribes $\frac{1}{4}$ S exp.
36" Cedar bears S 16 3/4° E 40 lks.; now 42" face grown over.
Restored
Set - 1 $\frac{1}{2}$ "x36" galv. i.p. with 3" bronze cap mkd. "Ore.St.For.Dept. $\frac{1}{4}$ S24
S25 1970 RS359". 34" in ground, in mound of rock, and from
which a:
42" Cedar bears N61° E 75.1 ft. to face; scribed $\frac{1}{4}$ S24 BT.
42" Cedar (orig.) bears S 16 3/4° E 24.0 ft. to face; scribed RS359.
Set - 4"x4"x72" white painted Cedar post 1.2 ft. NE of corner pipe. Ore.
St.For.Dept. metal location poster on 42" Cedar BT N 61° E 75.1 ft.
Dated May 21, 1970.

5/18/70

67

$\frac{1}{4}$ Corner common to Sections 26 and 35.
Found - Orig. Cedar Post, missing, from which a:
8" Spruce bears S.3°W. 40 lks.; now missing
24" Fir N.32°W. 6 lks.; now 60" stump, in place, scribe visible.
Restoration by Haines (No record found, date unknown--in tele. conversation,
Mr. Haines stated he had filed this corner. (Checked, corner not filed)
1" Tee Bar (found in place) from which a:
40" Hemlock S.8°W. 24.8 ft., to face; in place, face open, scribes visible
53" Hemlock bears N.61°W. 48.7 ft., to face, in place, face closed.
Set - 1 $\frac{1}{2}$ "x36" galv. I.P. with 3" br. cap mkd: "Ore.St.Bd.of Forestry $\frac{1}{4}$ S36
S35 1970 RS359", 34" in ground, over 1" T.Bar & from which:
46" Fir bears N.31°W. 51.8 ft., to face; scribe $\frac{1}{4}$ S26 BT RS359.
Set - 4"x4"x72" white painted Cedar post 1.2 ft. N.22°W. of corner pipe.
Ore.St.Forestry metal location poster on 46" Fir BT N.31°W. 51.8 ft.
5/22/70

FD OK 1/8/6
By: Lloyd Smith
M100-38

68

$\frac{1}{4}$ Corner to Sections 27 and 34.
Reset by proportionate measurement.
Set - Ore.St.Bd. of Forestry 1 $\frac{1}{2}$ "x36" Galv. Iron Pipe with 3" Bronze Cap. 102
36" Spruce N.82 $\frac{1}{4}$ °W. 7.5 ft., Yellow metal location poster.
16" Fir S.15 $\frac{1}{2}$ °E. 17.3 ft. (RS 359).
4"x4"x72" White painted Cedar Post N. E. 1.2 feet.

69

Section Corner to Sections 26 - 27 - 34 - 35.
Section Corner Reestablished.
Set - Ore.St.Bd.of Forestry 1 $\frac{1}{2}$ "x36" Galv.I.P. with 3" Bronze Cap. 101
21" Fir S.52°W. 12.9 ft., yellow metal location poster.
29" Myrtle (Dbl. Trunk) S.81°E. 34.0 ft.
16" Fir N.10°W. 24.3 ft. (RS359).
4"x4"x72" White Painted Cedar Post 1.0 feet from corner, S. W.