

Douglas County Surveyor's Record of
Government Corners Renewed

T.22 S. T.S. R.12W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

109

Meander Corner btwn. Sections 19 and 30.
Found-30" Fir Snag Corner Tree, bark scribed visible, "MC"
& other scribe marks.

40", now 55", Spruce, S.65°W. 9.9 ft., shows scar.
No trace of N.E. Bearing Tree.

Set-Brass Cap alongside S.E. side of Corner Tree mkd:
County Surveyor's Office

T22S R12W
S 19
M.C.S330
1973

New BT: 40" Spruce N.52°E. 30.6 ft. scribed, "T22S R12W S19=
M.C. CS BT".

Note: This corner lies on E. side of ridge(orig. call 24.43 ch).
Also lies approx. 15 ft. above lake.

10/2/73

110

Meander Corner to Sec. 24, T22-13 & Sec. 19, T22-12W.
Found-40" Spruce, now stump, found reverse scribed "M".
Set-Brass Cap at M.C.Mkd: County Surveyor's Office

T.22 S.
R13W S 24 | S 19 R12W
1973

New BT's: 13" Spruce S.26°W. 31.3 ft. scribed "M.C. S24
T22S R13W CS BT".
13" Spruce S.19-1/2°E. 33.3 ft. scribed "M.C. S19
T22S R12W CS BT".

FD. OK 2/20/75 CO. SURV. OFF. L.E.M. C.S. 59/46

111

1/4 Corn. Sec. 3 and Sec. 34, T21-12.

Found - Chisled "+" in concrete on east abutment of bridge
bears S.35°16'W., 191.1 ft. Ren. No. 6
Chisled "+" in concrete on east abutment of bridge
bears S.55°28'W., 15910 ft.

Set - Brass cap from found bearing objects, per telephone
conversation from Eugene Bloom, 11/8/73.

Baughman Surveying
for Lillebo &
Holliday
M 49 - 41
April 1973

112

1/4 Corner for Secs. 4 and 5

Found - Old sq'd. 5"x5"x36" Post, down, not in true position,
O.B.T., 24" rotted spruce stump w/old axe work, S.43°W.,
25.0 ft.

O.B.T. 48" D. Fir stump w/ old face, scribe destroyed
by logging. S.40°E., 16.5 ft.

Set - 1 1/4" I.P., scribe "1/4S 3683 BT" on:
19" Hemlock, S.81°30'E., 17.6 ft.
9" Hemlock, S.44°W., 12.5 ft.

FD OK PER HINTZ
3-87 MIB-59
FD 9/93
M117-64

FD. OK 2/18/75 CO. SURVEYOR'S OFFICE L.E.M. C.S. 59/46

SEE C.S. 63/46
FOR CORNER REPORT

113

1/4 Corner for Secs. 5 and 6

Found - O.B.T. 24" rotted Spruce stump w/remains of old axe work
and face at base, S.38°W, 11.2 ft

18" 2nd growth spruce growing in rotted remains of
former O.B.T. spruce stump, N.77°E., 10.6 ft.

Set - 1 1/4" I.P., scribe "1/4S 3683 BT" on:
29" Hemlock, S.48°E., 16.6 ft.
17" Hemlock, S.62°45'W., 20.4 ft.

SEE C.S. 63/46
FOR CORNER
REPORT

114

1/4 Corner, Sec. 5 and T21-12 Sec. 32

Found - O.B.T. 30"x10' tall rotted spruce stub, "BT" scribe
visible (also fd. by Epstein, C.S., 1925) See Ren.
#3 in T21-12

Set - 1 1/4" I.P. (in swamp), scribe "1/4S 3683 BT" on: #186
18" Alder, N.8°30'E., 18.5 ft.
17" Alder, S.71°30'W., 51.4 ft.

RENEWED CORNER NO. #186

Ed. Monrean & J. Powell
October, 1973
C.S. File No. 56/39

Robt. Thompson
For Edin Properties
M 51 - 65 C.S. 55/328
Apr.-Nov. 1973