

Douglas County Surveyor's Record of  
Government Corners Renewed

T 22 T. S. R 12 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91981

Ronald Stuntzner  
Dec. 10, 1986  
M 103 - 31

193

Section Corner for Secs. 5 and 4 only of T.23-12  
Corner report only, from infor. filed with Coos Co. only)  
Section Corner per proportion: (See Ren. No. 16)  
1" iron pipe  
20" D. fir, N.40°E., 23.4 ft.  
24" D. fir S.70°W., 18.5 ft.  
10" D. fir, S.50°E., 14.8 ft.

194

North 1/4 Corner for Sec. 4 only, T.23-12  
Set - 5/8" x 30" iron rod with I.D. cap mkd. Stuntzner Eng.  
BT - 58" W. R. Cedar S.84°W., 16.9 ft.  
(information filed previously with Coos Co. only) See our Ren. #17

195

Center 1/4 Corner for Section 36  
Set - Oreg. State Bd. of Forestry 1 1/2" x 36" alum. pipe with cap, 34"  
in the ground.  
New BTs - 27" Fir, S.38°W., 14.8 ft. scribed C 1/4 S36 BT and bearing tree tag  
37" Fir, N.22°W., 32.0 ft. scribed C 1/4 S36 BT and BT tag.  
4"x4"x72" white painted cedar post, S.48°E., 1.2 ft.

Lloyd D. Smith  
For: State of  
Oregon, Dept. of  
Forestry  
December 30, 1986  
M 103 - 42

196

1/4 Corner for Section 36 only. South boundary.  
Set - Oreg. State Dept. of Forestry 1 1/2" x 36" alum. pipe with cap, 34"  
in ground.  
New BTs-32" maple, N.25°W., 41.7 ft. scribed 1/4 S36 BT with bearing tree tag  
48" cedar, N.52°E., 40.1 ft. scribed 1/4 S36 BT and BT tag.  
A 1 ft. wide creek west 5 ft. course S.87°W., from N.67°E white painted  
cedar post., S.34°E., 1.2 ft.

FO. OK 2/92  
H. WILCOX M114-75

197

True Township corner for Sections 36 and Sec. 31 of T.22-11  
Set - Oreg. State Dept. of Forestry 1 1/2" x 36" alum. pipe with 3 3/4" alum.  
cap and magnetic insert, 34" in ground.  
New BTs-31" fir, N.08°W., 79.2 ft. scribed T22S R12W S36 CC BT with bearing  
tree tag.  
27" cedar, N.25°W., 17.3 ft. to nail in base of face (OSDF 1982  
northwest BT) and bearing tree tag.  
OSDF pipe/cap, S.0°10'02"W., 20.97 ft. stamped AM.  
White painted cedar post, N.69°E., 1.2 ft.  
Original closing corner bears S.0°10'02"W., 20.97 ft. Ren. #155-T22-11

Richard Hintz  
For: International Paper  
Co., March 1987  
M 103 - 59

198

1/4 Corner Sections 3 and 4.  
CORNER REPORT ONLY  
Found: 1 1/8" Iron rod set in concrete on the South line of  
Highlands Addition to the City of Reedsport.  
Note: Origin unknown but accepted as the best available evidence  
of the position of the original corner.

FA 9/93  
M 117-64

Bruce Shaner  
For: Moore Hill & Lumber Co.  
February, 1987 RM 3 - 66A&B

199

1/4 Section Corner for Section 22 and 23. See Ren. # 200  
Set - A 2 1/2" brass cap on a 2" x 34" Iron pipe, marked "1/4 S22,  
, S23, 1987, RLS 430".  
BT's - A 18" spruce bears N48E, 13.4 ft. scribed "1/4 S23 BT".  
24" Hemlock stump bears N40W 2.5 ft. scribed "1/4  
S22 BT".  
Note: Section 22 has been recently clearcut logged.

200

1/4 Corner for Section 22 and 23. See Ren. #162  
Found - A 2 1/2" brass cap with a 2" iron pipe, marked "1/4 S22, S23, 1982"  
BT's - A 22" Alder BT bears S75 1/2°W., 9.9 ft.  
21" Alder BT bears N12°E, 42.4 ft.  
Note: This corner was set in the wrong place by Surveyor Ward. Per  
this survey. See Renewal #199 for new corner information.

FO. OK 5/91  
M 113-35 A&B