

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 22 T. S. R. 12 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

W. Carey Weatherly LS 1667
For: International Paper Co.
Nov. 1991
C.S. 63/129

243

1/4 Corner between sections 9 & 16.

Found - 30" downed hemlock, N.60°W., 25.5 ft. orig. BT. (rec. N.59°W., 24.4'
Set - 3/4" x 12" aluminum rod with 5" aluminum tip and 3 1/4" alum. cap
12" below gravel surface of logging road in ditch line on
northerly side of road. Buried orange magnetic marker next
to monument. See renewal No. 222

New accessories -

18" W. Red Cedar bears N.49 1/4°W., 52.9 ft. to spike in side.(dead)
24" burned W. Red Cedar stump 12' high bears S.81 1/2°E., 50.4'
to spike in side.
17" burned D. Fir stump 12' high bears S.41°E., 36.3' to
spike in side.
27" D. Fir stump 1' high bears S.0 1/4°E., 35.6' to spike in side.
6' aluminum post with survey monument sign and IPCo. location
tag bears North 7.0'.

Note - Monument and 2 BT's set by Stuntzner in 1985 (M98-54) and spruce
stump (orig. BT) destroyed during road const. Prior to road
const. 3 reference points were set.

12/03/91

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
January 30, 1992
C.S. File 64/23

244

South 1/16 Corner for Secs. 17 and 16

Found - 2 3/8" dia. 1986 DCSO brass cap on a 1 3/8" O.D. Iron pipe
protruding 6" above a 2 ft. dia. mound of sandstone. Ren. #214
Three BTs as recorded in Ren. #214 found OK.
8" Spruce bearing S.8 1/2°E., 67.2 ft. is now down and out of
position.

Position of S 1/16 cor. was in error because of a problem with tie made to
SE cor. of Section 17 in 1986. Position of DCSO BC/IP is referenced, BC/IP
is removed, I.P. measured 32" long.

Set - A 5/8" x 30" long Iron rod with plastic DCSO cap is set at
referenced BC/IP position. Iron rod protrudes 4" above a 2 ft.
dia. mound of sandstone.
The marks "RESET 1992" are added to DCSO brass cap. BC/IP is set
at a newly determined position of the S 1/16 cor. BC/IP
protrudes 5" above mound of sandstone.

BTs - 13" now 14" dia. Spruce with a partially healed double blaze,
scribing visible "S 1/16 S17 CS BT" (S16 changed to S17) bears
N.4 1/2°W., 52.2 ft.
19" now 20" dia. Alder with a partially healed double blaze,
scribing visible "S 1/16 S16 CSBT" bears N.58°E., 24.5 ft.
22" now 23" dia. Alder with a partially healed double blaze
scribing visible "S 1/16 S17 CSBT" bears S.33 1/2°W., 14.9 ft.
5/8" Iron rod with plastic DCSO cap bears N.23 3/4°W., 8.9 ft.

Corner lies near the bottom of a steep slope approx. 20 ft. northeast
running creek. Bearings taken with staff compass.

1/30/92

245

Closing Corner for sections 1 & 2, T. 23-12

Found - 3 1/2" alum. cap on 1 3/4" alum. pipe in creek. 4" X 4" white post
bears N.60°W., 3.9 ft. (Smith) See renewal no. 182.

Fnd. BTs- 11" Alder w/bark scribe and tag bears S.30°W., 80.4 ft. (Smith)
18" Alder w/bark scribe and tag bears S.14°E., 67.6 ft.
(69.4 ft Smith)

New BT - 38" Cedar scribed and tagged bears N.38°W., 52.9 ft.

4/13/92

246

North 1/4 Corner for section 1 only. T. 23-12

Set - 3 1/4" alum. cap on 3/4" X 24" alum. rod w/alum. post and sign
alongside. Buried a magnetic marker alongside.

BT's - 28" Fir scribed "1/4 S1 BT" with "X" and tags, bears S.84°W., 8.1'
46" Cedar scribed "BT" with "X" and tags bears N.31°E., 41.1 ft.
26" Maple, face scribed "BT" with "X" and tags bears N.61°E. 72.5'
42" Fir scribed "1/4 S1 BT" with "X" and tags brs. S.49°E., 36.1'

4/13/92

Harvey Wilcox
For: International Paper
Feb. 1992
M 114 - 75
C.S. 63/119