

Douglas County Surveyor's Record of
Government Corners Renewed

22

T. S.

13

R. W. W. M.

$\frac{1}{4}$ section corner to section 36, T22S, R13W., and section 31, T22S, R12W.
Found $\frac{3}{4}$ inch X 10 foot iron pipe at 3 inch X 3 inch sq. post, scribed $\frac{1}{2}$ " #21
corner on North face, 31 on East face, 36 on West face and D. L. on South
face.

James W. Byron, Dep.
County Surveyor.
March 3, 1955.
C. S. File 46/110.
M 7-12

FD. 1976 L.E.M. Co. Surveyor File C.S. 60/17 No Orig. Evidence FD.

$\frac{1}{4}$ Section corner to secs. 12 and 13.
A 2" iron galvanized pipe is now at the place purported to be the $\frac{1}{4}$ sec. cor.
Said pipe placed there before any of the present owners now living on the ground.
Two bearing trees now showing, one a blaze on a 48 inch spruce stump, no
scribe seen, the other a 36 inch spruce stump, now rotten, the scribe BT
very visible, on the tree of this stump, a blaze 2 feet long with the
following, C. S. $\frac{1}{4}$ S.12 with some cruisers monicker. The 48 inch stump
bears S.66°W., 10.5 feet. The 36" spruce bears N.37E., 5.8 feet.

Wm. J. Brayton
Feb.-Apr., 1955.
C. S. File 41/342.

(See Renewal Previous to this -) (Ren #5)

Center of Section 13.

Set Iron Pipe for Center Section.

30" Spruce B.T. leaning to W. N. 10°W. 40 feet. #19
30" Fir B.T. N. 50°E. 25 feet.
16" Fir B.T. S. 45°W. 16 feet.
36" Spruce BT. S. 15°E. 30 feet.

H. L. Epstein,
Co. Surveyor
Oct. 1931.
C.S. 18/20A & B.
Map M 1 - 74

$\frac{1}{4}$ Section Corner to Sections 12 and 13.

Found - 2 $\frac{1}{2}$ " I.P. from which a rotten stump bears #17
N. 35°E., 5.2 ft. with scribing still visible.
(See Renewal No. 8, above.)

New BT's: 16" Spruce bears N. 76 $\frac{1}{2}$ ° E., 53.8 ft. $\frac{1}{4}$ S12 B.T.
45" Spruce (broken top) bears S. 87°E. 106.4 ft. $\frac{1}{4}$ S13BT.

Richard J.
Hintz
Aug. 23,
1963
C.S. File
No. 51/252

Sec. Cor. to Sections 7 & 18, T22-12W. & Secs. 12 & 13, T22-13W.
Found - R.P. Bolt, set in solid rock 1' above shoulder grade on one
side of hwy. & R.P. RR spike set in solid rock 2' above
shoulder grade on other side of hwy.

Also located metal object in highway with metal finder.
Did not open.

(Ore. St. Hwy. Dept. set drill stem 18" long, 1" below surface of
pavement when new road was built in 1954.)

See Ore. St. Hwy. Dept. sketch in file. 8/73 - FD.O.K. - Y.R.T. C.S. 56/35

Point on Range Line btwn. Ranges 12 and 13.

Setting of point on range line from traverse line on S. edge of
County Road.

Set - Brass Cap on Rge. Line Mkd: County Surveyors T22S
Office, 1967 R13W S 12/ S 7 R12W

New BT's: 7" Alder N. 68° W. 4.7 ft. mkd. T22S R13W S12 CS BT.
6" Alder N. 35° E. 9.0 ft. mkd. T22S R12W S 7 CS BT.

Also fine PK nail in rock point approx. 6 ft. high S. 77°E. 2.2 ft.
(See sketch in field notes, C.S. 54/54)

James W. Byron, Co. Surv.
John Powell - J. Brady - D. West
August, 1967
C.S. File No. 54/54 - M 33 - 24

MICROFILM TO HERE 10/67

$\frac{1}{4}$ Corner to Sec. 30, R12W and Sec. 25, R13W. (Found Only)

Found - 1/2" I. Pipe recorded in M20-69, no other record.

2 unrecorded BT's., as follows:

6" Dead Fir N. 59°E. 21.2 ft., scribe visible, "SO T22R12 @ S"

22" Dwarf Pine N. 30°W. 57.8 ft., scribe visible, " $\frac{1}{4}$ S25
T22S R13W", scribed about 30-40 years ago.

Note: No BT. scar or scribe on either tree, No trace of Orig. BT's.
This cor. lies approx. 250' S. of power line access road at S. end of
Clear Lake.

FD. O.K. 2/18/75 - Co. Surveyors Off. L.E.M. C.S. 59/46 8/15/73

V. "Ray" Tracy
J. Heritage & J. Isgero (Land)
Aug. 1973
C.S. File No. 56/351

FD. O.K. 2/19/75
L.E.M.
C.S. 59/46

FD. O.K. 11-92
J. M. J. J.
M 116-11