

Douglas County Surveyor's Record of
Government Corners Renewed

T 23 T. S. R 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C O N T.

New BT's - A 7" Fir, bears N. 76°E., 14.7 ft. scribed "T23S R1W S36 CS BT" in a double blaze. (Note bearing taken approx. 1.0 ft. south of tree trunk due to shape of tree.)
A 13" Fir, bears S.9 1/2°W., 20.1 ft. scribed "S 2 T24S R1W CS BT in a double blaze.
Cor. lies on NE slope.

10/21/76

5

Gary L. Langlitz
Gregory Quibell
Karen Cheney
Oct. 21, 1976
C.S. 59/24

1/4 Corner for Sec. 31 only of T23-1E. West boundary

Found - 1925 GLO brass cap properly marked.
6" now 15" Fir, bears S.26°E., 18.5 ft. We open and find scribing. Tree alive and well.
12" now 34" Fir, bears N.50°E., 39 ft. (Rec. 35.6 ft.) Tree alive and well.

Set - At corner point we reset Iron pipe with brass cap uprooted at site.
New BT - An 8" Fir, bears S.63 1/2°E., 17 ft. scribed 1/4 S31 CS BT with double blaze.

Note - Corner is 50 ft. west of Road 2422 Z.

11/2/76

6

Section Corner for Secs. 25 and 36 only. East Boundary.

Found - Stone, 6" x 10" x 8", S25 on NW face, S36 on SW Face, four notches on North edge (rec. 5) and one notch on South edge.
5" now 12" Hemlock, bears N.86°E., 24.4 ft. Scribe obliterated in 1925 resurvey.
8" now 16" Hemlock, bears S.23°E., 17.1 ft. (Rec. 18.5 ft.) Scribe obliterated in 1925 resurvey.
8" Hemlock, bears S.6°W., 21.1 ft. uprooted and badly rotted. Scribe mark found "S".

Northwest bearing tree not found.

Set - 30" x 1" Iron pipe with brass cap at corner point stamped:
"Douglas County Surveyor"

R	T 23 S	R
1	S 25	1
W	S 36	E
	1976	

We place orig. stone monument on West edge of cap.

New BT - An 8" Hemlock, bears N.35°W., 17.4 ft. Tree double blazed and scribed "T23S R1W S25 CS BT"

There are no suitable trees to scribe in South quad.

10/26/76

8

A. Victor Cangie
M. Tompkins
Doug. Co. Surveyor
Nov. 3, 1976
C.S. 59/26

1/4 Corner for Secs. 26 and 25.

Found - 1960 brass cap stamped 1/4 S26 S25, uprooted by logging.
A 44" Fir stump bears S.57°E., 5.9 ft. Stump shows visible "BT" in partially healed blaze.
A 22" Hemlock stump bears N.57°W., 29.0 ft. Open, unhealed blaze shows "1/4 S2". Remainder of stump is covered by a slide.

Set - We replace found brass cap at corner point established from above stumps and stamp "1976" on it.

Corner is in a large clearcut unit and there are no trees available for scribing. We Set a 5/8" x 30" Iron Rod with Douglas County Aluminum cap stamped "B.O." in a 51" Fir stump. Rod bears N.70°E., 70.9 ft.

11/3/76

9

1/4 Corner for Sec. 36 and Sec. 1 of T24-1

Found - An orig. 12" now 24" Hemlock, down and rotten with illegible scribe marks visible on a previously opened blaze.
An orig. 30" now 36" Hemlock, alive and in good condition with illegible scribing visible on previously opened blaze.
The original corner post is gone.

At the corner point as determined by the found orig. BT's as follows:

A down 24" Hemlock, bears N.16 3/4°W., 27.7 ft. and a
36" Hemlock, bears S.76 1/2°W., 29.0 ft.

We set - A 1" x 30" Iron pipe 26" in the ground on a steep east slope approx. 30 ft. West of a small ravine, with brass cap attached marked:

DouglasCo. Surveyor

	T 23 S	R
1/4	S 36	1
	S 1	W
	T 24 S	
	1976	

Gary L. Langlitz
A. Vic Cangie
M. L. Tompkins
Oct. 28, 1976
C.S. 59/24