

Douglas County Surveyor's Record of
Government Corners Renewed

T 23 T. S. R 1 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C O N T -

From which we mark the following:

New BT - A 6" Hemlock, bears N.40 1/2°E., 9.9 ft. scribed "1/4 S36 CS BT" on a single blaze.

3-77

10/28/76

1/4 Corner for Secs. 35 and 36.

Found - Basalt stone and orig. BT which bears N.48°W., 31.4 ft. Found scribing "1/4 S. Was 13" now 25" Fir.

10

1/4 X on west face of stone.

Set - 2 1/2" x 36" I.P. with brass cap marked: T23S R1W 1/4 S35 S36 1977 PLS 536. Placed orig. stone alongside of pipe on west side.

New BT's-6" Fir bears S.56°30'W., 7.2 ft. scribed 1/4 S35 BT.

6" Hemlock bears S.72°30'E., 26.3 ft. scribed 1/4 S36 BT.

12/77

11

1/4 Corner for Secs. 25 and 36.

Set - 2 1/2" x 36" Iron pipe with brass cap marked: T23S R1W 1/4 S25 S35 1977 PLS 536.

BT's- 12" Hemlock bears S.38°E., 13.2 ft. scribed 1/4 S36 BT.

15" Hemlock bears N.54°W., 17.9 ft. scribed 1/4 S25 BT.

12/77

12

1/4 Corner for Sec. 36. East boundary.

Set - 2 1/2" x 36" I.P. with brass cap marked: T23S R1W R1E 1/4 S36 1977 PLS 536.

BT 's - 16" D. Fir bears N.20°E., 17.2 ft. scribed 1/4 S36 BT.

18" D. Fir bears S.63°W., 39.0 ft. scribed 1/4 S36 BT.

12/77

13

Township corner for Sec. 31; and Sec. 36 of T.23-2; Sec. 6 of T.24-1 and Sec. 1 of T.24-2.

Found - 1964 GLO brass cap, not disturbed by adjacent timber felling. Orig. 50" Fir stump, S.48°E., 22.0 ft. to face, 24.0 ft. center measurement; no scribing found.

36" Hemlock, S.38°W., 18.0 ft. to face, 19.3 ft. center measurement; scribing visible on mostly healed face.

32" White Fir snag, N.66°W., 20.8 ft. to face, 21.9 ft. center measurement; scribing, extremely fine, on round surface of tree, not on a flat face.

18" White Fir, N.34°E., 30.7 ft. center measurement; scribing visible.

Accessories added:

64" Fir, N.8°W., 61.3 ft.

48" Fir stump, S.48°E., 21.1 ft. (Orig. BT)

Bearings and distances are to "W" nails driven into base of reference trees; Weyerhaeuser plates on trees.

3/78

14

1/4 Corner for Sec. 31; and Sec. 36 of T.23-2

Found - 1964 GLO brass cap.

Down, windthrown 36" Fir, slid down hill; plate intact, face partly healed, bears S.44°E., 20.5 ft. to center of root hole.

32" Fir; low face healed over; BLM BT plate intact bears S.55°W., 51.7 ft. to center of tree measurement.

Accessories added:

40" Fir, N.69°E., 8.3 ft.

18" Hemlock, S.61°W., 3.8 ft.

32° Red Cedar stump, bears N.78°W., 50.8 ft.

Trees have "W" nails with Weyerhaeuser plates.

3/78

15

Glenn S. Baughman
For: U.S. Forest
Service
December, 1977
M 65 - 51

Glen McChesney
For: Weyerhaeuser
Company
March 10, 1978
C.S. 58/8
(Filed 12/80)