

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Closing Corner Sections 30 and 31, T23-2W. 7

Found - Weyerhaeuser Corner with evidence of Orig. Corner.

1 1/2" I.P. for cor. & 10 ft. high marker pipe.

Weyerhaeuser BT: 50" Fir Stump N.32°E. 4.3 ft., "W" Nail & Tag.

Orig. 36" Fir, now 40" Stump, N.50°E. 24.4 ft., cut open & face burned. No scribe.

Orig. 16" Fir, now 17" Stump, S.40°E. 29.0 ft., cut open, scribe vis.

Orig. 24", now 30" Fir Stump, N.18°W. (Record N.31°W.) 12.5 ft., shows good scar. Do not open.

Note - This corner lies 75 ft. E. of spur, sloping south approximately 730 ft. N. of corner of secs. 25 & 36, T23-3W.

11/3/67

Southeast Corner of Section 36, T23-3W. 8

Found - 1/2" I.P. "Weyerhaeuser" Method, See C.S. File No. 53/107.

Orig. 26", now 42" Fir Stump, N.45°W. 8.6 ft., old bark scribe visible in poor condition. Also "W" Nail.

40" Fir Stump N.47°E. 13.7 ft., "W" Nail & Tag. R R

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S 3 S 36 2
(Reset I.P. alongside) Office, 1968 T24S W W

New BT: 60" Fir Stump N.47°W. 26.1 ft. mkd. T23S R3W S36 CS BT.

Note - This corner lies on S.E. slope on top of cut bank of old Cat Road in logged-off area.

9

Closing Corner Sec. 31, T23-2W. & Sec. 6, T24-2W.

Found - 1/2" Tubing at corner & 1/2" I.P. for marker with Orig. BT/s. & "W" method BT., as recorded in Ren. #3, & C.S. 53/106.

Orig. 16", now 24" Cedar, now 5' high stump, N.10°E. 27.7 ft., scribing visible on nearly healed blaze.

Orig. 60" Fir, now 64" Fir Stump 2 ft. high, S.57°E. 25.1 ft., top of blaze visible on top of stump.

26" Hemlock Stump S.50°W. 18.1 ft., "W" Nail & Tag. R R

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S 3 C S 31 2
(Reset 1/2" Tube alongside) Office, 1968 T24S W C S 6 W

New BT: 9" Cedar Snag N.44°E. 28.9 ft. mkd. T23S R2W S31 CC CS BT.

Note - This corner lies on E. side of spur, ridge sloping south approx. 50 ft. E. of top.

10

SEPT. 68

Section Corner to Sections 26 - 27 - 34 - 35.

Found - Probable Corner Stone, broken in several pieces.

Unrecorded 3/4" Iron Rod, 24" long at corner point.

Orig. 36", now 40" Fir N.57°E. 32.3 ft., alive.

Orig. 12", now 15" Hemlock, alive, S.15°E. 6.6 ft., scribe visible.

Rescribed: "T23SR2W S35 CS BT".

Orig. 15", now 21" Cedar, alive, S.57°W. 13.2 ft., scribe visible.

Rescribed: "TT23S R2W S34 CS BT"

Orig. 40", now 48" Fir, alive, N.45°W/ 10.6 ft., shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyor/s T 23 S R 2 W
Office S 27 S 26
1969 S 34 S 35

New BT: 13" Hemlock N.50°E. 35.7 ft. mkd: "T23S R2W S26 CS BT".

This corner lies 190 ft. W. of creek, course N.W. & 50 ft. E.

Top of rounded spur, sloping North.

7/1/69

1/4 Corner to Sections 35 and 36. 11

Found - Stone 15"x18"x12" mkd. "X" on top, not called for in notes.

Orig. 8", now 18" Fir, down, East 19.1 ft. Open to old blaze, not scrbd.

Orig. 12", now 22" Fir, down, N.65°W. 21.8 ft., open & find scribe.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 2 W
(Reset stone alongside) Office, 1969 1/4 S 35 S 36

New BT's: 6" Fir N.46°W. 14.9 ft. mkd: "1/4 S35 CSBT".

11" Fir N.79°E. 31.0 ft. mkd: "1/4 S36 CSBT".

This corner lies 15 ft. north of small creek, course east.

7/2/69

C.S. File No. 54/16

Vernon "Ray" Tracy
Jack Heritage & V. Perron
April, 1968
C.S. File No. 54/27

JULY, 1969
C.S. File 54/27