

Douglas County Surveyor's Record of  
Government Corners Renewed

T 23 T. S. R 2 R. W. W. M.

ROBE-CHAPMAN CO., EUGENE, ORE. 21881

34

Donald L. Peel  
LS #752  
For: Triangle Engin.  
Aug. 28, 1979  
C.S. 58/176

1/4 Corner for Secs. 26 and 35  
Found - 1969 County brass cap in place, in a mound of stone. Ren. #16  
Orig. Fir, 40" bears N.43°E., 21.8 ft. closed face.  
Orig. Hemlock snag, down down.  
Two County BTs, now down.  
New BT - A 42" fir stump, bears S.1°E., 63.3 ft. scribed 1/3 S35 BT.  
8/28/79

35

Township corner, Sec. 36; and Sec. 31 of T.23-1; Sec. 6 of T.24-1;  
and Sec. 1 of T.24-2.  
Found - 1964 GLO brass cap, not disturbed by adjacent timber felling.  
Orig. 50" Fir stump, S.48°E., 22.0 ft. to face, 24.0 ft. center  
measurement; no scribing found.  
36" Hemlock, S.38°W., 18.0 ft. to face, 19.3 ft. center  
measurement; scribing visible on mostly healed face.  
32" White Fir snag, N.66°W., 20.8 ft. to face, 21.9 ft. center  
measurement; scribing, extremely fine, on round surface of tree,  
not on a flat face.  
18" White fir, N.34°E., 30.7 ft. center measurement; scribing  
visible.

Accessories added:

64" Fir, N.8°W., 61.3 ft.  
48" Fir stump, S.48°E., 21.1 ft. (Orig.BT).

Bearings and distances are to "W" nails driven into base of reference trees;  
Weyerhaeuser plates on trees.

3/10/78

Glen McChesney for  
Weyerhaeuser Co.  
March 10, 1978  
C.S. 58/8

(Filed 12/80)

36

East 1/4 corner for Sec. 36  
Found - 1964 GLO brass cap.  
Down, windthrown 36" Fir, slid down hill; plate intact, face  
partly healed, bears S.44°E., 20.5 ft. to center of root hole.  
32" Fir; low face healed over; BLM BT plate intact bears S.55°W.,  
51.7 ft. to center of tree measurement.

Accessories added:

40" Fir, N.69°E., 8.3 ft.  
18" Hemlock, S.61°W., 3.8 ft.  
32" Red Cedar stump, bears N.78°W., 50.8 ft.

Trees have "W" nail with Weyerhaeuser plate.

3/10/78

Glen McChesney  
Weyerhaeuser Company  
Oct. 18, 1968  
(Rec'd infor. in  
this office, 6/1981)  
C.S. 58/8

1/4 Corner for Sections 31 and 32.  
(See Renewal #5)  
"M.D. Hale noted a discrepancy in the bearing to the 50" fir BT as being  
N.81°W instead of S.85°W. after determining the corner point by distances  
and noting the bearing to the NE BT as being good. After determining the  
corner point from Hale's called distances and bearings, I concur with his  
findings, except I have N.79°W., instead of N.81°W. to the original 50"  
fir BT." Under all accessories I have driven round "W" nails beside Hale's  
square ones, put new plates on his reference trees (now stumps), changing the  
one to read N.79°W., instead of N.81°W., and have added the one new reference  
A 24" Fir stump, bears N.38°E., 12.5 ft. with "W" anile and plate.  
10/18/68

37

Sec. corner to Sec's.35 & 36 and Sec's. 1 & 2 of T.24R.2. 38

Found - Brass Cap, firmly set, protruding 11" out of (Ren.#14).  
ground, properly marked.

BT's - 20" decayed stump (orig. 18" Fir), and log bears N.53°E., 13.9-ft.  
no face or scribing visible.

33" stump (orig. 30" Fir), with bark removed & metal cover on  
top bears S.29°E., 37.6-ft. (Rec. S.49°E), no scar visible,  
with bark off.

65" stump (orig. 48" Fir), bears S.25°W., 21.1-ft. Stump is  
cut low. No face or scribing visible.

38" blowdown (orig. 30" Fir), with well healed double blaze,  
bears N.28°W., 19.1-ft. to center of root hole.

60" stump (orig. 52" Fir), with scribed "S BT" Ren.#14.  
visible, bears N.13°E., 74.4-ft.

New BO's- Set PK nail in burl on 45" Fir stump (stump has bark off and  
metal cover on top) which bears S.81°E., 20.0-ft.

Gregory E. Quibell  
Deputy, Doug. County  
Surveyors Office  
Debbie Stewart, witness  
Sept. 8, 1981  
C.S. 61 / 27