

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 3 W. R. W. W. M.

KOBE-CHAPMAN CO., EUGENE, ORE. 21881

38

$\frac{1}{4}$ Corner to Sec. 31, T23-3W. & Sec. 6, T24-3W.
Found - I. Post with Brass Cap, 1950.
10" Yew N.64°45'W. 14 lks. 9.2 ft., scribing legible.
10" Yew S.16 $\frac{1}{2}$ ° E. 19 lks. 12.5 ft., scribing legible.
BT's: - 17" Yew N.40°W. 26.1 ft. "W" Nail & Plate.
72" Fir Snag S.42°W. 5.3 ft., "W" Nail & Plate.

39

Sec. Corner to Sections 26 - 27 - 34 - 35.
Corner burned through by slash fire, 1959, *SEE ALSO REN #45*
Found - 8" Cedar S.60°E. 30 lks. stump pushed over by cat., no scribing.
33" Cedar S.85°W. 6 lks., burned out stump(shell) 2W" Nail remained.
36" Cedar N.40°W. 4 lks., burned out stump(shell) no "W" Nail.
No evidence of 6" Maple N.20°E. 54 lks.
Set - $\frac{3}{4}$ " x 38" Gal. Conduit
BT's: - 48" Cedar Stump(Shell), Orig. BT. N.3°W. 4.7 ft. "W" Nail & Plate.
46" Cedar Stump(Shell), Orig. BT. S.63°W. 3.4 ft. "W" Nail & Plate.
24" Cedar Stump S.5°W. 16.0 ft. "W" Nail & Plate.
26" Cedar Stump N.72°W. 28.1 ft., "W" Nail & Plate.

40

$\frac{1}{4}$ Corner to Sec. 34, T23-3W. & Sec. 3, T24-3W.
Found - Orig. Post gone, cruiser's marks.
Orig. 7" Yew N.40°W. 9.9 ft., now leaning, scribe partially visible.
No trace of 6" Dogwood N.75°E. 13.2 ft.
Set - $\frac{3}{4}$ " x 31' Monel Pipe. 1958.
BT's: - 48" Fir S.53°W. 54.7 ft. "W" Nail & Plate.
36" Cedar N.30°E. 49.0 ft. "W" Nail & Plate.
7" Yew (June 1941) N.40°W. 9.9 ft. (Orig. BT) "W" Nail & Plate.
(NOT FOUND - OCT. 1967 C.S. 54/11 V.B.T. DESTROYED BY RECENT LOGGING & ROAD CONST.)

41

Sec. Cor. to Secs. 34 - 35, T23-3W. & Secs. 2 & 3, T24-3W.
Found - Orig. 6" Maple, now 8" Vine Maple, S.46°W. 32.3 ft. Axe marks, no scribing visible.
Orig. 20" Fir N.19°W. 29.0 ft., now Snag, broken top, some scribing on bark.
Orig. 36" Fir N.46°E. 29.7 ft., most scribing visible on bark.
Orig. 36" Fir S. 5°E. 12.5 ft., scribe on bark visible.
Set - $\frac{3}{4}$ " x 35" Iron Rod
BT's: - 42" Fir S.45°W. 36.6 ft. "W" Nail & Plate.
50" Fir N.59°W. 51.0 ft. "W" Nail & Plate.
42" Fir N.46°E. 31.0 ft. "W" " " , Orig. BT.
52" Fir S. 5°E. 10.3 ft. "W" " " , Orig. BT.

June 1958

42

Sec. Cor. to Secs. 33 & 34, T23-3W. & Secs. 3 & 4, T24-3W.
Found - No evidence Post, 1882.
No evidence 36" Spruce S.70°E. 23.10 ft., probably D. Fir.
36" Spruce, 36" D. Fir, snag, rootwad, corner pt of face.
36" D. Fir, now 40" Windfall, scribing on bark visible, N.60°W. 3.3'.
40" D. Fir, now 46" Snag, bark sloughed away, no scribing, N.10°E.,
46.2 ft.
BT's: - 46" Fir, Orig. BT. N.12°E. 17.7 ft. "W" Nail & Plate.
62" Fir N.58°W. 33.9 ft. "W" Nail & Plate.
36" Fir S.39°W. 67.8 ft. "W" " "
36" Fir(1946 Plate) S.17°W. 7.3 ft. (Orig. BT) "W" Nail & Plate.

43

$\frac{1}{4}$ Corner to Sections 27 and 26.
Found - 6" Hemlock, now 15", broken off near ground level by logging,
burnt & no scribing visible but I saw this corner in April, 1956,
when area was felled & bucked timber, & scribing was visible.
Set 1" x 2" Cedar Stake in broken off Hemlock.
60" burned out fir snag stump, possible Orig. BT., S.31°W. 8.0 ft.,
no scribing visible or evident.
60" Fir N.20°E. 25.0 ft. Tree gone, hole in ground.
BT's: - 28" Cedar Stump N.73 $\frac{1}{2}$ °E. 30.8 ft. (Orig. BT) "W" Nail & Plate.
48" Fir Stump N. 3°W. 26.0 ft. " " " "

January 1958

(Nov. 1967 - Since this corner was recorded a $\frac{1}{2}$ " I. Pipe
has been set on E. side of Orig. Corner Stump & 1"x4'
marker pipe. No trees avail. for new BT. "W" stumps
in good condition.) C.S. File No. 54/16.

Weyerhaeuser Co.
1957 - 1963
C. S. File No. 53/107