

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

58

Southeast Corner of Section 36.
Found - $\frac{1}{2}$ " I.P. "Weyerhaeuser" method, See C.S. File No. 53/107.
Orig. 26", now 42" Fir Stump, N.45°W. 8.6 ft., old bark scribe visible in poor condition. Also "W" nail.
40" Fir Stump N. 47°E. 13.7 ft., "W" Nail & Tag. R
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S 3 S 36 R
(Reset I.P. alongside) Office, 1968 T24S W W
New BT: 60" Fir Stump N.47°W. 26.1 ft. mkd. T23S R3W S36 CS BT.
Note - This corner lies on S.E. slope on top of cut bank of old cat road in logged-off area.

59

Closing corner to Sec. 31, T23-2W. & Sec. 6, T24-2W.
Found - $\frac{1}{2}$ " Tubing at corner & $\frac{1}{2}$ " I.P. for marker with Orig. BT's., & "W" method BT, as recorded in Ren. #3, T23-2W., C.S. 53/106.
Orig. 16", now 24" Cedar Stump, 5' high, N.10°E. 27.7 ft., scribing visible on nearly healed blaze.
Orig. 60" Fir, now 64" Fir Stump, 2 ft. high, S.57°E. 25.1 ft., top of blaze visible on top of stump.
26" Hemlock Stump S. 50° W. 18.1 ft., "W" Nail & Tag. R
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S 3 C S 31 R
(Reset $\frac{1}{2}$ " Tube alongside) Office, 1968 T24S W C S 6 W
New BT: 9" Cedar Snag N.44°E. 28.9 ft. mkd. T23S R2W S31 CC CS BT.
Note - This corner lies on E. side of spur, ridge sloping south about 50 ft. east of top.

60

Closing Corner to Sec. 1, T24-3W. & Sec. 6, T24-2W.
Found - $\frac{1}{2}$ " I.P. at corner & "W" BT's. as Recorded in Ren. #39, T24-3W.
Orig. 18", now 20" Yew, alive, S.30°W. 39.0 ft., scribe marks visible on old blaze. "Rescribe "T24S R3W S1 CC CS BT".
Orig. 60" Fir, now 62" Fir Stump, slightly out of position, S.70°E 37.0 ft., shows good scar. No trace Orig. BT. to N.W.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R C.C. R
(Reset I.P. alongside) Office, 1968 T24S 3W S 1 S 6 2W
New BT: 14" Yew S.50°E. 54.8 ft. mkd. T24S R2W S6 CC CS BT.
Note - All "W" BT/s., now stumps. No other trees suitable for BT's. This corner lies on bench sloping S.W. in logged-off area.

4/1/68

61

East 1/4 Corner Section 24 T23-4.
No Monument Found.
Found : A 54" Fir stump with sign that says corner bears S 28° W. 32.4 ft. 42" Fir in NW quadrant gone.
Set : Spike nail with L.S. cap in log for 1/4 corner (S 28°W, 32.4 ft from 54" B.T.).
New BT's : 3" D. fir bears S.70°W., 2.7 ft. with "X" scribed and L.S. washer.
2" D. fir bears S. 43°E., 4.1 ft. with "X" scribe and L.S. washer.

4/87

62

1/4 Corner for Sections 28 & 29
Found - 1/2" x 34" galv. iron pipe. see ren. #8
30" Cedar stump, N.75°W., 43.6 ft. to "W" nail
39" Hemlock stump, S.70°E., 65.5 ft. to "W" nail
BLM tag, 54" x 30 ft. Fir snag, N.10°E., 60 ft. slope dist. to corner.
Corner Set - 1 1/2" x 30" iron pipe with 2 1/2" cap dated 1998
New Accessories -
14" Fir, N.66°E., 23.7 ft. to "W" nail - scribed "1/4 S28"
18" Fir, S.33°E., 5.7 ft. to "W" nail - scribed "1/4 S28"
17" Fir, S.47 1/2°W., 15.8 ft. to "W" nail - scribed "1/4 S29"
20" Fir, N.43 1/2°W., 29.1 ft. to "W" nail - scribed "1/4 S29"

Note - Corner lies in slight depression on easterly side of wide ridge. Road switchback and landing bears N.65°W about 300 ft. distant.

John M. Powell
Frank Jones & W. Penley
April, 1968
C. S. File No. 54/27

Donald Branch
L.S. 1137
For: U.S. Bank
M 104 - 1
C.S. 63/48

David Wellman
Jan. 8, 1998
C.S. File 65/20-3