

Douglas County Surveyor's Record of
Government Corners Renewed

23 T. S. 4 R. W. W. M.

135 26-A
1/4 Corner between sections 20 & 21.
Set Lot Marker from 2 old BTs.: 18 inch Fir Stump S 25°E 16.5 feet.
36 inch Fir S 62°W 60.0 feet. *REN #4*

27
Rescribe Bearing Tree for Standard Corner $\frac{36}{31}$ T22S
RSW $\frac{17}{6}$ *R4W* T23 S
Found - Original 14" now 33" W. Oak N.80°W. 1091.0 ft. This Bearing Tree opened & rescribed about 20 years ago, probably by Theil. I open inside shell & find good scribing (negative). I reblaze & rescribe this Bearing Tree T22S R5W S36 CS BT. *40*
Other Bearing Trees for this Corner gone.
I also find 1 1/2" Iron pipe 4.4 ft. North of temp. Corner. (See Sketch in file)
Note: This Corner not renewed, because the distance to Bearing Tree is too great to fix Corner Location. *SEE LATER RENEWAL - COR. NO. 40*

James W. Byron
For Office Record
Nov. 20, 1957
C. S. File No. 49/412

28
1/4 Section Corner to Sections 6 & 7.
Found - Mound of stone at fence Corner. BT. scribed by B.B.I., 1940. *ALSO SEE #11*
Alive & good condition, Shows good scar. I do not open, Checks bearing & distance. Now 15" R. Fir. *#17*
Also find 2" x 1/2" x 12" Iron at Corner.
Set 3/8" x 3 1/2" x 18" Iron with T on bottom at Corner.
New BT: 18" R. Fir bears S35°E. 29.8 ft. scribed 1/4 S7 CS BT.

James W. Byron
M. Godfrey
S. Blouw
Dec. 4, 1957
C. S. File #49/42

Also see Thom's Book 28 FEB
29
Section Corner to Sections 5 & 6, T23S, R4W, & Secs. 31 & 32, T22S, R4W.
Found - Both BTs. as renewed by Theil, 1926-1931, See Book ? Page 45.
BTs. alive but scribing about gone. Corner 2' North of East West Fence.
Find base of Old Cedar Stake 12" under at Corner.
BTs. check bearings & distances. No Original BTs. found.
Set Brass Cap at Corner marked $\frac{S31}{S6}$ | $\frac{S32}{S5}$ T22S R4W County Surveyor's Office, 1958.
New BTs: 12" Maple bears N.72°W. 24.8 ft. scribed T22S R4W S31 CS BT.
32" W. O. bears N.83°E. 43.8 ft. scribed T22S R4W S32 CS BT.
24" W. O. bears S.59°E. 71.6 ft. scribed T23S R4W S 5 CS BT.
16" Ash bears South 31.7 ft., rescribed this BT. T23S R4W S6CS BT.

James W. Byron, Dep. Co. Surveyor
M. Godfrey
S. Blouw
Jan. 8, 1958
C. S. File No. 49/54

30
Section Corner to Sections 8, 9, 16, & 17.
Found - Scribed Stake at corner which is also fence corner. *72*
REN #6 All of Boyer's BTs. The N. E. & S. E. now stumps only. N.W. & S.W. BTs. alive, bark scribed. No trace of original BTs. found at this time.
Set Brass Cap alongside scribed stake marked $\frac{S8}{S17}$ | $\frac{S9}{S16}$ T23S R4W County Surveyor's Office, 1958
New BTs.: 10" Cedar bears S.67°E. 111.4 ft. scribed S16 T23S R4W CS BT.
8" R. Fir bears N.76°E. 40.7 ft. scribed S9 T23S R4W CS BT.

James W. Byron, Dep. Co. Surveyor
M. Godfrey
S. Blouw
Jan. 13, 1957
C. S. File No. 49/42

FDPK BY R. Hoffine 4/1998 M128-60
31
1/4 Section Corner to Sections 8 and 9.
Found - Rotted scribed stake & 5" x 8" x 14" Rock with chisled + at corner.
Both Boyer's BTs., now stumps only (with scribing) *REN #8*
BTs. check bearings & distances.
Note - Corner at 4 way fence int. & 3' above small stream.
Set Brass Cap at corner marked $\frac{1}{4}$ S8/S9 T23S R4W County Surveyor's Office, 1958.
New BTs.: 6" R. Fir bears N.23 1/2°E. 41.4 ft. scribed 1/4 S9 CS BT.
10" R. Fir bears N.44 1/2°W. 18.8 ft. scribed 1/4 S8 CS BT.

32
Section Corner to Sections 4, 5, 8, & 9.
Found - 3 of Eppstein's trees alive & in good condition, all showing good scars, as follows: W. Oak, now 22" diam. S.10°E. 89.4 ft. *REN #1*
W. Oak, now 19" diam. S.32°W. (instead of S.23°W.) 53.4 ft.
D. Fir (instead of W. Fir) now 24" diam. N.56°W. 33.6 ft. - chopped out exposing scribe "BT".
Found possible original BTs. as follows:
Rotten Fir Stump, about 48" diam. S.50°W. 46 ft. *115*
Rotten Laurel stump, about 24" diam, N.16°E, 60 ft.
Live & standing Laurel Tree (rotted out inside), now 36" diam. N.35°W. 72.6 ft. No scribing found on any of these.
For Corner set Iron Pipe with (continued next page)