

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 4W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

$\frac{1}{4}$  Section Corner to Sections 9 and 10.

Found - 24" Fir Stump S. 67° E. 25.4 ft. *REN. #9*

10" Fir S. 77° W. 40.4 ft., down. *73*

Set - 1" x 1" x 36" T. Iron

67

$\frac{1}{4}$  Section Corner to Sections 4 and 9.

Found - 1 $\frac{1}{2}$ " Iron Pipe.

2 D. Fir Bearing Trees (not W. Fir.) *#174*

Set - 1" x 1" x 36" T. Iron in pipe. *SEE REN. #5*

Rescribed same Trees: 16" Fir S. 60° W. 13.3 ft.

14" Fir N. 3° W. 20.2 ft.

68

$\frac{1}{4}$  Corner to Sec. 31, T23-4S. & Sec. 6, T24-4W. *5/81 Fwd. O.K. R. Quimby M 79-77*

Found - Rotten Oak Log S. 40° E. 55.4 ft., picked rotten wood apart and found good reverse scribing "S".

Small depression in ground, possible stump hole, N. 5° E. 42.9 ft.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R4W  $\frac{1}{4}$  S31  
Office, 1963 T24SR4W S 6

New BT's: 11" D. Fir N. 29° W. 17.2 ft. Mkd:  $\frac{1}{4}$  S31 CS BT.

D. Fir S. 11° W. 22.4 ft. Mkd:  $\frac{1}{4}$  S6 CS BT.

Corner lies 8 ft. south of E. & W. fence line, near N.W. corner of patch of 2nd. growth fir timber.

69

Corner to Sections 32 and 33 only, T23-4W.

At a point 271 lks. East of the Closing Corner of Sections 4 & 5, T24-4W.

Found - 65" Fir Stump S. 86° E. 29.7 ft., old axe marks on bark appear to be where Thiel destroyed bark scribing, see notes, on lower scar what appears to be portion of scribe mk. "B", is visible.

50" Fir Stump N. 70° E. 27.7 ft., no marks found.

60" Fir Stump N. 43° W. 25.1 ft., one single axe mark found in wood approximately 110 years old.

No trace of S.W. BT. I believe these trees to have been larger at time of Orig. survey than field notes indicate & that they were bark scribed. Did not find Rock set by Thiel, appears to be in old slide area.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R4W S32/S33  
Office, 1963

New BT's: 52" D. Fir N. 75° W. 65.0 ft. Mkd: T23S R4W S32 CS BT.

12" R. Cedar S. 73° E. 38.0 ft. Mkd: T23S R4W S32 S33 CS BT.

No trees available to N.E. Corner lies on very steep North face of mountain.

70

Closing Corner to Sections 5 and 4, T24-4W.

Found - 30" Maple S. 40° E. 23.8 ft., scribing visible on old face, opened several years ago. Mail trunk of tree broken off 5 ft. above gr.

Rotten Maple Stump S. 72° W. 27.7 ft., broken trunk of tree lying alongside, axe marks visible, but no scribing found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T24SR4W CC S 5/S 4  
Office, 1963

New BT's: 16" W. Fir S. 1° E. 55.6 ft. Mkd: T24S R4W CC S 4 CS BT.

11" I. Cedar S. 77 $\frac{1}{2}$ ° W. 86.4 ft. Mkd: T24SR4W CC S5 CS BT.

Corner lies on a bench just below steep north face of mountain.

71

Section Corner to Sections 8 - 9 - 16 - 17.

Found - County Surveyor's Brass Cap set in 1958. *REN. NO. 30*

Three Bearing Trees standing, alive & in good conditions:

10" Cedar S. 67° E. 111.4 ft.

8" D. Fir N. 76° E. 40.7 ft.

15" D. Fir N. 20° W. 50.8 ft.

S.W. Tree is uprooted & down, recent.

One New BT: 13" D. Fir S. 76° W. 22.5 ft. Mkd: T23SR4W S17 CS BT.

72

Wilford N. Haines  
For Jim S. Whipple  
December 1962  
Map File M 24 - 42

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy and Mike Stone  
February 1963  
C. S. File No. 53/9