

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy and Mike Stone  
February and March, 1963  
C. S. File No. 53/9

1/4 Corner to Sections 9 and 10.

73

Found - Haines "T" Iron Cap, at corner. - *Ren. No. 67*

16" D. Fir, not white Fir, S. 77° W. 40.4 ft, recently uprooted & down.

30" D. Fir Stump S. 67° E. 25.4 ft., found portion of scribe mark.

Rotten Remnants of Fir Stumps to N.E. & S.W., No marks remaining.

DID NOT SET NEW MONUMENT, BRASS CAP.

New BT's: 14" D. Fir S. 68° W. 90.7 ft. Mkd: 1/4 S9 CS BT.

6" D. Fir S. 59° E. 59.2 ft. Mkd: 1/4 S10 CS BT.

Corner lies in recently bulldozed fire trail. A fence corner (fences, East & South) bears South 125 ft.

1/4 Corner to Sections 9 and 16.

74

This is a re-renewal of Boyer's renewal of 1/4 corner. - *Ren. No. 7*

Found - Old scribed Wooden Stake in fence corner "1/4 S9" on N. side, other sides burned.

36" Fir Stump bears S. 71° E. 44.0 ft. Good scribing visible "BT".

23" Fir Snag N. 20° E. 42.8 ft., not N. 43° E, good scribing visible.

Scribing face definitely faces fence corner & not direction as called for in notes, scribing appears same age as scribing on stump to S. E.

A depression in ground, possible stump hole, bears N. 15° E. 43 lks. (Fits call for Orig. N.E. BT.)

Set - Brass Cap in fence corner Mkd: County Surveyor's T23S R4W 1/4 S9  
Office, 1963 S16

No live trees within 500 feet of Corner.

*SEE C.S. 41/5 FOR  
THAT CORNER REPORT  
(Info. Above 3/10)  
M.E.*

Section Corner to Sections 9 - 10 - 15 - 16.

75

Found - 42" Fir Stump N. 45° E. 42.9 ft. Cut open & fd. good scribing "BT".

Hollow Maple S. 24° W. 19.1 ft., portion of old rotten face inside with good scribing visible on old face.

No trace of N.W. or S.E. trees found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R4W S9 | S10  
Office, 1963 S16 | S15

New BT's: 12" I. Cedar N. 10° E. 111.7 ft. Mkd: T23S R4W S10 CS BT.

17" I. Cedar N. 25° W. 92.7 ft. Mkd: T23S R4W S9 CS BT.

12" W. Fir S. 52° W. 44.4 ft. Mkd: T23S R4W S16 CS BT.

No trees available to S. E.

Corner is in fence corner, fences North, South & West from corner. Scribed Stake is 1 ft. South.

*SEE C.S. 41/5  
FOR THAT CORNER  
REPORT  
(Info. Above 3/10)  
M.E.*

Corner to Sections 14 - 15 - 22 - 23.

76

Found - Old uprooted Fir, now 24", N. 21° E. 9.9 ft. Fragments of scribing visible on partly rotted & charred face. (previously opened) Ring County proves it is an Original BT.

No trace of any other Orig. BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R7W S15 | S14  
Office, 1963 S22 | S23

New BT's: 5" D. Fir S. 80° W. 5.4 ft. Mkd: S22 CS BT.

6" D. Fir N. 46° W. 12.4 ft. Mkd: S15 CS BT.

9" D. Fir N. 55° E. 21.6 ft. Mkd: T23S R4W S14 CS BT.

6" D. Fir S. 63° E. 10.4 ft. Mkd: S23 CS BT.

A "T" iron, no cap, bears S. 52° W. 2.9 feet. (F.B. H-237) FOR POSSIBLE SOURCE 9/90 M.E.  
Corner lies on steep north slope, approx. 100 ft. S. of bottom of slope.

*Fd. 4/90  
C.S. 63/127*

Section Corner to Sections 28 - 29 - 32 - 33.

77

Found - 42" Cedar S. 28° E. 240.7 ft., scribing visible in previously opened

scar "3 R4W BT". Tree alive & in good condition. # 200

30" W. Oak N. 9° E. 90.0 ft., 2 good scars visible, did not open.

RE Did not find Iron bar set by Eppstein. - *Sec Ren. # 4*

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R4W S29 | S28  
Office, 1963 S32 | S33

New BT: 13" Ash S. 28° W. 18.3 ft. Mkd: T23S R4W S32 CS BT.

No trees available to N.W.

Corner falls in fence corner, fences North, South and East from corner.

*Fd. OK 4/5/76 - G.M. Chesney - WEYERHAEUSER Co. C.S. 58/18*