

Douglas County Surveyor's Record of
Government Corners Renewed

T 23 T. S. R 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Frank O. Williams
by Glen McChesney
For: Weyerhaeuser
Company
April 5, 1976
C.S. 58/8

North 1/4 Corner Section 33
Found - 18" now 42" Fir, scribing visible, bears N. 15° E., 33.0 ft., Orig.
1855 survey. Scribing in fire charred face # 203
No trace of post or SE BT.
Iron bar set by Thiel and Haines T Iron alongside. Ren. #78
Iron bar and NE BT is supported by G. Langdons affidavit in
CS File No. 53/9.
New BT - 10" Madrone bears West, 21.0 ft. with "W" nail and plate.
Corner point is about 1 ft. East of fence corner, fenced to West & to South.
4/5/76

156

1/4 Corner for Secs. 10 and 15.

Set - Brass cap.
BT's - 18" D. Fir bears S. 52° W., 20.6 ft. scribed 1/4 S15 BT.
9" D. Fir bears N. 31° W., 23.0 ft. scribed 1/4 S10 BT.
1/2" I.P. bears N. 74° 30' W., 3.0 ft.

157

Glenn Baughman
For: Sun Studs, Inc.
March 13, 1978
M 65 - 71

Section corner for Secs. 3, 2, 10 and 11.

Set - Brass cap.
Bearing Objects:
5/8" I.R. on Northerly R/W BLM Road No. 23-4-10.1 bears S. 79° W., 96.5'
1/2" I.R. on Northerly R/W BLM Road No. 23-4-10.1 bears S. 86° 45' E.,
218.6 ft.

158

1/4 Corner for Secs. 3 and 2.

Found - A 1" x 36" T. Iron with a brass washer attached. Washer marked
"Wilford N Haines" 239 Survey Point Drain, Oregon. Top of T-Iron
is 3" above surface of ground and bent. Ren. #55
A 16" D. Fir now a 20" stump with scribing visible "S BT" bears
S. 88° W., 74.4 ft. Ren. #55

159

Gary L. Langlitz
S.J. Flaue
F.C. Silagy
Doug. Co. Surveyors
Office
April 11, 1978
C.S. 59/46

Rotted remains of a D. Fir bears S. 10° E., 54.4 ft.. Ren. #55
An 8" now 10" W. Oak bears S. 47 1/2° W., 105.3 ft. with well
healed single blaze. Ren. #108.
A power pole (No. 4-183) bears S. 8° W., 25.7 ft. Ren. #108
Set - Flush with ground at present location of T-Iron set a 1" x 30"
I.P. with a brass cap attached marked: "Douglas Co. Surveyor"
T-Iron is placed alongside brass cap.

Accessories:
A 2" Iron pipe at the initial point of Sun
Subdivision bears East 13.5 ft. from brass cap.

Note: Corner is 29 ft. East of centerline of Scotts Valley Rd. #8;
13 1/2 ft. West of fence corner with fences running North and
South, and East; 1 ft. West of iron fence post with survey marker
witness sign attached.

Center 1/4 Corner for Section 9.

Found - A 4" x 4" squared cedar post is stapled in fence wire, with
scribing "Cen Sec 9". Ren. #12

A 14" now 16" Cedar stump has been pushedover, orig. position
approx. bears S. 34° W., 14 ft.

A 6" now 18" Cedar bears S. 83 1/2° E., 23.0 ft. with a chopped open
blaze and bark scribing "Cen".

Set - A 1" x 36" I.P. with a brass cap set 4" above ground and marked:
"Douglas County Surveyor" T23S R4W
1978 C1/4
S 9

New BT - A 6" D. Fir bears N. 5° E., 9.8 ft., I double blaze and mark
"C 1/4 S9 T23S R4W CS BT".

Corner is on a south slope and 1.0 ft. south of a fence corner west and north,
SE corner of a clearcut unit.

R. B. Kimberling
P. L. Earle
Dog. Co. Surveyor
Office
May 24, 1978
C.S. 60/11

1-79