

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97881

Milo E. Godfrey
& Crew
Nov. 1964
C. S. File
No. 49/42

Section Corner to Sections 16 - 17 - 20 - 21. 73
Found - "T" Iron with Cap at Corner. (See Ren. #27 & #32)
Accessories, per Ren. #32, in 1959, except 40" Fir S.55°W.
2.0 ft. has blown down. Corner monument not disturbed.
Fir Shag S.82½°E. 13.2 ft., scribing still plain.
7" D.Fir N.61½°E. 37.9 ft., very good scar. Tree in good condition.
8" D.Fir N.84½°W. 89.6 ft., " " " " "
8" W.Oak S.12°E. 22.2 ft., scribing still visible, Tree in good condtn.
New BT: 13" Bl. Oak S.84°W. 26.6 ft. Mkd: T23S R5W S20 CS BT.
9/69 - Fo. O.K. - 54/16 Nov. 27, 1964

Bruce R. Rogers, Deputy
Wm. Stoffel & Mike Stone
February 1965
C. S. File No. 53/101

Section Corner

T23S	T23S	
R6W	R5W	SC
S 1	S 6	1943

74
Found - GLO Brass Cap at Corner as marked above:
9" Fir, now stump, S.29°E. 68.9 ft. - No trace of S. W. Tree.
New BT's: 14" W.Fir S.84°E. 93.0 ft. Mkd: T23S R5W S6 CS BT.
7" D.Fir S.70°W. 34.4 ft. Mkd: T23S R6W S1 CS BT.
Note - Corner is at E - W - S Fence Corner.

Section Corner

T 22 S R 6 W	S 36 / S 31	
S 1	S 1	
T 23 S R 6 W	1943	

75
Found - GLO Brass Cap at Corner as marked above:
20" Fir, now stump, N.56½°W. 156.4 ft., scribing visible.
Note - Corner is 2 ft. south of E. - W. Fence.
New BT's: - 7" D.Fir N. 4° W. 26.0 ft. mkd; CC T22S R6W S36 CS BT.
6" Madrone N.62°E. 22.5 ft. Mkd: CC T22S R5W S31 CS BT.
February 1965

Section Closing Corner for Sections 32 & 33 only, T22-5W. 76
Found - 12" Fir, now 43", N.23°E. 8.0 ft., scribing visible "BT".
No trace of N. W. Tree. T 22 S
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965 S 32 | S 33 R5W
C C
New BT: 8" Fir N.29°W. 45.5 ft. Mkd: T22S R5W CC S32 BT.
Rescribed - 43" Fir CC T22S R5W S33 CS BT. Feb. 11, 1965

Sec. Cor. to Secs. 12 & 13, T23-5W. & Secs. 7 & 18, T23-4W. 77
Found - ¾" Iron Rod attached to fence corner, course S. & E.
BT's. as recorded in Ren. #36, (723-4W) now snags. Ren. #30 T23-5
All Orig. BT's., now stumps or turned out.
New BT's: 7" W.Fir N.33°W. 42.3 ft. Mkd: S12 CS BT.
7" W.Fir S.24°W. 51.2 ft. Mkd: S13 CS BT.
8" D.Fir S.22°E. 102.5 ft. Mkd: T23S R4W S18 CS BT.
No BT. available to N. E.

Vernon "Ray" Tracy
Mike Stone & Jerry Layne
October 1965
C. S. File No. 54/16

¼ Corner to Sec. 13, T23-5 and Sec. 18, T23-4. 78
Found - Brass Cap at Corner, as recorded Ren. #29, pushed out of place.
Original 50" Fir Snag still in place.
16" Cedar S. 13½°E. 99.0 ft., now snag 10.0 ft. high, scribing visible.
14" D.Fir N.35°W. 12.0 ft., alive, in fence corner, face
almost healed over, scribed high because of fence wire.
Reset Brass Cap and marked one new Bearing Tree:
9" D.Fir N.18°E. 31.9 ft. Mkd: ¼ S18 CS BT.

Sec. Cor. to Secs. 13 & 24, T23-5 and Sec. Cor. 18 & 19, T23-4. 79
Found - Brass Cap & BT's. as recorded Ren. #70. Corner lies
in fence corner, course N. - S. - W.
40" D.Fir N.60½°W. 46.2 ft., bark scribe in good condition,
metal disc. mkd. "RE 2741" nailed to tree.
33" D.Fir S.7½°E. 199.3 ft., scribe visible on pitched face.
22" I.Cedar N.61°E. 223.6 ft., scribe visible.
S.W. BT. dead. Other trees alive & in good condition.
New BT: 30" D.Fir S.17°W. 181.0 ft. Mkd: T23S R5W S24 CS BT.