

Douglas County Surveyor's Record of  
Government Corners Renewed

T 23 T. S. R 5 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

BOOK BY Daniel Baker  
For: Weyerhaeuser 12/93 103  
M118-43

Section corner for Secs. 6 and 7; and 1 and 12 of T23-6  
Found - 1943 GLO brass cap on 2" pipe (O.D.) 7" above ground properly mkd.  
A 24" Fir stump bears S.5°E., (Rec. S.10°E.) 21.1 ft. Blazed & mkd. "R5W T23S S7".  
A 16" Fir stump bears S.45°W., 42.6 ft. (Rec. 44.9 ft.) blazed & mkd. "T23S S21 BT".  
Remains of Fir stump, center of root hole bears N.5°W., 14.5 ft.  
A D. Fir windfall, 41", bears N.49°E., approx. 32.3 ft. to center of root hole, single blaze & mkd. "T23S R5W S6 BT".  
A D. Fir, 36", bears S.21°E.- 31.7 ft. with well healed blaze.  
A 28" Cedar, bears N.53 1/2°W., (Rec. N.55°W.) 47.5 ft. with well healed blaze facing N.70°E.  
New BT's - A 11" Madrone, bears S.68°W., 19.4 ft. double blazed & mkd. "T23S R6W S12 CS BT".  
A 11" D. Fir bears N.56°E., 51.0 ft. double blazed & mkd. "T23S R5W S6 CS BT"

SEE CS 61/5  
FOR THEIR  
1934 REPORT

FD. COR 4/90  
C.S. 63/127

Larry E. Monrean, Doug. Co. Surveyors Office  
Roderick B. Kimberling  
April 12, 1977  
C.S. 59/31

4/12/77

104

1/4 Corner to Sec. 6 and Sec. 1 of T23-6  
Found - 1943 GLO brass cap on 1" pipe (O.D.) 13" above ground properly mkd.  
A Fir stump, decayed, orig. 36" now indeterminate, bears S.48°E., 37.6 ft. No visible scribing.  
A Fir stump, badly decayed, 24" bears S.35°W., 32.9 ft. with open blaze mkd. "1/4 S" (Rec. 31.7 ft.).  
A Fir snag, 20 ft. high, 25" bears N.84°E., 19.1 ft. with well healed blaze. (Rec. 19.8 ft.)  
A Fir stump, 29" bears S.76 1/2°W., 46.2 ft. One open blaze, scribing chopped out.  
New BT-s- A Black Oak, 18" bears S.69°W., 33.3 ft. blazed & mkd. 1/4 S1 CS BT.  
A D. Fir, 8" bears S.60 1/2°E., 21.1 ft. double blazed and marked 1/4 S6 CS BT.  
Note - Corner lies approx. 36 feet north of old road.

4/12/77

105

1/4 Corner for Secs. 6 and 7 only.  
Found - Rotten remains of a scribed wood post, approx. 3" x 3" (source unknown) (PROBABLY THEIR - SEE C.S. 61/5)  
A 1" axle with gear, flush in ground (source unknown).  
3/4" I.P. found by Hayden in 1952 (CS 41/65) not found. Ren. #55  
A 1" I.P. extending 12" above ground with brass cap attached marked County Surveyor's Office T23S R5W 1/4 S6 S7 1960. Ren. #53  
An orig. 44" Fir now a 66" stump with scribing "BT" visible on previously opened blaze bears S.54 3/4°W., 13.9 ft.  
Orig. NE BT, an 18" Fir not found.  
A 22" G. Fir (CS 41/65) alive with well healed double blaze bears S.45°E., 25.9 ft. (Rec. 12" Hemlock S.40°E., 25.9 ft.)  
A 10" now 17" D. Fir (CS 41/65) alive with well healed double blaze bears N.17°E., 67.1 ft. (Rec. N.21°E., 67.1 ft.).  
A 13" W. Fir, now an 18" snag, with well healed blazes bears N.88°W., 18.3 ft. (Ren. #53).  
Condition report only, no new monuments or accessories set.

Jan 78

BOOK BY Daniel Baker  
For: Weyerhaeuser  
12/93 M118-43

1/14/1980 ALSO  
SEE CS 61/5  
d.h.

Gary L. Langlitz  
F.C. Silagy  
Doug. Co. Surveyor  
Office  
March 1978  
C.S. 59/46

3/28/78

106

Southwest Corner DLC #40, T.23-5  
Found - Large rock with 5/8" I. Rod alongside.  
At SW corner, I scribed:  
26" D. Fir "SWC DLC 40 BT" bears N.42°W., 113.7 ft. #108  
32" D. Fir "SWC DLC 40 BT" bears N.74°E., 111.4 ft.  
Corner lies at SWC of Yoncalla Cemetery and on North fenceline of a large cleared pasture to the South.

12/11/75

107

1-79  
1/4 Corner for Secs. 29 and 30  
Set - 1" Iron pipe with brass cap marked T23S R5W 1/4 S30 S29 RLS #958 1979.  
Found - Stone per M 72 - 17  
BT's - 12" Madrone scribed "1/4 S29 BT bears N.75°E., 57.0 ft.  
6" Madrone scribed 1/4 S30 BT bears N.16°30'W., 53.4 ft.

3/79

Russell Pinard  
LS #958  
For: Wooley Lumber  
Co M 76 - 48