

Douglas County Surveyor's Record of
Government Corners Renewed

T 23

T. S.

R 5

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

Ken Hoffine
L.S. 2291
For: Lone Rock
Timber Co.
June 1990
C.S. 63/104

131

1/4 Corner for Section 19; and Sec. 24 of T.23-6

Found - Corner is a brass cap 0.5 ft. above ground. Corner has been bent nearly 40° from plumb in a west direction. Ren. #69
36" fir stump bears N.70°W., 95.8 ft. scribing visible. (1943)
1943 40" SE bearing tree is a blowdown badly decayed tree.

New BTs - Put Lone Rock Timber location tag on a 11" D.F. bearing S.25°W., 6.0 ft.
Put Lone Rock Timber location tag on a 8" D.F. bearing S.22°E., 9.5 ft.

Painted face and wrote BT on tree trunk of BTs with fluorescent orange paint. Corner lies on steep west slope approx 2½ chains west of gravel road, 15-20 year old timber west and a clearcut to the east.

6/90

132

Section Corner for secs. 11, 12, 14 and 13

Found - 1/2" iron rod protruding 18" above a 3 ft. x 2 ft. high mound of stone. Ren. #8

16" now 14" dia. 1½ ft. high rotted D. fir stump, no blazes or scribing visible, is found near record position (S.49°W., 81.8 ft) Possible orig. BT. (BT is approx 45 ft. below corner, near toe of bluff)

No other original BTs found.

16" now 26" dia. D. fir with a fully healed double blaze, bears N.19°W., 46.9 ft. (agrees w/rec.) Ren. No. 8

6" now 10" dia. double trunked madrone with a brass washer mkd. "RE 2741" and possible bark scribing found on southwest trunk bears N.47½°E., 49.5 ft. (Rec. N.47½°E., 47.8 ft. dist. to washer) Ren. No. 8

16" now 26" dia. D. fir with a fully healed double blaze, bears S.60½°E., 30.6 ft. (Rec. S.60½°E., 28.6 ft. dist. a possible face measurement.)

SW madrone from Ren. No. 8 is gone.

A brass cap/iron pipe was not set, ground is too rocky to get a solidly set iron pipe.

New BT - 3" W. oak double blaze and scribed "X BT" bears S.24°W., 5.4 ft. Corner lies at top of rock bluff 12 ft. east of drop off and 10 ft. west of a northerly and easterly running fence corner.

~~BOOK~~ 9/93 M 119-5

12/6/90

133

Southeast corner, DLC #43

Found - A 2½" DCSO brass cap on 1¼" O.D. iron pipe protruding 15" above ground. Ren. #90

A stone is found 0.5 ft. north of BC/IP, its top measures 4" x 6", protruding 2" above ground. No marks are visible. We did not disturb stone. (source unknown)

24" now 24" dia. 3 ft. high D. fir stump with an unhealed single blaze scribing visible "SE DLC 43 CS BT", bears S.45°W., 5.0 ft. (agrees w/rec) Ren. No. 90

17" now 17" dia. 5½ ft. high cedar with scribing visible on an open double blaze "SE DLC 43 CS BT" bears S.24°E., 17.2 ft. (agrees w/rec.) Ren. No. 90

No original BTs found.

New BTs - 4" dia. cedar double blazed and scribed "X BT" bears N.40°W., 50.1 ft.

14" dia. W. fir double blazed and scribed "SE DLC 43 CS BT" bears N.61°E., 42.8 ft.

7" dia. W. fir double blazed and scribed "SE DLC 43 CS BT" bears N.15°W., 74.1 ft.

5" dia. cedar double blazed and scribed "SE DLC 43 CS BT" bears S.29°W., 7.2 ft.

Corner lies in an east-west fence line, remnants of a northerly running fence are found north of corner.

12/6/90

Douglas County Surveyors Office
Randall Smith, Deputy
Stephen Flause - Terrie Fransson
December 6, 1990
C.S. 64/11