

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 6 W. R. W. W. M.

KOHL-CHAPMAN CO., EUGENE, ORE. 97601

37

1/4 Corner to Sections 8 and 9.
Found - G. L. O. Brass Cap and following trees: *See also Ren. #24*
12" Chinquapin S.70°E. 43 lks. is gone
10" Fir S.84°W. 89 lks., Fire or bug killed. *(Rec. S.48°W) R.R. 7/85*
New BT's: 16" Fir S. 4°E. 31.0 ft.
10" Fir N.87°W. 42.7 ft.

38

Section Corner to Sections 6 and 5 only. *(see also Ren. #12)*
Found - Brass Cap set by G.L.O., pulled out - Set back in same hole.
Orig. Fir B.T., now 60 ft. Stump bears S.25°E. ~~41~~ 53 ft. to *face*.
New BT's. by G.L.O.: 16" Hemlock S.29°E. 53.3 ft. (not 47 lks.)
10" Hemlock S.31°W. 47 lks. (not 79 lks.)
(This tree is down)

39

Closing Corner for Sections 31 and 32, T22-6W.
Found - My Corner T Iron with G.L.O. Brass Cap alongside in
a pile of Rocks.
18" Fir B.T. N.36 1/2°W. 45.4 ft. *NO. 56*
24" Fir Stump scribed CC S32 B.T. N.20°E. 48.1 ft.

40

1/4 Corner to Sections 34 and 35.
Found - Gov't. Brass Cap set in 1957 out of ground & lying against
Fir Stump alongside of Corner.
51" D.Fir S.40°E. 74.0 ft. Mkd. by Co.Surv., Jan.1962. Scribing
still visible, tree alive & standing. *Ren. #33*
8" W.Fir N.15°W. 96.0 ft. Mkd. by Co/Surv., Jan.1962. Scribing
still visible, Tree still standing by badly burned & nearly dead.
10" Fir Snag S.72 1/2°W. 79.9 ft. showing blaze & BT. tag.
The Fir Snag marked in 1957 to the S.E. is now gone.
RESET BRASS CAP in Orig. position.
New BT: 10" Red Cedar N.60 1/2°W. 90.2 ft. Mkd: 1/4 S34 CS BT.
Corner is in East edge of Fire Trail.

41

Corner to Sections 26 - 27 - 34 - 35.
Found - G.L.O. Brass Cap & Haines' "T" Iron at Corner. *#78*
29" Fir N.47 1/4°W. 208.6 ft., scribing visible, tree alive, in good cond.
25" Maple N.87°E. 141.9 ft., scribing visible, tree alive & good cond.
46" Cedar S.34 3/4°W. 91.1 ft. Tree standing but dead, marks all burned off.
30" Cedar S.50°E. 32.3 ft., uprooted & down, marks all burned off.
Part of old Maple Stub S.80°E. 10.6 ft., still standing but dead
& burned, no markings left.
New BT's: 34" Maple S.89°W. 128.8 ft. Mkd: T23S R6W S34 CS BT.
34" R. Cedar (top broken out) S.30°E. 92.3 ft. Mkd:
"T23S R6W S35 CS BT".
FO. OK 1/8/75 - GARY L. SURVEYOR'S OFFICE C.S. 57/17

42

1/4 Corner to Sections 26 and 25.
Found - Iron Pipe with Brass Cap, but cap burned & melted so badly it
is impossible to read it. Old Fir East 50.8 ft., tree uprooted,
dead & badly burned. No markings left.
No trace of N.W. BT., location falls in landing at end of logging road.
Alongside Corner Post set aluminum Post 3 1/2 ft. high.
New BT's: 7" D.Fir N.11°E. 50.0 ft. Mkd: 1/4 S25 CS BT.
13" D.Fir S.42 1/2°W. 86.0 ft. Mkd: 1/4 S26 CS BT.

43

N. 1/16 Sections 26 and 25.
Found - Iron Pipe with GLO Brass Cap, bulldozed out of position, in fire
trail, approximately 10 ft. SW. of corner.
8" W.Fir S.67 1/2°E. 12.5 ft. scribing still visible. Tree alive & good.
Stump of 10" Fir S.50 1/2°W. 19.8 ft. scribing still visible, stump
partly uprooted & tipped over.
At Corner Reset Pipe with Brass Cap.
New BT: 18" D.Fir N.7°W. 41.8 ft. Mkd: "N 1/16 S26 CS BT".

Wilford N. Haines
June 29, 1962
C. S. File No. 51/222

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
November 1962
C.S. File No. 52/102

RE-RENEWED
NO. 56
#78