

Douglas County Surveyor's Record of
Government Corners Renewed

T23 T. S. R6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner for Secs. 22 and 23. See 1957 Resurvey.
Found - I.P. 26" in ground, 2" in diameter marked correctly set by cadastral
in 1957 resurvey in good condition, with brass cap from which:
An 8" now 10" fir bears S76°E., (record S78 1/2°E.) 17.2' dist. in
good condition with healed blaze.
A 9" fir bears N31 1/2°W (record N33 1/2°W.), 22.5' in fair condition
with healed blaze.
New BT - A 21" D. fir bears S25 1/2°W., 30.0' dist. marked "1/4 S22 CS BT"
in a double blaze.
Note: Corner lies approx. 160' East of N.E. flowing creek.
Compass dec. 20° East.

FD OK
BY K. HOFFINE
M117-3-4-93

68

A. Victor Cangie
James Cook
Karen Cheney
Douglas County Surveyor's Office
C.S. 59/15
5/18/76

3-77

Section corner for Secs. 1 and 12; and 6 and 7 of T23-5

Found - 1943 GLO brass cap 2" pipe (O.D.) 7" above ground properly mkd.
A Fir stump 24" bears S.5°E., (Rec. S.10°E.) 21.1 ft. blazed and
marked "R5W T23S S7".
A Fir stump 16", bears S.45°W., 42.6 ft. (Rec. 44.9 ft. blazed &
mkd. "T23S S12 BT".
Remains of Fir stump, center of root hole bears N.5°W., 14.5 ft.
A D. Fir windfall, 41" bears N.49°E., approx. 32.3 ft. to center
of root hole, single blaze & mkd. "T23S R5W S6 BT".
A D. Fir 36" bears S.21°E., 31.7 ft. with well healed blaze.
A Cedar, 28" bears N.53 1/2°W., (Rec. N.55°W.) 47.5 ft. with well
healed blaze facing N.70°E.
New BT's- A 11" Madrone, bears S.68°W., 19.4 ft. double blazed & mkd. "T23S
R6W S12 CS BT"
A 11" D. Fir bears N.56°E., 51.0 ft. double blazed & mkd. T23S
R5W S6 CS BT".

69

Cor. Rd 4/90
C.S. 63/27

Larry E. Monrean, Doug. Co. Surveyors Office
Roderick B. Kimberling
April 12, 1977
C.S. 59/31

SEE C.S. 61/5
FOR THEIR 1934
REPORT.
(Info. ADDED
3/21/1984
J.R.)

4/12/77

1/4 Corner for Sec. 1 and Sec. 6 of T23-5

Found - 1943 GLO brass cap on 1" pipe (O.D.) 13" above ground mkd. properly.
A Fir stump, decayed, orig. 36" size now indeterminate, bears
S.48°E., 37.6 ft. no visible scribing.
A Fir stump, badly decayed 24" bears S.35°W., 32.9 ft. with open
blaze mkd. "1/4 S" (Rec. 31.7 ft.).
A Fir snag, 20 ft. high, 25" dia. bears N.84°E., 19.1 ft. with
well healed blaze (Rec. 19.8 ft.)
A Fir stump, 24" bears S.76 1/2°W., 46.2 ft. One open blaze.
Scribing chopped out.
New BT's- A Black Oak, 18" bears S.69°W., 33.3 ft. blazed and mkd. 1/4 S1 CS BT.
A D. Fir, 8" bears S.60 1/2°E., 21.1 ft. double blazed and mkd.
1/4 S6 CS BT.
Note - Corner lies approx. 36 feet north of old road.

70

4/12/77

Township corner for Sec. 31; and Sec. 36 of T23-7; Sec. 1 of T.24-7 and
Sec. 6 of T24-6.

Found - All evidence of the orig. corner is gone.
Found a BLM brass cap reset by unknown party approx. 0.5 ft. from
proper location. This cor. was referenced by Doug. Co. Surveyors
Office in 1972 for road construction per notes attached to field
notes this renewal.
Found a 5/8" I.R. and PK nail in stump established as references for
this corner, N.84 1/2°E.
The SE references have been destroyed.
We RESET the BLM brass cap at the proper location as determined by transit and
chain from the County Surveyors references.
Found - From the 1957 dependent resurvey, a 22" now 23" G.Fir with well healed
blaze bears N.74 1/2°W., 115.6 ft. (Rec. 116.8 ft.)
The NE bearing tree has been destroyed.
From the 1964 BLM resurvey correcting the 1957 dependent resurvey:
an 8" now 12" D.Fir alive with well healed single blaze bears
N.63°E., 73.3 ft.
and a 15" now 17" I.Cedar with scribing "S R6W S6" visible on partially
healed single blaze bears S.85°E., 107.6 ft.

71

RESET the BLM iron post with brass cap attached marked as described in the
official record, flush in the shoulder of a dirt logging road. We add
the markings "Reset 1977" to the B.C. No new accessories. We place steel
fence post with survey marker witness sign attached approx one foot west of B.C.

8/29/77

Gary L. Langlitz, Doug. Co. Surveyors Office
R. B. Kimberling - M. W. Cline
Aug. 29, 1977
C.S. 59/38

RE-SET BLM CORNER NO. #92

Jan 78