

Douglas County Surveyor's Record of
Government Corners Renewed

23 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97126

RE-RENEWED SEE CORNER NO. #155 28
 1/4 COR. 34 and 35
 C. S. a 24" red fir, Vol. 1 Page 9

Dec. 30 1913 C.C. Boyer
 N. E. L. Cor. D.L.C. 38
 Set post, old B.T. down, marked New B.T.
 Fir 8" N 79° 10' E 24 lks. 127
 Fir 6" N 58° 10' W 23 lks.

S.W. Cor. D.L.C. # 51 Set Post Marked New B.T. Old bearing
 tree decayed. 123 Robert's 12/1906 30
 Bl. 10" S 72° W 22 1/2 lks
 W. Oak 8" N 61° W 22 lks.

1/4 COR. N. SEC. 5
 Reset stone 5" x 8" x 16" for 1/4 corner.
 12" B. Oak bears S 41° 43' W 12 lks
 10" B. Oak bears S 72° 27' E 24 lks. 183 31
RE-RENEWED SEE CORNER NO. #27
 (Copied from old corner book 2/264)

Ben B. Irving
 Wit: Ray Irving
 Jim Byron
 September 28, 1953
 Surveyors file
 45/211

Meander corner on North side of river. Sections 4 and 5. 32
 Found original B. T. 60 inch Fir S. 80° W., 55 lks. in fair condition.
 Blazed and scribed two new bearing trees; 119
 A 10" R. Fir, S. 68° 20' W., 90.0 feet distant, marked MC S5 S4
 C.S. B.T. & brass plate mkd MC S5 S4, T23S R7W.
 A 24 inch R. Fir, MC S5 S4, C.S. B.T. (markings) N. 10° 55' E., 64.0 feet,
 & with brass plate mkd MC S5 S4, T23S, R7W.

John M. Phillips
 Witnesses:
 Bill Edwards
 George F. Winterbotham
 Aug. 17, 1954.
 C. S. File 41/380

1/4 sec. corner to secs. 3 and 4. 33
 I reestablish corner by single proportional measurement.
 The corner is a 1 1/2 inch x 3 inch iron pipe, **SEE CORNER NO. 52**
 from which:
 A 32 inch D. Fir (MK 1/4 S 3 BT LS 307) bears S. 27° 40' E., 83.2 feet.
 A 56 inch D. Fir (MK 1/4 S 54 BT) bears S. 33° 35' W., 68.0 feet.
 A fence corner bears N. 28° 25' E., 40.0 feet.
 (See also later establishment by Wilford Haines)

James W. Byron, Deputy County
 Surveyor.
 Ray Irving, chairman
 May 25, 1955.
 C. S. File No. 46/24.
 FDBe
 Charles Guir
 7/80 4179-52

Section corner to secs. 35 and 36, (T 23 S, R 7 W) and ~~secs. 1 and 2,~~ 35+ 36 ONLY 34
~~(T 24 S, R 7 W).~~
 Found rotted stump of O. B. T. recorded 16 inch Fir, N. 42° W., 40.9 feet.
 Stump now only 12 inches. The upper part of stump rotted. No scribing
 visible. We cut out old blaze at base and find old blaze and scribing
 "B" "T". I also find W. Fir stump that shows old blaze. We do not
 cut out. Both stumps check for bearing and distances. The W. Fir stump
 is now 36 inches.
 Set a 1 inch iron pipe with brass cap at corner marked ~~35/36~~ T 23 S R7W
~~2/1~~ T 24 S
 County Surveyors Office 1954.
 Bark scribe a 40 inch R. Fir, N. 80° W., 22.0 feet S 35 T 23 S, R 7 W CS BT.
 Blaze and Scribe:
~~14 inch W. Fir., S. 80° E., 109.0 feet mkd. S 1 CS BT.~~ Correction O.K.
~~14 inch W. Fir., S. 57° W., 57.2 feet, mkd. S 2 CS BT.~~ J. M. Daily
 No tree near in N. E. Quad. See Also Cor #35 1/27/58