

KORE-CHARMAN CO., EUGENE, ORE. 21881

1/2 Section Corner East Side Section 3.  
Set 1" x 1" x 36" T. Iron.  
Found - 1" Iron Pipe & 2 BT's., scribed 1881.

RE-RENEWED SEE CORNER NO. #168 72

Wilford N. Haines  
For E. G. Whipple Mills  
Filed April 28, 1960  
Map File M 18 - 33

1/2 Section 2, West Side.  
Set 1" x 1" x 36" T. Iron.  
Found - 1" Iron Pipe N. 88° W. 34.0 ft.  
2 BT's., scribed 1881.  
36" Fir N. 11° E. 13 lks.  
18" Fir S. 25° E. 31.7 ft.

RE-RENEWED, SEE CORNER NO. #136 see Rev #67 73

S. 1/2 Corner Section 32.  
Found - 3/4" I. P. at Corner & BT. as recorded by Grant.  
Also find base of large rotted Fir Stump that  
checks orig. Dist. & Bearing for S. W. BT.  
Note - Corner Pipe is alongside 8" Ewewood Fence Post &  
is scribed "1/4 S32".  
I scribe new BT: 10" W. Oak bears S. 34° W. 29.0 ft.  
1/4 S32 CS BT.

74 Rev #26

Corner to Sections 32 and 33 only.  
Found - Orig. 14", now 22" R. Fir N. 45° W. 25.1 ft., shows  
good bark scribing "3 T23S R7W".  
Orig. 28", now 38" R. Fir S. 75° E. 35.6 ft., shows  
good bark scribing "S4".  
Orig. 8", now 3" Spike Stump of Orig. N.E. BT.  
Orig. S. W. BT. not found.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960  
S32/S33 T23S R7W  
T24S  
New BT's: 10" Cedar bears N. 29° E. 35.9 ft. scribed S33 T23S R7W CS BT.  
Rescribed, now 22" R. Fir N. 45° W. 25.1 ft. S32 T23S  
R7W CS BT.

75

James W. Byron, Deputy County Surveyor  
Milo Godfrey  
Clete Putnam  
September 1960  
C.S. File 49/49

Corner to Sections 31 and 32 only.  
Found - Orig. 16", now 30" W. Oak S. 10° W. 35.6 ft. I open  
& find good scribing "T".  
Orig. 30", now 52" Fir N. 13° W. 105.6 ft., shows  
good scar.  
Orig. 8", now 48" Fir shows good scar S. 40° E. 137.3 ft.  
Orig. N. E. BT. not found.  
Find 1" Iron Pipe at Corner.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960  
S31/S32 T23S R7W  
T24S  
New BT's: 14" R. Fir bears N. 14° E. 13.0 ft. scribed S32 T23S R7W CS BT.  
10" W. Fir bears N. 57 1/2° W. 37.8 ft. scribed S31 T23S R7W CS BT.

76

FD. OK 4-72  
DOLAN M115-3

Meander Corner Sections 32 and 33.  
Found - 6", now 14" Fir S. 35° W. 16.0 ft. I open & find good  
scribing "M S32".  
Frear's N. E. BT. not found. No Original BT's. found.  
Note - M.C. is in river bed set Wit. Cor. 50' South.  
Set - Brass Cap Mkd: WC 50' N. to MC T23S R7W County  
S32/S33 Surveyor's Office, 1960  
New BT's: 6" R. Fir bears S. 40° W. 55.7 ft. scribed W.C. MC S32 CS BT.  
8" R. Fir bears S. 52 1/2° E. 176.9 ft. scribed W.C. MC S33 CS BT.  
W. C. is 31.0 ft. North of Centerline of County Road.

77

RE-RENEWED SEE CORNER NO. #109

Renew R8W R7W  
S36/S31 T23S  
T24S.

78

Found - Orig. 16", now 36" Fir S. 65° W. 38.9 ft. Previously  
opened. Shows good scribing "T24S".  
Orig. N.E. & S.E., now rotted stumps only.  
Orig. 14", now 30" Fir N. 28° W. 72.6 ft., shows good scars.  
(continued next page)