

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

112

Sec. Cor. to Secs. 12 & 13, T23-7W. & Secs. 7 & 18, T23-6W.
Found - GLO Brass Cap, 1957 survey.
Dead White Fir Snag bears N.39°W. 39.6 ft., all scribing
visible on open blaze.
White Fir, uprooted & down, bears S.30°W. 33.7 ft., scribing
visible.
Doug. Fir, uprooted & down, bears S.68°E. 25.7 ft. Face
down, but old blaze had been chopped open (Orig. BT)
No other BT's. found at present time.
New BT's: 13" W. Fir S.81°W. 30.8 ft. Mkd: T23S R7W S13 CS BT.
6" W. Fir N.42½°W. 46.8 ft. Mkd: S12 CS BT.
8" Hemlock N.84½°E. 42.2 ft. Mkd: T23S R6W S7 CS BT.
6" White Fir S.53°E. 70.8 ft. Mkd: S18 CS BT.

May 8, 1964

113

Section Corner to Sections 1 - 2 - 11 - 12.
Found - Haines' T. Iron with 6" wooden Stake alongside (Ren. #94)
36" Cedar N.35°E. 53.5 ft., lower scar not completely healed
ever, good scribing visible "BT". Tree in good condition.
Cedar Snag S.38°W. 29.0 ft., center completely burned
away, scar visible on N.E. face.
Cedar Stump S.18°E. 28.4 ft., center rotted away. No scars.
No trace found of Maple to N. W.
Set - Brass Cap at Cor. alongside "T" Iron & Mkd: T23S R7W S 2 | S 1
County Surveyor's Office, 1964, Erect Rock Mound S11 | S12
around Corner.
New BT's: 26" Myrtle S.53°E. 76.0 ft. Mkd: T23S R7W S12 CS BT.
20" Maple N.16°W. 45.5 ft. Mkd: T23S R7W S 2 CS BT.
30" Maple S.30°W. 47.4 ft. Mkd: T23S R7W S11 CS BT.
Note - Corner is in draw, approx. 40 ft. W. of small stream.

Oct. 9, 1964

114

½ Section Corner to Sections 11 and 14.
Found - Haines' "T" Iron, See Ren. #62 & BT's. as follows:
Orig. 6", now 18" Maple S. 20° W. 31.0 ft., recorded as S.15°W.
Opened shows "T". Open higher & find "BT" scribe, rev.
Orig. 12", now 22" Maple N. 72° E. 29.0 ft., down, lying
almost on face. Did not open.
"T" Iron apparently set by distance intersection.
New BT's: 11" W. Fir S. 14° W. 24.7 ft. Mkd: ½ S14 CS BT.
5" W. Fir N. 24° W. 5.5 ft. Mkd: ½ S11 CS BT.
This corner lies on steep, N. W. slope.

115

Meander Corner to Sections 11 and 14.
Found - Haines "T" Iron & BT's. as follows:
Orig. 40", now 52" Fir S. 23° E. 29.0 ft., shows bark scribe
in poor condition & "363" bark scribe on West face.
DID NOT SET BRASS CAP.
New BT's: 7" Myrtle N. 80° E. 10.6 ft. Mkd: M.C. S11 CS BT.
7" Myrtle S. 9° W. 22.9 ft. Mkd: M.C. S14 CS BT.

116

½ Corner to Sections 30 and 31.
Found - 1" I.P. S. 35° E. 1.8 ft. of actual corner & location.
Orig. 15", now 40" Fir N. 35° W. 64.7 ft. & 66.5 ft. to
I. Pipe mentioned above. Open & shows "T" scribe on
partially burned faces. No trace S. W. BT.
DID NOT SET BRASS CAP because of log lying over corner point.
New BT's: - Bearings & Distances from Iron Pipe.
24" D. Fir N. 32° W. 26.5 ft. Mkd: ½ S30 CS BT".
20" D. Fir S. 52° E. 7.0 ft. Mkd: ½ S31 CS BT.
This corner lies on moderate, N. E. slope approximately 450 ft. W. of Road.

Milo E. Godfrey, Deputy
Wm. Stoffel - Stone - Darby
C. S. File No. 52/102

M. E. Godfrey &
Crew
Oct. 9, 1964
C. S. File No.
52/125

Vernon "Ray" Tracy
Mike Stone and J. Layne
December 1965
C. S. File No. 52/125

RE-REVIEWED & RE-CORRECTED #160