

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21601

FD. OK 9-92 BY BECKLEY M119-80

117

Meander Corner to Sections 5 and 8.

Found - Orig. 15", now 30" Oak N. 15° W. 106.3 ft., now almost dead.
(BT. on right bank, prev. opened & shows scribe. We open & find "BT".

No trace of S. W. BT. Since corner fits the E-W section line btwn. sections 5 and 8, we assume a mistake in original section number, should be S 5.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23SR7W M.C. $\frac{S}{S} \frac{5}{8}$
Office, 1965

New BT's: 13" D.Fir S. 66° W. 110.7 ft. Mkd: M.C. S8 CS BT.
6" W.Oak N. 18° W. 78.5 ft. Mkd: M.C. S5 CS BT.

This corner lies approximately 75.0 ft. S. of Road, course S.W. & N. E.

118

$\frac{1}{4}$ Section Corner to Sections 5 and 4.

Found - Orig. 25", now 54" Fir N. 4° E. 33.0 ft. shows "4 S", bark scribe in very poor condition.

No trace of other BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965
T23S R7W $\frac{1}{4}$ S 5/S 4

New BT's: 8" Myrtle N. 67° E. 6.7 ft. Mkd: $\frac{1}{4}$ S 4 CS BT.
15" D.Fir S. 51° W. 24.6 ft. Mkd: $\frac{1}{4}$ S5 CS BT.

This corner lies on very steep S. E. slope of River Bluffs.

119

Meander Corner To Sections S 5 / S 4.

This corner lies on the right or North Bank of River.

Found - One BT., as recorded Ren. #32

24", now 27" D.Fir N. 11° E. 64.0 ft., part of brass plate & some scribe visible on partially healed face.

No trace of S. W. BT.

Orig. BT., now stump.

Drive - $\frac{3}{4}$ " Iron rod at Corner Point - Not practical to set Brass Cap due to possibility of high water.

New BT: 9" D.Fir N. 31° W. 68.1 ft. Mkd: M.C. S 5 CS BT.

120

$\frac{1}{4}$ Section Corner to Sections 4 and 9.

Found - Orig. 8", now 20" W.Oak N. 9° E. 44.2 ft. We open & find " $\frac{1}{4}$ S" reverse scribing.

No trace of S. E. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R7W $\frac{1}{4}$ $\frac{S}{S} \frac{4}{9}$
Office, 1965

New BT's: 18" W.Oak N. 1° E. 143.6 ft. Mkd: $\frac{1}{4}$ S4 CS BT.
18" W.Oak S. 71° E. 215.5 ft. Mkd: $\frac{1}{4}$ S9 CS BT.

This corner lies approximately 260 ft. west of top of river bluff in open field.

121

S. W. Corner D.L.C. No. 48.

Found - Orig. 18", now 40" Fir N. 15° W. 11.9 ft., shows "C 123S 7W", bark scribed in fair condition.

No trace of S. E. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965
T23S R7W \angle S.W. D.D.C. #48.

New BT's: 8" D.Fir N. 80° E. 45.2 ft. Mkd: SW DLC 48 CS BT.
11" D.Fir N. 16° E. 48.4 ft. Mkd: S.W. DLC 48 CS BT.

This corner lies on top, small, round spur, sloping East.

122

E. SE. Corner D.L.C. No. 48.

Found - Orig. 10", now 30" Oak N. 6° E. 266.0 ft., now charred stump.
We open & find notch & "B" scribe & reverse.

No trace of S. W. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965
T23S R7W E. SE. DLC 48 $\frac{1}{4}$

New BT's: 12" W.Oak S. 18° W. 36.7 ft. Mkd: E SE DLC 48 CS BT.
10" W.Oak S. 57° E. 7.0 ft. Mkd: E SE DLC 48 CS BT.

This corner lies approximately 60 ft. East of creek, course South and approximately 80 ft. North of Road.

Vernon "Ray" Tracy
Mike Stone and Jerry Layne
December 1965
C. S. File No. 52/125