

Douglas County Surveyor's Record of
Government Corners Renewed

T 23 T. S. R 7 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

157

Meander corner for Secs. 33 and Sec. 4 of T.24-7
Found - 5/8" x 30" I.R. firmly set buried 4" in the ground with
a white 2" x 2" post 1 ft. high alongside. Ren. #147
40" now 44" fir with partially healed pitched over blaze bears
N.52°W., 43.1 ft. (rec. 42.3 ft.) Ren. #147
18" now 20" maple with scribed "T24S R7W S4 MC BT" visible
in unhealed blaze, bears S.36°E., 14.0 ft. Ren. #147
Set - At the location of the found 5/8" I.R. I SET a 1" x 30" I.P. with
brass cap attached marked "County Surveyors Office T23S R7W
S33 S4 MC T24S 1982".
I bury 5/8" I.R. along north edge of brass cap 6" deep.
New BT - 11" myrtle scribed "T24S R7W S4 MC CSBT" in double blaze bears
S.57°E., 30.7 ft.
Sketch in C.S. file.

Greg Quibell,
Deputy, Doug. Co.
Surveyors Office
John Powell
Jan. 6, 1982
C.S. 61/30

158

Meander corner for Secs. 4 and 3 only, of T.24-7
Found - 5/8" x 30" I.R. set in rip-rap shoulder of road. Ren. #146
21" myrtle with scribed "T24S R7W S3 MC BT" visible in unhealed
blaze bears S.67°E., 53.2 ft. Ren. #146
15" now 18" myrtle with scribed "T24S R7W S4 MC BT" visible in
unhealed blaze bears N.29°W., 17.6 ft. Ren. #146
Set - Being unable to set standard I.P./brass cap monument in rep-rap
shoulder, I PLACED 1 1/4" dia. alum. cap on found 5/8" I.R.
and marked it "Douglas Co. MC 4 3 1982 Surveyor".
Sketch in file.

159

1/4 Corner for Secs. 24 and 25
Set - 2" x 32" galv. iron pipe with a 2 1/2" brass cap marked
"Shaner Engineering RLS 430, 1982, T23S R7W W.M., 1/4 S24
S25" with a steel fence post alongside, and from which:
A 52" D. fir stump, orig. BT, with probable scribe "B" cut from
toe of stump, bears N.46°W., 9.2 ft. Tag by Surveyor Wilfred Haine
and U.S.B.L.M. BT tag both on this stump. I rescribed
"1/4S S24 BT".
A 52" D. fir, orig. BT, bearing S.15°E., 26.4 ft. now missing.
Apparently removed by U.S.B.L.M. land clearing operation to the
South for the progeny tree orchard.
Note: In 1962 when I was at this corner the NW BT had scribes visible and
the SE BT was still in position. Ren. #105. Also see Ren.142
New BT - 36" D. fir stump, I scribed "1/4S S25 BT" bears S.79°W., 29.6 ft.
Note: The corner is at the same location as the corner that I set a square
wood stake in 1962. (See CS File M23-62). The wood stake was found
on the ground near the corner. There is an East-West blazed line and
timber cutting line through the corner location. There is a
cutting line 1/2 mile North on a bearing of N.1°W., as per 1962
survey on the North-South section centerline.

Bruce Shaner L.S. #430
For: International
Paper Company
November 9, 1982
C.S. 58/229

11/9/82

160

1/4 Corner common to Secs. 30 & 31. Ren. #116.
Set - 1" x 36" Iron Pipe in concrete w/Brass CapMkd: T23S R7W
PLS 839 1/4 30 31 1983.
New BTs- 26" fir bears N.26°E., 49.4-ft., Mkd:1/4 S30 BT.
14" fir bears S.9°E., 35.0-ft., mkd:1/4 S31 BT.
Fd - 1" I.P. bears S.35°E., 1.8-ft. 3/83

Don Bentz
PLS #839
For: International
Paper Co.
March, 1983
M 90 - 38 A & B

Center 1/4 Corner of Sec. 31. Ren. #175
Set - 1" x 36" I.P. in conc. w/Brass Cap mkd: T23S R7W PLS 839 C-C 1/4
31 1983.
New BTs- 18" fir bears N.45°W., 19.0-ft. mkd:C1/4 S31 BT.
14" fir bears S.30°W., 29.1-ft. mkd:C1/4 S31 BT. 3/83

RE-RENEWED, SEE CORNER NO. #175

161

SE corner of Lot 10. (Born 19430)
Set - 1-1/2" x 36" I.P. with B.C. at proportionate distance.
New BTs- 9" fir bears S.55°E., 5.3-ft. (both trees scribed).
15" fir bears N.5°E., 32.2-ft.
Note - North-south fence bears east 6.0-ft. 4/12/83

Les Roberts,
LS#1039
For:International
Paper Co.
M 94 - 12
April 12, 1983

162