

Douglas County Surveyor's Record of
Government Corners Renewed

T 23

T. S.

R 7

R.W.W.M.

ROSE-CHAPMAN CO., EUGENE, ORE. 97101

167

1/4 Corner for Section 2 only. (west)

Found - Iron pipe with 1966 County brass cap properly marked and firmly set. Ren. #136

1" dia. iron pipe referred to by Haines as N.86°W., 64.9 ft.

Orig. BT, a 12" fir now a shattered fir stump 36" dia. with fragmentary scribing visible on blaze bears N.11°E., 8.6 ft.

Possible Orig. BT, recorded Ren. #73 as 18" fir, S.25°E., 31.7 ft.

is dead and down, out of position and partially decayed. We find scribing possible "S" and "B" (see photos in file) along with old axe notch in old blaze.

Not found - Record orig. BT, 10" fir N.72°W., 124 lks. not found.

Found - 7" W. fir S.20°E., 7.2 ft. is dead and down. Ren. #136

7" D. fir now an 8" dia. snag bears N.21°E., 25.2 ft. Ren. 136

New BTs - 8" dia. D. fir double blazed & scribed "1/4 S2 CS BT" bears S.62½°E., 34.6 ft.

6" dia. D. fir double blazed & scribed "¼ S2 CS BT" bears S.35°E., 48.3 ft.

13" dia. D. fir double blazed & scribed "¼ S2 CS BT" bears N.56°E., 47.4 ft.

168

East 1/4 Corner for Section 3 only.

Found - Haines "T" iron protruding about 12" above ground, firmly set bent and partially covered by decaying log. Ren. #72

Haines Map M18-33 shows finding a 1" iron pipe. We were unable to locate this monument at or near the "T" iron. I checked with Mr. Haines who checked back through his notes. He provided a copy showing the 1" I.P. at S.64°49'W., 61.23 ft. from his monument. We were not able to locate the iron pipe. (Haines copy of his note is filed in C.S. file #62/31)

No bearing trees were found at S.3°W., 79.2 ft. or S.38°E., 99.0 ft

Found - 42" dia. fir stump, 6 ft. high with previously opened blaze (14" deep) scribing "1/4S" and old axe notch visible. (see photos in C.S. file) A ring count places blaze at about 70 years prior to trees death. From Haines monument this tree bears N.88°W., 80.6 ft.

A 48" dia. fir stump 4 ft. high with previously opened possible blaze bears N.10½°E., 68.7 ft. The apparent blaze has been burned out. No scribing, face, axe notch, or burl wood was located in the blaze. This stump has 3 axed notches on westerly edge.

The blazes on the two found trees were oriented toward Haines monument. (See Photos)

Set - To perpetuate this location as determined by Haines, WE Set a 1" x 30" iron pipe with a brass cap marked: "Douglas County Surveyors Office T23S E 1/4 S3 only R7W 1986". We place the found "T" iron monument along northerly edge of brass cap.

New BTs- 7" D. fir double blazed & scribed "1/4 S3 CS BT" bears S.28½°W., 35.5 ft.

9" W. fir double blazed & scribed "¼ S3 CS BT" bears S.76°W., 45.2 ft.

27" W. fir double blazed & scribed "¼ S3 CS BT" bears N.46°W., 68.3 ft.

Note: This position (according to M18-33) is located on line between W 1/4 Sec. 2 and corner of sections 3 and 2 on township line.

169

1/4 Corner for Sections 21 and 28

Found - 1963 BLM brass cap on a 2½ in. dia. iron pipe protruding 4" above ground mkd. "U.S. Dept. of Interior" 1/4 S21 S28 T23S R 7 W 1963 Bur. of Land Management".

A 5/8" iron rod protruding 4" above ground and is along east edge of 1963 BLM brass cap. Ren. #46

Sandstone monument was not looked for. (Buried alongside BC/IP per BLM 1963 dep. resurvey)

30" now 36" dia. ± 40 ft. high D. fir snag with a partially healed single blaze, scribing visible "S21 BT", bears N.1½°W., 47.2 ft. (Rec. N.1½°W., 48.2 ft. Dist. is a slope dist. 1963 BLM resurvey)

6" now 13" dia. D. fir with a fully healed single blaze bears S.10°E., 24.1 ft. (agrees well with 1963 BLM resurvey)

6" now 12" dia. D. fir with a fully healed single blaze bears N.42½°W., 24.7 ft. (rec. N.42½°W., 25.7 ft. dist. is to center

Douglas County Surveyors Office
Larry E. Monrean, Deputy
S. J. Flause - Randall Smith Notekeepers
Witness: Rhonda Amer
February 7, 1986
C.S. 62/31

Douglas County
Surveyors Office
Randall W. Smith
Stephen J. Flause
March 31, 1987
C.S. 62/40