

Douglas County Surveyor's Record of
Government Corners Renewed

T 23

T. S.

R 7

R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 91881

176

Section Corner for Secs. 14, 15, 22 and 23

- Found - 3 1/4" dia. BLM brass cap on a 2 1/2" O.D. Iron pipe protruding 6" above ground. 1961 BLM)
2 1/2" dia. brass cap on a 1 1/4" O.D. Iron pipe protruding 6" above ground is located along the west edge of BLM BC/IP. (unrecorded survey by John Phillips)
1" T.Iron proturdes 12" above ground set by Wilford Haines in Ren. No. 58, bears N.57°E., 8.3 ft. from BLM BC/IP.
24" now 30" dia. B.Oak down and rotted B. Oak, no blazes or scribing visible, root hole bears N.33°W., 75.2 ft. (agrees with record.) Orig. BT.
6" now 13" dia. B.Oak with a fully healed single blaze, bears N.36 1/2°E., 11.7 ft. (BLM record N.21°E., 12.5 ft.) Ren. No. 58
16" now 31" dia. D.Fir with a fully healed single blaze, bears S.24°E., 89.8 ft. (Rec. S.39°E., 89.8 ft.) 1961 BLM
10" now double trunked B.Oak with a fully healed single blaze on 22" East trunk, root crown bears S.68 3/4°W., 85.8 ft. (Rec. S.53°W., 85.8 ft.) 1961 BLM

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Terrie Frannsen
Feb. 10, 1992
C.S. File 64/23

Note: A consistant bearing rotation on renewal trees. I think tie to original BT and Haines T-Iron was done with a different instrument than one used in tieing Renewal trees.

- New BTs - 20" now 39" dia. D.Fir with a fully healed single blaze bears N.48°E., 20.8 ft. (BT from Ren. No. 58 not tied to BC/IP in 1961)
14" DBH D.Fir scribed "T23S R7W S15 CS BT" on a double blaze. (Upper blaze reads from bottom to top), bears N.70°W., 23.6 ft.
A North-South fence line is 1 ft. west of BLM BC/IP.

2/10/92

Tsp. Corner - SE Corner Section 36

- Found - 3 1/2" dia. BLM brass cap on iron pipe is flush with ground. 1957 BLM cap, reset 1977) Ren. No. 150
22" now 35" dia. Grand Fir with a fully healed single blaze bears N.74 1/2°W., 115.6 ft. (agrees with Ren. No. 150) BLM BT
8" now 15" dia. D.Fir with a fully healed single blaze, bears N.63°E., 73.3 ft. (agrees with record) 1964 BLM tree
15" now 22" dia. I.Cedar with a fully healed single blaze, bears S.85°E., 107.6 ft. (agrees with record) 1964 BLM.
New BT - 8" dia. D.Fir double blazed and scribed "T24S R7W S1 CS BT" bears S.45°W., 19.3 ft.

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Feb. 7, 1992
C.S. File 64/23

2/7/92

- FO. OK BY BECKLEY 9-92 M119-80*
Closing Corner for Sections 31 and 32 only, T.22-7
Found - A sandstone rock marked "SC" on South face, stone protrudes 9" above ground, top ;measures 10" x 4". Ren. #46 in T22-7
15" now 34" dia. D.Fir with a fully healed single blaze, bears N.36°W., 96.2 ft. (agrees w/rec) Ren. No. 101
29" now 20" dia. down and rotted Oak stump, no blazes or scribing visible, bears N.14°E., 248.5 ft. to root hole (agrees with record) (Ren. No. 46 in T22-7)
No other BTs found.

Brass cap not set, stone is solid and in good shape.

New Accessories:

- 6" dia. B.Oak double blazed and scribed "T22S R7W S32 CS BT" bears N.0 1/2°E., 100.8 ft.
1/2" copper rod at intersection of east-west and south running fence lines bears S.89°E., 118.1 ft.

Corner lies 0.5 ft. north of an east-west fence line. Approx. 100 ft. west of crest over rolling hill.

2/12/92

179

Interior "L" Corner for DLC #44 (on bdy. between Secs. 20 & 29)

- Set - 5/8" Iron Rod.
BT - 18" W. Oak bears S.32°30'W., 36.4 ft. scribed Int. "L" Cl. 44.

6/11/66

Don E. Garrett
For: Roseburg Realty
June 11, 1966
C.S. File 55/2