

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

36

Section Corner to Sections 16 - 17 - 20 - 21,
Found - Orig. 40", now 60" Fir S. 24° W. 21.8 ft. Open & find
"8" scribe & reverse,
Orig. 30", now 50" Fir N. 18° W. 52.1 ft., shows scar.
We do not open,
No trace other Orig. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T23S	S 17	S 16
R8W	S 20	S 21

New BT's: 13" Hemlock S. 21° E. 19.4 ft. Mkd: T23S R8W S21 CS BT.
24" Hemlock N. 61° E. 19.1 ft. Mkd: T23^S R8W S16 CS BT.
16" Hemlock N. 37½° W. 22.2 ft. Mkd: T23S R8W S17 CS BT.
11" Hemlock S. 59° W. 14.9 ft. Mkd: T23S R8W S16 CS BT.

Note - This corner lies 30 ft. North of road on top of ridge.

37

¼ Corner to Sections 18 and 17.
Found - Orig. 40", now 48" Fir Stump N. 26° W. 29.7 ft., prev. opened
& shows "¼S" scribe on burned face.

Orig. 40", now 48" Fir Stump S. 74° E. 21.8 ft. Do not
open, cut low probably no scribe left.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T26S R8W ¼ S 18/S 17

New BT's: 8" D. Fir S. 9° W. 18.1 ft. Mkd: ¼ S18 CS BT.

13" Hemlock S. 16½° E. 54.0 ft. Mkd: ¼ S17 CS BT.

Note - This corner lies on steep, East slope, approx. 100 ft.
North of top of ridge, course N.W. & S.E.

38

¼ Corner to Section 15 and 16.

Found - Orig. 9" D. Fir, now rotted stump, S. 44° W. 13.2 ft.,
unhealed face shows "¼S" scribe.

No trace of S. E. BT.

Set - Brass Cap at ¼ Cor. Mkd: County Surveyor's Office, 1966

T23S R8W ¼ S 16/S 15

New BT's: 20" D. Fir S. 88° W. 22.3 ft. Mkd: ¼ S16 CS BT.

22" I. Cedar N. 80° E. 31.0 ft. Mkd: ¼ S15 CS BT.

Note - This corner lies on steep, south slope, approx. 300 ft.
south of top of ridge, course E. & W.

39

¼ Corner to Sections 20 and 29.

Found - Stone at Corner 14" x 12" x 7" mkd: "¼" on N. face,
firmly set, as called for in Orig. field notes.

Orig. 40", now 60" Fir N. 2° W. 39.6 ft., shows good scar,
Alive, we do not open.

No trace of other Orig. BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T23S R8W ¼ S 20
¼ S 29

Reset Stone alongside.

New BT's: 5" Hemlock N. 78° W. 15.8 ft. Mkd: ¼ S20 CS BT.

25" Chinquapin N. 36° E. 30.4 ft. Mkd: ¼ S20 CS BT.

Note - This corner lies on top of ridge, course N.W. & S.E.

40

North ¼ Corner to Section 4 only, T24S. R8W.

Found - 1894 Rock with ¼ on N. Side

1894 BT., now a windfall lying Eastward with face up,
not chopped out.-N.87°W. 30.4 ft.

1894 BT., S.34°E. 11.2 ft., now 14" Dead Snag, face open,
scribes X copped in bark.

6" Alder BT. S.38°22'E. 35.62 ft., dying, with Weyer.Alum.Tag.

Set - 5/8" Rod, 4.0 ft. tall, adjacent to Rock. & Mkd:

4 ft. Dead Fir S. 89° 35' E. 4.6 ft., old "X" chopped in bark,
placed Weyer. Metal Tag.

Note - Corner is located 92.86, slope dist. (81.09 horiz) North of top
of spur ridge which slopes eastward towards Rader Creek, approx.

¼ mile eastward down spur ridge from BLM, blacktopped Buck Mt. Road.

Vernon "Ray" Tracy
Mike Stone and Jack Heritage
April 1966
C. S. File No. 54/12

WeyerhaeuserCo.
By Louis Prahar
August, 1966
C. S. File No. 55/11