

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 8 W. R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE., 21891

Section Corner to Sections 4 - 5 - 8 - 9.
Found - Orig. 24", now 40" Fir, N. 67° W., 25.1 ft. Open & find @S"
scribe.

All other Orig. BT's. now only badly decayed remains of stumps,
apparently destroyed by old fire.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1966
(Set in mound of Stone)

T 23 S	R 8 W
S 5	S 4
S 8	S 9

New BT's: 13" D. Fir S. 21° W. 23.0 ft. mkd. T23S R8W S 8 CSBT.
12" D. Fir S. 18° E. 15.4 ft. mkd. T23S R8W S 9 CSBT.
8" D. Fir N. 64° E. 5.7 ft. mkd. T23S R8W S 4 CS BT.
5" D. Fir N. 28° W. 8.8 ft. mkd. S 5 CS BT.

Note - This corner lies 6 ft. east of top of ridge, sloping north.

CORNER REFERENCED 2/4/79 L. MANREAN Div. Co SURVEYORS OFFICE FOR ROAD CONSTRUCTION C.S. 53/30

Sec. Cor. to Sections 33 and 34 only, T23-8W.
(N. Bdry. T.24S.)

Found - Orig. 60", now 62" Fir, N. 83° E. 19.1 ft. Alive, shows "T W"
& fragmentary bark scribe.

Orig. 40", now 43" Fir, S. 67° W. 40.9 ft. Alive, shows good
scar. We do not open.

Orig. 12" Fir, now 16" decayed remains of stump, N. 79° W.
41.6 ft., find "BT".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967
(Set in mound of Stone)

T 23 S	R 8 W
S 33	S 34

New BT's: 16" D. Fir W. 34½° E. 22.7 ft. mkd. T23S R8W S34 CS BT.
12" D. Fir N. 37° W. 25.2 ft. mkd. T23S R8W S33 CS BT.

Note - This corner lies on steep, south slope approx. 40 ft. west
of shallow draw, course S.W.

¼ Corner to Sections 32 and 33.

Found - Sandstone 13"x8"x5" mkd. ¼" on W. face, firmly set.

Orig. 30", now 36" Fir, alive, S. 18° E. 35.6 ft., shows,
¼ S BT" bark scribe in fair condition.

Orig. 30", now 36" Fir, alive, N. 22° W. 17.8 ft., shows good
scar. We do not open.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967

T 23 S	R 8 W
S 32	S 33

New BT's: 15" Yew S. 10° W. 41.5 ft. mkd. ¼ S32 CS BT.
5" Yew N. 69° E. 2.7 ft. mkd. ¼ S33 CS BT.

Note - This corner lies on steep, west slope, approx. 200 ft. north
of E.-W. cutting line, cut off to south.

Sec. Cor. to Sections 30 & 31 only, T23-8W.

Found - Sandstone 16"x6"x8", firmly set but covered 6" deep with
loose dirt & mkd. with 1 notch on S. & 5 notches on N. edges.

Org. 5", now 18" Fir, alive, N. 41° E. 3.3 ft., shows good scar.
(Rescribe "T23S R8W S30 CS BT")

Orig. 10", now 30" Fir, alive, S. 61° E. 13.9 ft., shows fair scar.
(Rescribe "T23S R8W S31 CS BT")

Orig. 14", now 38" Fir, alive, S. 54° W. 75.9 ft., shows good scar.
Do not open.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967
(Reset stone alongside)

R	T 23 S	R
9	S 30	8
W	S 31	W

Note - This corner lies on E. edge of small creek, course S. 10° E.

Sec. Cor. to Sections 25 & 36 only, T23-9W.

Found - No trace of rock called for.

Orig. 28", now 28" Fir Snag, S. 89° W. 12.5 ft., shows @T23SR9W S36"
on unhealed blaze.

Orig. 20", now 34" Fir, alive, N. 80° W. 33.0 ft., shows good scar.
(Rescribe "T23S R9W S25 CS BT")

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967

T 23 S	R
S 25	W
S 36	W

New BT: 24" D. Fir S. 75° W. 17.4 ft. mkd. T23S R9W S36 CS BT.

Note - Cor. lies on very steep N.E. slope approx. 540 ft. South of Creek.

Vernon "Ray" Tracy
Jack Heritage & Edmer West
January, 1967
C. S. File No. 54/12

RE-RENEWED, SEE CORNER NO. #118
RE-RENEWED, SEE CORNER NO. #121
RE-RENEWED, SEE CORNER NO. #135

51

52

53

54

55