

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 8 W. R.W.W.M.

Vernon "Ray" Tracy  
Jack Heritage & E. West  
January, 1967  
C. S. File No. 54/12

$\frac{1}{4}$  Corner to Section 18 only, T23-8W. 61  
Found - Orig. 40" D. Fir, now snag, S. 5° E. 94.4 ft., scribe "4s"  
in the wood, there were two good faces plus ring count.  
No trace of other BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967 

R	T 23 S	R
9 $\frac{1}{4}$	S 18 8	
W		W

  
New BT's: 30" W. Fir S. 47° E. 14.5 ft. mkd.  $\frac{1}{4}$  S18 CS BT.  
11" W. Fir N. 61° E. 36.8 ft. mkd.  $\frac{1}{4}$  S18 CS BT.  
Note - This corner lies on top of ridge, course West.

Sec. Corner to Sections 18 & 19 only, T23-8W. 62  
Found - Orig. 50", now 72" Fir, N. 15° E. 18.5 ft. Alive, shows good  
scar. Do not open.  
Orig. 20", now 38" Cedar, S. 75° E. 44.2 ft. Alive, scribe  
visible on unhealed blaze.  
Orig. 14", now 30" Cedar, N. 79° W. 9.9 ft., badly injured,  
no scribe found.  
No trace of sandstone called for in notes.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967 

R	T 23 S	R
9	S 18	8
W	S 19	W

  
New BT's: 8" Hemlock S. 59° E. 26.3 ft. mkd. T23S R8W S19 CS BT.  
14" Hemlock N. 75° E. 30.8 ft. mkd. T23S R8W S18 CS BT.  
Note - This corner lies on steep, S.W. slope, approx. 200 ft. N. of Creek.

$\frac{1}{4}$  Corner to Section 6 only, T24-8W. 63  
Found - Orig. 24", now 34" Fir Snag, N. 26° E. 35.0 ft., Open & find "S"  
scribe very lightly cut into face.  
Orig. 12", now 26" Hemlock, turned out & lying face down, S. 26° E.  
21.8 ft. 21.8 ft.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 

$\frac{1}{4}$	T 23 S	R 8 W
S 6	T 24 S	

  
New BT's: 13" Hemlock S. 8° E. 26.5 ft. mkd.  $\frac{1}{4}$  S 6 CS BT.  
8" Hemlock S. 45 $\frac{1}{2}$ ° W. 29.7 ft. mkd.  $\frac{1}{4}$  S6 CS BT.  
Note - This corner lies nearly on top of ridge, course E. - W.

$\frac{1}{4}$  Corner to Section 31 only, T23-8W. 64  
Found - Orig. 28", now 32" Fir, shattered snag, N. 23° W., 4.0 ft.  
shows  $\frac{1}{4}$  S" bark scribe on upper blaze in fair condition  
& fragmentary bark scribe on lower blaze.  
S.W. Orig. BT. could be under a pile of blow down.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 

$\frac{1}{4}$	S 31	T 23 S	R 8 W
		T 24 S	

  
New BT's: 10" Hemlock N. 65° W. 6.8 ft. mkd.  $\frac{1}{4}$  S31 CS BT.  
6" Hemlock N. 37° E. 15.0 ft. mkd.  $\frac{1}{4}$  S31 CS BT.  
Note - This corner lies 33.0 ft. East of  $\frac{1}{4}$  Cor. Sec. 6, T24-8W. #58, see above.

Sec. Cor. to Secs. 32 & 33 only, T23-8W. 65  
Found - 1963 Cadastral Brass Cap, properly mkd. with  $\frac{1}{2}$ " pipe alongside.  
Orig. 16" Hemlock, now broken & high stumped, N. 7 $\frac{1}{2}$ ° E. 25.1 ft.,  
blaze chopped open & scribe visible.  
Orig. 28" Hemlock Stump S. 73 $\frac{1}{2}$ ° W. 33.0 ft., shows old scar.  
Orig. 8" Hemlock, (not fir) N. 68° W. 23.1 ft., Dead & nearly  
pushed over, scribe visible on chopped out blaze.  
45" Hemlock N. 82° E. 34.3 ft., turned out & burned, scribe visible.  
New BT: 40" Fir Stump N. 51° E. 17.1 ft. mkd. T23S R8W S33 CS BT.  
Note - This corner lies on west edge of Cat. Road, nearly buried.