

Douglas County Surveyor's Record of  
Government Corners Renewed

23 T. S. 8 R. W. W. M.

YOKE-CHAPMAN CO. EUGENE, ORE. 97801

100

John M. Powell  
Gary Langlitz  
8/3/72  
C. S. File 54/12

Section Corner, Sections 18, 17, 19, and 20.  
Found - Orig. Hemlock, now 10' stump, N.22°W., 31.2 ft. Faint scribe visible "S18".  
28" Hemlock, now 7' stump, S.76°E., 14.5 ft. Scribe visible T.23S. R.8W. S20 CS BT.  
20" Cedar, uprooted stump lying on face (VBT's BT tag)  
No trace of 1965 Brass cap. Area badly torn up from logging. Other BT's destroyed. Ren. No. 29  
Set - Brass Cap at sec. cor. mkd. County Surveyor's Office 1972

T 23 S R 8 W
S 18   S 17
S 19   S 20

Also steel fence post along side.  
New BT's: 52" Fir stump, S.49° W., 45.5 ft.  
30" Cedar stump, S.37°E., 43.7 ft.  
Note: This corner lies in old clear cut. No trees available for BT's.  
August 3, 1972

Hintz,  
Richard J.  
For:BLM  
Map:M46-59

Center 1/4 Corner to Section 14.  
Set - 5/8" Iron Rod.  
Location Sign on 14" Fir which bears N. 42° W. 15.7 ft.  
9/18/72

101

John M. Powell  
J. Heritage  
G. Commons  
March, 1973  
C.S. File 56/25

Section Corner, Secs. 8-9-17-16.  
Found - Orig. 30" Fir, now stump, S.53 1/2°W., 31.0 ft.  
1958 BT, 34" F. stump, N.15°W., 27.7 ft. scribed T23S R8W S8 BT.  
1958 BT, 50" Fir snag, N.12°E., 150.5 ft.  
1958 GLO brass cap at section corner.  
New BT's - 6" W. Fir, S.74°E., 18.4 ft. scribed S16 CS BT.  
6" D. Fir, N.50°E., 11.3 ft. scribed S9 CS BT.  
12" D. Fir, N.42°W., 19.7 ft. scribed T23S R8W S8 CS BT.  
5" D. Fir, S.3°W., 15.2 ft. scribed S17 CS BT.  
3/16/73

102

John M. Powell  
J. Heritage  
April 23, 1973  
C.S. File 56/25

1/4 Corner, Sections 13 and 14. *(1/4 COR 13 ONLY)*  
Found - 1967 County Surveyors Brass Cap mkd. T23S R8W 1/4 14/13. Ren. #69  
Note - Dependent Resurvey has changed this to 1/4 S13 only.  
Renewal - Remark Brass Cap for Sec. 13 only. Destroy BT's for Sec. 14.  
New BT's - 28" D. Fir, N.63°E., 32.0 ft. Scribed 1/4 S13 CS BT.  
Note - BLM Brass Cap bears south 7.3 ft. mkd. for Sec. 14 T23S R8W.  
4/23/73

103

L. E. Monrean  
P. Earle  
10/19/73  
C.S. 56/39

Sec. Corner, Secs. 1 and 12; ~~T23-96~~ and ~~1~~ Sec. 6 only, T23-8  
Unrecorded evidence found. Corner not set.  
Found - 2" sq. post out of ground with "location marker" tag "S B Merrick, D. Mower 1 8/15/57  
12  
6' stump, uprooted and down hill from its orig. location, bears a tag mkd. "RD 5/2/67, Sadler  
Scribed stake, 2' north, H O Malac, 10-15-64.  
15" Fir with Forestry appraisal tag.  
All BT's are gone or uprooted with no scribing.  
10/19/73

104

John B. Gearhart  
for Hazel Clark  
M 51 - 45  
October 1973

Center Section 11  
Found - Brass cap at center of sec. 11 disturbed.  
Found hole and reset brass cap  
Found - 13" Fir stump, bears S.03°13'E., 187.5. feet.  
(S.3°E., 185.46 feet)  
10/1973

105

Gary Langlitz  
P. Earle  
C.S. 56/51  
5/20/74

Sec. Cor. for Secs. 30-29-31-32  
Found - Orig. 18" now 30" Hemlock stob, rotten with scribing "2 R 8" visible on unhealed blaze.  
Orig. 12" now 30" Hemlock, we open and find scribe marks.  
We do not find adequate evidence to verify the remaining two original bearing trees.  
Set - Brass cap at the corner point mkd.  
COUNTY SURVEYORS OFFICE 1974

T 23 S R 8 W
S30   S29
S31   S32

106

CONT.