

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 T. S. R. 8 R.W.W.M.

CONT.

#106

from which:

An orig. 18" now 30" rotten hemlock stob with scribing visible bears S.35°W., 20.5 ft.

An orig. 12" now 30" hemlock bears N.55°E., 17.2 ft. We open & find scribe marks.

- New BT's - 15" hemlock bears S.84°E., 50.2 ft. scribed "T23S R8W S32 CS BT":
22" hemlock bears S.65°W., 62.3 ft. scribed "T23S R8W S31 CS BT"
14" hemlock bears N.55 1/2°W., 37.8 ft. scribed "T23S R8W S30 CS BT".

5/20/74

107

Section corner for Secs. 21-22-28-27

Found - Small "X" chiseled in sandstone bedrock, could not find notches called for in orig. notes: from which:

An orig. 12" now approx. 26" rotten fir stob with faint bark scribe "BT" at base bears at record bearing and distance S.11°W., 66.0 ft.

A 60" D.Fir apparently thought to have been an OBT bears S.81 1/2°E., 132.7 ft. (rec. S.81 1/2°E., 135.3 ft.) This tree has been opened previously, we find no markings.

No trace of orig. NE and NW bearing tree.

Set - Brass cap in a drill hole in rock at the corner point mkd.:

DOUGLAS COUNTY SURVEYORS	T 23 S R 8 W
OFFICE	S 21 S 22
1974	S 28 S 27

- New BT's - A 12" D.Fir bears S.17°E., 26.9 ft. scribed "T23S R8W S27 CS BT"
12" D.Fir bears N.20°E., 34.5 ft. scribed "T23S R8W S22 CS BT"
14" D.Fir bears N.68 1/2°W/. 21.7 ft. scribed "T23S R8W S21 CS BT"
15" D.Fir bears S.70°W.. 34.6 ft. scribed T23S R8W S28 CS BT"

This corner is set on an exposed sloping sandstone face in the bottom of a small ravine on a steep north-easterly slope, ravine course N.40°E.

5/15/74

108

1/4 Corner for Sections 22 and 27

Found - A sandstone 10" x 12" x 14", firmly set with a "1/4" plainly cut in the north face.

We also find the remains of two possible BT's:

An 18" rotten stob bears N.70°W., 6.6 ft. No markings found.

A 16" rotten stump bears S.50°E., 14.2 ft. (rec. S.53°E., 15.8 ft.) No markings found.

The rotted condition of these two stumps makes a tree species determination impossible. We find this stone to be 164 ft. east of a stream, 1 link wide, course north, (record 133.3 ft. east).

Set - At the corner point, we set a brass cap mkd:

COUNTY SURVYORS	T 23 S
OFFICE	S 22 1/4
1974	S 27
	R 8 W

- Deposit original stone alongside brass cap and mark the following BT's:
a 12" red cedar, bears N.64 1/2°E., 41.4 ft. scribed "1/4 S22 CS BT"
A 9" hemlock, bears S.31 1/2°E., 3.0 ft. scribed "1/4 S27 CS BT".

6/10/74

109

NE Corner DLC #38

Found - 12" Round post at fence cor. & 2 BT's mkd. in 1957 by State Board of Forestry, both alive & will healed & located at the positions indicated in Ren. #7.

We do not check for evidence of the orig. BT's at this time as our purpose for visiting this cor. is to remove the painted cedar post to allow for widening of the county road.

We remove the above mentioned cedar post and note the following measurements to an additional bearing object:

A brass cap marked Douglas County Surveyors Office U-50-1972 set in a concrete filled monument along the northerly edge of County Road #203. (Wells Road) bears S.71°E., 161.1 ft.

Compass declination setting: 20° East.

1/30/75

Gary L. Langlitz, County Surveyors Office
P. Earle
C.S. 56/51
5/15/74

Gary L. Langlitz, County Surveyors
Peter L. Earle
Office
C.S. 56/51
June 10, 1974

Gary L. Langlitz
John E. Nordling
Surveyors Office
Jan. 30, 1975
C.S. 57/17

RECEIVED
CORNER NO. #138

1/30