

Douglas County Surveyor's Record of  
Government Corners Renewed

T 23

T. S. R 8

R. W. W. M.

FORE-CHAPMAN CO., EUGENE, ORE. 91881

132

Steven Ness  
L.S. 811  
Dec. 28, 1989  
C.S. 63/104

Closing Corner for Sections 24 and 25 only of T.23-9

- Found - 1" iron post with 2½" Douglas Co. brass cap. The monument was tipped down hill (SE) ±2 ft. and under debris from logging operation. Ren. No. 129  
± 70" D. fir, 36.0 ft. bark scribing visible.  
13" hemlock, 17.7 ft. two small faces, not yet healed, scribing visible.  
?" maple in group of 3 or 4 has broken off at ground level - no attempt made to measure.  
± 30" W.R. cedar, now a snag 25 ft. tall, it has slipped down the hill ±20 ft. (it is still upright but leaning to SW), it will probably slide farther down the hill and wipe out the monument sometime in the future. No measure taken.
- Set - We reset the County monument upright, the bottom had not moved. No attempt was made to find the chiseled "X" in bedrock.  
Set 6 ft. steel post with USFS attention sign 1.2 ft. west of monument.

The corner is on a very steep (±85%) SE slope. It is ±70 ft. from creek bottom and on the edge of a recent BLM clearcut, (Unit #2 Old Camp Timber Sale.)

12/28/89

Section Corner for 35 and 36 only of T.22-8

- Found - 3½" dia. 1964 BLM brass cap on an iron pipe flush with ground. 133  
19" now 37" dia. W.Oak with a fully healed single blaze, bears N.17½°E., 58.7 ft. (agrees w/rec.) 1964 BLM  
15" now a cluster of W.Oaks, brg. distance and fully healed single blaze is on 17" East trunk, East trunk's root crown bears N.64½°W., 70.6 ft. (agrees w/rec) 1964 BLM

New Accessories:

- 26" dia. W.Oak double blazed and scribed "T22S R8W S36 CS BT" bears N.27°E., 106.4 ft.  
5/8" Iron rod with plastic cap 5" below ground bears East 211.2 ft (T23S R8W NW Cor. Sec. 1) (Ren. No. 127 in T.23-8)  
2/12/92

Section Corner for Secs. 1 and 2 only (North)

- Found - 5/8" Iron rod with yellow plastic cap 5" below ground. Ren. #127  
24" now 25" dia. W.Oak with a fully healed double blaze, bears S.25°W., 58.4 ft. (agrees w/rec) Ren. No. 127  
32" now 34" dia. W.Oak with a fully healed double blaze bears S.62°E., 165.2 ft. (agrees w/rec) Ren. No. 127

New Accessoreis:

- 20" W.Oak double blazed and scribed "T23S R9W S1 CS BT" bears S.20½°E., 150.1 ft.  
3½" dia. BLM brass cap/iron pipe flush with ground bears West 211.2 ft. (T22S R9W SE Cor. Sec. 35, 1964 BLM)  
2/12/92

Section Corner to Sections 25 and 36 only T.23-9.

- Found - A 2½" D.C.S.O. Brass Cap (properly marked dated 1967) on 135  
1½" O.D. iron pipe, protruding 11" above ground Renewal # 55.

Accessories Found -

- 28" now rotted D. Fir stump of indeterminable size, no blazes or scribing found, bears S.82°W., 12.5 ft. (rec. S.89°W., 12.5 ft. orig. BT)  
20" now 36" dia. D. Fir with a fully healed double blaze bears N.80°W., 33.0 ft. (agrees with rec.) Orig. BT.  
24" now 26" dia. 10 ft. tall D. Fir snag with a fully healed double blaze, bears S.75°W., 17.4 ft. (agrees with rec.) renewal 55.

New Accessories -

- 12" dia. Hemlock double blazed and scribed "T23S R9W S25 CS BT" bears N.30°W., 22.8 ft.  
5" dia. D. Fir double blazed and scribed "XBT" bears N.79°E., 23.0 ft

Note - Cor. lies on very steep NE slope approx. 540 ft. south of creek.

7/28/92

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Feb. 12, 1992  
C.S. File 64/23

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Feb. 12, 1992  
C.S. File 64/23

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
July 28, 1992  
C.S. 64/31