

Douglas County Surveyor's Record of
Government Corners Renewed

23

T. S.

8

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91801

136

1/4 Cor. Secs. 5 & 8

- Found - The original $\frac{1}{4}$ corner position.
 .55" DF (uprooted and slid down hill) with visible scribes
 55" (S. 28 $\frac{1}{2}$ E. 18 lks rec.) down hill) with visible scribes
 45" DF stump with scribe fragments, bears N.72 $\frac{1}{2}$ W., 42.9'.
 (Rec. 65 lks)
 A steel fence post (BLM's approx. $\frac{1}{4}$ corner) bears N.81 $\frac{1}{2}$ W.,
 10.4'.
 Set - 3 $\frac{1}{4}$ " alum. cap on a 36" alum. rod
 40" DF, bears N.12 $\frac{1}{2}$ W., 27.1', scribed " $\frac{1}{4}$ S5 BT"
 34" DF, bears N.71 $\frac{1}{2}$ E., 27.4', scribed " $\frac{1}{4}$ S5 BT"
 11" DF, bears S.5 $\frac{1}{2}$ E., 18.8', scribed " $\frac{1}{4}$ S8 BT"
 10" DF, bears N.71 $\frac{1}{2}$ W., 33.4', scribed " $\frac{1}{4}$ S5 BT"

Clyde Mulkins
 For: IP Timberlands
 Operating Co. LTD
 Dec. 1995
 M 123-32

see previous ren. #32

137

SW DLC COR #39

- Mon. Fd.- 2 $\frac{1}{2}$ " Dia. Brass cap on a 1 $\frac{1}{2}$ " O.D. iron pipe, protrudes 2"
 above ground.
 BT's Fd.- 34" Dia. W.Oak, with a fully healed blaze, bears S.86 $\frac{1}{2}$ W.,
 31.3' (rec. S.86 $\frac{1}{2}$ W., 32.3').
 18" Dia. Ash, with partially healed double blaze, scribing
 visible "SW DLC 39 CS BT", bear N.49 $\frac{1}{2}$ E., 18.5' (agrees
 with rec.)
 21" Dia. Ash, with a fully healed blaze, bears N.14 $\frac{1}{2}$ W.,
 6' (agrees with rec.).
 44" Dia. W.Oak, with a possible previously opened blaze,
 now healed, bears S.65 $\frac{1}{2}$ E., 308.9' (agrees with rec.)
 OBT.
 New BT- 6" Dia. Myrtle, double blazed and scribed "SW DLC 39 CS
 BT", bears S.66 $\frac{1}{2}$ E., 41.7'.

Douglas County Surveyor
 Randall Smith &
 Stephen Flause
 Jan. 9, 97
 C.S. 64/71-1

see previous ren. #109

138

NE COR DLC #38

- Mon. Fd- New fence, round fence post not found.
 Accessories Fd-
 20" now 39" dia. W.Oak, previously opened with a rotted out
 center, no scribing or blazes found, bears N.82 $\frac{1}{2}$ W.,
 772.2'. OBT
 24" now remains of badly rotted Oak stump, bears West 818'.
 OBT ?
 18" now 27" Dia. W.Oak, with a fully healed single blaze,
 bears N.71 $\frac{1}{2}$ E., 198.3'.
 28" W.Oak, now root hole with rotted Oak roots, bears
 S.45 $\frac{1}{2}$ E., 249.2'.
 DCSO County monument set in concrete stamped "U-50 1972",
 bears S.71 $\frac{1}{2}$ E., 161.1'.
 Mon Set- PK nail in concrete fence post footing approx. 1' west of
 fence post at angle in fence line.
 Position of corner was determined at intersection of
 distances from BT's and B.O. Note: a bearing agreement
 with renewal #109 to U-50 and 3' bearing rotation to left
 on BT's in Ren #7.
 New BT- 28" W.Oak, double blazed and scribed "NE DLC 38 CS BT",
 bears N.36 $\frac{1}{2}$ W., 188.9'.

Douglas County Surveyor
 Randall Smith &
 Stephen Flause
 Dec. 16, 1997
 C.S. 64/71-5