

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97198

14

N. W. Corner Section 6, T23-8W. - E. Line Sec. 1, T23-9W.  
Found - 40" Fir Stump, badly burned, N.40°W. 27.1 ft. Found scribing,  
"S6 & W", at bottom edge of upper face. BT. scar compl. burned.  
Stump Hole with Fir roots S.30°W. 29.7 ft.  
No trace of Dogwood to N. E. - Area has been logged & burned.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S T22S R9W  
Office, 1963  
Rescribe 40" Fir Stump N.40°W. 27.1 ft. R 9 W S 1  $\frac{S 36}{S 6}$  T23-8W  
Mkd: T23S R9W S1 CS BT.  
New BT: 9" D. Fir S.70°E. 56.2 ft. Mkd: T23S R8W S6 CS BT.  
No other live trees near.  
Corner lies on West slope approximately 300 ft. W. of ridge top.

15

N. Line Section 6, T23-8W.  
Found - 1½" Iron Pipe (galv.) & Wooden Stake.  
54" Fir N.65°W. 77.9 ft., old uproot, dead, found good  
bark scribing "S36 T22S R9W B".  
72" Fir N.70°E. 90.4 ft., old, dead, uproot, bark charred &  
covered with mud, no scribing found.  
DID NOT SET BRASS CAP - Iron Pipe in good condition.  
New BT's: 9" D. Fir N.68°E. 45.8 ft. Mkd: T22S R8W S31 CS BT.  
20" D. Fir N.66°W. 25.0 ft. Mkd: T22S R9W S36 CS BT.  
D. Fir S.89°W. 30.4 ft. Mkd: T23S R8W S 6 CS BT.  
Corner lies on steep N. E. slope.

S. 1  $\frac{S 36}{S 6}$  16

N. E. Corner Section 1, T. 23 S., R. 9 W.  
Found - 1½" Galv. Iron Pipe at Corner.  
Old, uprooted Fir, now 32", N.88°W. 19.1 ft., traces of old  
scribing visible on prev. opened face, "S" only legible.  
30" old, uprooted Fir S.50°W. 15.8 ft., lying face down.  
40" Fir Stump N.20°E. 15.8 ft., bark flaking badly, no marks.  
Hollow Chinquapin Snag, now 24", S.70°E. 26.4 ft., both upper  
& lower blaze visible on bark, but entire center rotted.  
DID NOT SET BRASS CAP: - Corner lies on top of ridge.  
New BT's: 13" W. Fir S.41°E. 31.4 ft. Mkd: T22S R9W S36 CS BT.  
12" W. Fir S.49°W. 58.3 ft. Mkd: T23S R9W S 1 CS BT.

17

Closing Corner Sections 28 and 33. S 28  
S 29  $\frac{S 33}{S 33}$   
Set Closing corner from original Fir BT., now a windfall lying  
northeasterly - Originally 30" diam. (now 34") bearing S. 119° E.,  
31.68 ft. from C. C. Found scribes on bark, bearing & distance  
taken from where the tree originally stood. #71  
Set - 5/8" Rod - 3.0 ft. high from Original BT.  
Marked New BT: A cut Fir Stump 29" diam., bear. & dist. to spike  
in notch, Weyer. Metal Tag. N.15°34'E. 35.32 ft.  
A cut Fir Stump, 4 ft. diam. S.05°42'W. 30.82 ft.,  
bear. & dist. to spike in notch. Weyer. Metal Tag.

18

¼ Corner to Sections 29 and 32.  
Found - Fir Windfall with bark scribes. Orig. 1898 Fir BT, 30" diam.,  
now 36", bears S.79°W. 21.8 ft. from ¼ corner.  
The Orig. 20" BT. Fir, not identifiable from other windfalls.  
Set - 5/8" Rod for ¼ Corner from Original position of the standing  
Tree, located on south, facing slope.  
New BT: 17" Chinq. N. 18° 43' W. 23.57 fto to notch with spike. Weyer. Metal.  
17" Chinq. S. 14° 52' W. 20.7 fto spike, Weyer. Metal Tag.

19

¼ Corner to Sections 28 and 33.  
Found - Orig. 20" Fir BT., now 33", face not chopped out, scaref by logging  
to the north. BLM Tag. Set spike in notch & Weyer. Metal Tag.  
Orig. 24" Fir BT., now a windfall, S.69°W. 17.82 ft. lying  
northwesterly - downhill, scribes visible.  
Set - 5/8" Rod, 2.3 ft. high.  
Note - ¼ Corner on West, facing slope, approx. 100 ft. horiz. from  
Spring Branch, flowing S. W.

Milo E. Godfrey, Deputy  
Vernon Tracy & Mike Stone  
March 1963  
C. S. File No. 52/14

Godfrey &  
Crew  
March 1963  
C. S. File  
52/14

JUNE 1970 - FOUND CORNERS O.K. →  
Meyerhaeuser Co.  
By Louis Prahar  
June 8, 1966  
C.S. File 55/11  
Map in file

WRT →  
C.S. 54/60 #72