

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T.S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

V. "Ray"  
Tracy &  
Crew  
C. S. File  
No.

54/12

Vernon "Ray" Tracy  
Jack Heritage & Elmer West  
January, 1967  
C. S. File No. 54/12

20

Closing Corner to Sections 7 and 18 only, T23-8W.  
Found - Orig. 24", now 30" W. Fir, N. 27° E. 58.1 ft., now 14' high Snag.  
Prev. opened & shows "T23S R8W S7" scribe. BT scar visible.  
Orig. 24", now 42" Fir, N. 57° E. 24.4 ft. Alive, shows  
old scar on edges where someone attempted to cut in &  
expose scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's R9W T23S R8W  
Office CC 

S	7
S	18

  
1966

New BT's: 12" Hemlock N. 36° E. 27.8 ft. mkd. T23S R8W S 7 CC CS BT.  
15" D. Fir S. 37° E. 9.3 ft. mkd. T23S R8W S18 CC CS BT.  
Note - This corner lies in flat, swampy area on edge of dense vinemaple.  
Sec. 9, 1966

21

Sec. Cor. to Sections 30 & 31 only, T23-8W.  
Found - Sandstone 16"x6"x8", firmly set, but covered 6" deep with  
loose dirt & mkd. with 1 notch on S. & 5 notched on N. edges.  
Orig. 5", now 18" Fir, alive, N. 41° E. 3.3 ft., shows good scar.  
(Rescribe "T23S R8W S30 CS BT")  
Orig. 10", now 30" Fir, alive, S. 61° E. 13.9 ft., shows fair scar.  
(Rescribe "T23S R8W S31 CS BT")  
Orig. 14", now 38" Fir, alive, S. 54° W. 75.9 ft., shows good scar.  
Do not open.  
Set - Brass Cap at Cor. Mkd: County Surveyor's R T 23 S R  
(Reset stone alongside) Office 9 

S	30
S	31

 8  
1967 W

Note - This corner lies on E. edge of small creek, course S10E.

22

Sec. Cor. to Sections 25 and 36 only, T23-9W.  
Found - No trace of rock called for.  
Orig. 28", now 28" Fir Snag, S. 89° W. 22.5 ft., shows "T23S R9W S36"  
on unhealed blaze.  
Orig. 20", now 34" Fir, alive, N. 80° W. 33.0 ft., shows good scar.  
(Rescribe "T23S R9W S25 CS BT")  
Set - Brass Cap at Cor. Mkd: County Surveyor's R T 23 S R  
Office 9 

S	25
S	36

 8  
1967 W

New BT: 24" D. Fir S. 75° W. 17.4 ft. mkd. T23S R9W S36 CS BT.  
Note - This corner lies on very steep N.E. slope approx. 540 ft. S. of creek.

23

Sec. Cor. to Sections 10 - 11 - 14 - 15.  
Found - Orig. 18", now 46" Hemlock, S. 51° W. 20.5 ft., prev. opened  
many yrs. ago or never completely healed over, shows "3 9W 15 T"  
scribe on badly rotted face.  
No trace of other original bearing trees.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 9 W  
Office 

S	10	S	11
S	15	S	14

  
1967

New BT's: 46" Hemlock S. 51° W. 20.5 ft., rescribed "T23SR9W S15 CS BT".  
5" Hemlock S. 65° E. 13.6 ft. mkd. S14 CS BT.  
28" Hemlock N. 53° E. 35.2 ft. mkd. T23S R9W S11 CS BT.  
No suitable trees in section 10.  
Note - This corner lies approx. 135 ft. W. of Otter Creek, course N.E.

24

1/4 Corner to Section 18 only, T23-8W.  
Found - Orig. 40" D. Fir, now snag, S. 5° E., 94.4 ft., scribe "4S" in  
the wood, there were two good face, plus ring count.  
No trace of other BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's R T 23 S R  
Office 9 

1/4	S	18
-----	---	----

 8  
1967 W

New BT's: 30" W. Fir S. 47° E. 14.5 ft. mkd. 1/4 S18 CS BT.  
11" W. Fir N. 61° E. 36.8 ft. mkd. 1/4 S18 CS BT.  
Note - This corner lies on top of ridge, course West.

Sec. Cor. to Sections 18 and 19 only